



Expertise

Protocol number: 41545684
Order No. / Reference: 25144452
Inspection date: 12 Sept 2025

Manufacturer: Mercedes-Benz
VIN: W1V44760313821905

Model: Vito 114 CDI Kastenwagen Lang VA BASE



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 114 CDI Kastenwagen Lang VA BASE	
Vehicle Identification number	W1V44760313821905
Mileage (Read)	86,542 km
First registration	15 Feb 2021
Number of holders	1
Next periodical technical inspection	03/2025
(Report on hand)	
Power / Engine displacement	100 kw / 1,750 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	brillantsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	374 Tag(e)
Last maintenance on / at	10/2024 at 77,160 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FY987293
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / ARV 00283		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	Fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R16 104T	Winter tyres on Steel rim with wheel cover	Pirelli	6mm / 6mm
2)	195/65 R16 104T	Winter tyres on Steel rim with wheel cover	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R16 104T	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	195/65 R16 104T	Summer tyres on Steel	Continental	6 mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • AdBlue tank (24 liters) • Attention Assist • Hill start assist • Brake lights, adaptive • diesel particulate filter • Electronic Stability Program (ADAPTIVE ESP) with integrated anti-lock braking system (ABS) (Traction Control (ASR) - Electronic Brake-force Distribution (EBD) - Brake Assist (BAS)) • Lockable glove box • Tailgate with opening angle approx. 90° • Headrests (2), front • Mercedes-Benz emergency call system (communication module (LTE) for digital breakdown management services) • Upholstery: Caluma black fabric • Wheels: steel rims 6.5 J x 16 • Crosswind Assist • Front stabilizer • Cruise control • Lashing eyes in the cargo area • Immobiliser | <ul style="list-style-type: none"> • Airbag for driver and front passenger • Outside temperature display • Brake light, third • Ceiling interior light (in the driver and passenger area) • ECO start-stop function • Electric window lifter driver/passenger (with anti-pinch protection, quick lowering and raising) • Transmission: 6-speed manual • Seat belt warning device for driver and front passenger seats • Instrument cluster (speedometer with trip meter - quartz-controlled digital clock - fuel gauge - electronic rev counter) • Package: BlueEFFICIENCY (efficiency package) • Tires: 195/65 R 16 C • Key: 3-button radio remote control • Electromechanical power steering • 12V socket • Partition wall continuous • Maintenance interval display >>ASSYST< • Central locking with radio remote control |
|---|--|

Extra equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Exterior mirrors electrically adjustable and heated, left and right • Interior lining of cargo area up to roof height (wood) • Air conditioning controlled Tempmatic • Radio: Audio 30 (DAB digital radio - 7" LCD touchscreen - Apple CarPlay and Android Auto - Bluetooth 3.0, hands-free system - 2-way front speakers) | <ul style="list-style-type: none"> • Battery: fleece battery 12 V / 92 Ah • Driving light assistant (automatic switching on of driving lights) • Paint finish: metallic • Rain sensor • Rear view camera, high resolution, with orientation lines • Heat-insulating glass (driver's cab) |
|---|--|

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available to inspect the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Bonnet	Bonnet - dent(s) - Smooth repair work
3	Vehicle glazing	Windscreen - Stone chips - Smart repair
4	Sill - left side	Sill - Dent / paintcoat damage - Smart repair



No.	Component group	Description
5	Side panel - rear left side	Side panel - Scratch(es) - Loss in value
6	Misc.	Main inspection - Due - Perform
7	Door - front left side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratch(es) - No deduction
2	Wing mirror - right side	Mirror housing - Scratch(es) - No deduction
3	Boot lid / rear door	Boot lid - Scratch(es) - No deduction
4	Sill - right side	Sill - Dent / paintcoat damage - No deduction
5	Front bumper	Front bumper (Unterhalb Sichtkante) - Scratched - No deduction
6	Door - front right side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Missing parts

Description

2nd wheel set - 1 tyre (Kompletttrad)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Provided by user / customer, from 8 Jun 2024	6.232,44 €

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	337 µm	Side panel - rear right side	359 µm
----------------------	--------	------------------------------	--------

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Fahrzeug kann nicht angehoben werden
- Unterbodenbesichtigung nicht möglich, es können Folgekosten entstehen



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Damage 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Damage 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Damage 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Damage 2: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 2: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 3: Vehicle glazing: Windscreen - Stone chips - Smart repair



Damage 3: Vehicle glazing: Windscreen - Stone chips - Smart repair



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 4: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Loss in value



Damage 5: Side panel - rear left side: Side panel - Scratch(es) - Loss in value



Damage 6: Misc.: Main inspection - Due - Perform



Damage 7: Door - front left side: Door - Scratch(es) - Paint




Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint



Wear and tear 1: Wing mirror - left side: Cap - Scratch(es) - No deduction



Wear and tear 1: Wing mirror - left side: Cap - Scratch(es) - No deduction



Wear and tear 2: Wing mirror - right side: Mirror housing - Scratch(es) - No deduction



Wear and tear 2: Wing mirror - right side: Mirror housing - Scratch(es) - No deduction



Wear and tear 3: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Wear and tear 3: Boot lid / rear door: Boot lid - Scratch(es) - No deduction



Wear and tear 4: Sill - right side: Sill - Dent / paintcoat damage - No deduction



Wear and tear 4: Sill - right side: Sill - Dent / paintcoat damage - No deduction




Wear and tear 4: Sill - right side: Sill - Dent / paintcoat damage - No deduction



Wear and tear 5: Front bumper: Front bumper (Unterhalb Sichtkante) - Scratched - No deduction



Wear and tear 5: Front bumper: Front bumper (Unterhalb Sichtkante) - Scratched - No deduction



Wear and tear 6: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 6: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 6: Door - front right side: Door - Scratch(es) - No deduction



Repainting 1: Boot lid / rear door



Repainting 2: Side panel - rear right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44760313821905

Hersteller / Modell: MERCEDES-BENZ MB Vito 114 CDI Lang VA BASE

Datum	KM-Stand	Beschreibung
30.10.2024	77.160	Regelwartungsdienst
16.05.2024	71.496	Bremsflüssigkeit; Bremsflüssigkeit ern; Bremssattel ern/inst; Bremsscheiben+Beläge v+h
25.09.2023	59.907	Regelwartungsdienst
24.05.2023	40.455	AU; Motoröl b. Wartung; Systemtest/Eigendiagnose; Turbolader ern
31.05.2022	26.014	Regelwartungsdienst