



Hüsges Gruppe®
Die Gutachter

status report

customer:	Bank 11, Neuss
contract number:	1267206851-AKR
reference:	

vehicle data			
Mercedes-Benz V -Klasse V 220/250/300 d AVANTGARDE EDITION 4MATIC lang			
Vehicle identification number	W1V44781313745626	mileage read:	90395 km
..:			
First Registration / construction year:	15.06.2020 / 2019	Visit Date / place of birth:	29.09.2025 Neuss
Bodywork:	transporter	Re - import:	no
Body type:	van	KBA no. :	2222//ABY
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1950 ccm / 176 kW (239 PS)	Engine:	four-wheel
paint:	obsidianschwarz metallic	Number of previous owners:	1
Doors / seats:	5 / 6	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	digital	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	80613 / 14.12.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	digital / -	80613 / 14.12.2023
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Pirelli	245/45/R19/102Y 1 mm
1st axis - right / states .	Pirelli	245/45/R19/102Y 2 mm
2nd axis - Left / states .	Pirelli	245/45/R19/102Y 4 mm
2nd axis - right / states .	Pirelli	245/45/R19/102Y 4 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Storage net in front seat back left <i>Ablagenetz an Vordersitzlehne rechts</i> • Airbag • Ambient lighting • Electrical socket for trailer • • Armrests passenger compartment • Mirrors, aspheric, both • Exterior mirrors with integral indicators • Avantgarde Edition • BlueEFFICIENCY package <i>Start/Stop-Anlage Motor</i> • Flooring carpet in load / passenger compartment • Brake system with ABS + ASR • Design and equipment line Avantgarde Edition • Off switch for headlights • Side sill with lettering Mercedes-Benz (illuminated) • Electron. Stability Program (ESP) • Driving Assistance System Attention Assist (fatigue detection sensor) • Driving Assistance System Crosswind Assist • Windows for rear doors / tailgate wiper / washer • Window in load / FG - space - fixed, front left • Power windows 2 times • Lock Sliding Door (Active) • Belt tensioners • Lockable glove compartment • Tailgate with automatic opening and closing system • heated rear window • Body / Structure Bus • childlock	• Adaptive brake lights • Airbag driver • traction • Anti- lock braking system (ABS) • Display for wash water level • • Power side mirrors . adjustable and heated, both • Outside temperature display • Lighting in the rear handle with reading spot • Flooring carpet in the driver's compartment • brake Assist • DAB tuner (digital radio reception) • Direct steering with variable steering force support • • entry lights • Driving Assistance package <i>Außenspiegel mit Totwinkel-Assistent, PRE-SAFE-System, Fahrassistenz-System: aktiver Bremsassistent, Fahrassistenz-System: Spurhalteassistent</i> • Fahrassistenz-System Pannenmanagement • Driving assistance system traffic sign recognition • • Window in load / FG - space - fixed, front right • Parking brake electrically • Automatic transmission GTronic - (9-speed) <i>Geschwindigkeits-Regelanlage (Tempomat)</i> • Grab bars in the rear • Urea tank (AdBlue) 24 ltr. • rear window openable • Intelligent Light System LED <i>Heckleuchten LED</i>

• • Comfort lighting in the passenger / cargo area • Head airbag system (Windowbag) • Steering wheel (leather) • Steering wheel with multifunction incl . Travel calculator • • Front center console with blind / storage • Motor 2.0 Ltr. - 176 kW CDI KAT • Navigation system for multimedia system MBUX • particle filter • PTC Heater • Tire Pressure Monitoring System • Low-emission according to the Euro 6d-TEMP emissions standard • Sliding load / passenger compartment left • • Seat feature for quick locking seat rail system • Seats in the cab driver seat heated <i>Sitze im Fahrerhaus: Beifahrersitz heizbar</i> • Seats in the charge / FG - room 1st row , 1 single seat right • Seats in the charge / FG - room 2nd row , 1 single seat right • Mirror package <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Umfeldleuchte, Innenspiegel und Außenspiegel links mit Abblendautomatik</i> • Outlets (12V connection) in the load / passenger compartment , 2 -fold • Surround System Burmester • Coloured glasses in black glass • Preparation for navigation system (for MBUX multimedia system) • Service interval indicator Assyst • Wärmeschutzverglasung	• Body / building long • Climate Fund (Tempmatik) • Deluxe automatic air conditioning Thermotronik <i>Innenraumfilter: Pollenfilter</i> • • Head and shoulders airbag (thorax) Driver / passenger side • Steering wheel (steering wheel . Adjustable) • Headlamp leveling • Metallic paint • model refinement • Multimediasystem MBUX (Touchscreen 10,25") <i>Freisprecheinrichtung Bluetooth, WLAN-Hotspot</i> • Parking package with 360 ° camera <i>Fahrassistenz-System: aktiver Park-Assistent, Kamerasystem 360 Grad</i> • vehicle permit • Wheelbase 3200 mm • Interior rear view mirrors • Windscreen wipers with rain sensor • • Seat feature Isofix child seat system • Seat cover / leather upholstery Lugano • Seats in the charge / FG - room 1st row , 1 single seat left • Seats in the charge / FG - room 2nd row , 1 single seat left • Sun visors with mirrors (illuminated) • Socket (12V connection) in load / passenger compartment • Bumper / Stoßf. bar painted on the side + handle on the tailgate • Daytime running lights • Fleece battery 92 Ah • Warm air channel for charge / passenger compartment • immobilizer • Perm. Total weight 3.10 t
--	---

special Features	
• AMG-Line <i>Verkleidung / Seitenschweller (AMG), Frontschürze AMG, Heckschürze AMG, Dachkantenspoiler AMG, Sport-Pedalerie</i>	• Trailer weight 2500 kg • roof rails

Aluminium gebürstet, Dachverkleidung / Innenhimmel Stoff schwarz, Bremssattel mit Schriftzug (Mercedes-Benz), LM-Felgen

- Trailer hitch (ball head removable)
- Theft alarm system
- Driver assistance system Traffic information system Live Traffic
- Interior trim parts carbon look
- Head airbag system (Windowbag) back
- LM rims 8x19 (AMG, 7 double spokes, black)
- Night-Package

Kühlergrill schwarz lackiert, Außenspiegel schwarz lackiert

- Heated washer nozzles
- Smartphone integration (Apple CarPlay and Android Auto)

- Driver assistance system High Beam Assistant Plus
- Suspension damping system Agility Control
- Open + close comfort with infrared remote control
- Enlarged fuel tank
- Navigation system Plus for the MBUX multimedia system
- Spare wheel and jack
- Seats in the cab driver's seat with lumbar support
Sitze im Fahrerhaus: Beifahrersitz mit Lendenwirbelstütze
- Auxiliary heating (hot water)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Batterie defekt.

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			Out of order	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
					examined limited
coupling:			unavailable	exhaust System:	
					examined limited
engine running:			examined limited	shock absorber:	
					not possible
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The alternator (generator) was wrong for visiting time .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time .
oil loss:	**Battery deep discharge. Vehicle was bridged with a jumper.
air conditioning:	The vehicle could be checked only limited to oil leaks .
lighting system:	The air conditioning system could be tested only restricted during the visit .
coupling:	The Lichtanlage could be considered limited to the tour date .
exhaust System:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
engine running:	The exhaust system has been tested only restricted during the visit .
shock absorber:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
transmission:	The shock absorber could not be checked during the inspection .
reference:	The transmission could be examined in the context of limited test drive / pull test .
	*Nutzfahrzeug typische Gebrauchsspuren und Beschädigungen. Kosten- und Schadenserweiterung möglich.

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. tailgate	Subsequently painted	acceptable
3. Sidewall - Rear - right	Subsequently painted	acceptable
4. Door Rear - right	Subsequently painted	acceptable
5. Rim rear - right	Scratch(es)	Smart repair
6. tire front - left	Worn	Replace
7. battery	Defective	Replace
8. Abstandsassistent	Error message	Carry out a fault diagnosis
9. battery	Error message	Carry out a fault diagnosis
10. Parkbremse	Error message	Carry out a fault diagnosis
11. Warnleuchte Reifendruck	Error message	Carry out a fault diagnosis
12. steering wheel	Scratch(es)	Replace
13. tailgate trim	Scrape	Replace
14. Front door - left	Abnormal noises	Carry out a fault diagnosis
15.	Wear and tear	acceptable
16. Front bumper	Scratch(es)	Paint
17. hood	Execution defect	Paint
18. tailgate	Execution defect	Refurbish and paint
19. Sidewall - Rear - right	Execution defect	Refurbish and paint
20. Door Rear - right	Execution defect	Refurbish and paint
21. Windshield	Chipping from stones	Replace
22. Rear door - left	Delle	Smart repair
23. Front door trim - left	Deformed (slightly)	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. hood



2. tailgate



3. Sidewall - Rear - right



4. Door Rear - right



5. Rim rear - right



5. Rim rear - right



6. tire front - left



8. Abstandsassistent



9. battery



10. Parkbremse



11. Warnleuchte Reifendruck



12. steering wheel



13. tailgate trim



15.



15.



16. Front bumper



16. Front bumper



17. hood




17. hood



17. hood



18. tailgate



18. tailgate



19. Sidewall - Rear - right



19. Sidewall - Rear - right




19. Sidewall - Rear - right



20. Door Rear - right



20. Door Rear - right



20. Door Rear - right



21. Windshield



21. Windshield



22. Rear door - left



22. Rear door - left



23. Front door trim - left



23. Front door trim - left