



status report

customer: Bank 11, Neuss
contract number: 1140454030
reference:

vehicle data

Audi A6 Avant 2.0 TDI quattro

Vehicle identification number	WAUZZZ4G5JN118183	mileage read:	173940 km
First Registration / construction year:	18.06.2018 / 2018	Visit Date / place of birth:	18.08.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0588//BED
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 140 kW (190 PS)	Engine:	four-wheel
paint:	black	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	1	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Nexen	255/40/ZR19/100Y 5 mm
1st axis - right / states .	Nexen	255/40/ZR19/100Y 5 mm
2nd axis - Left / states .	Nexen	255/40/ZR19/100Y 5 mm
2nd axis - right / states .	Nexen	255/40/ZR19/100Y 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Adaptive brake lights • Anti-Blockier-System (ABS) • Drive all-wheel drive permanent • Mirrors aspherical, left • Exterior mirror body color • brake Assist • roof spoiler • Electron. Stability Program (ESP) • Driving Assistance System occupant protection system (Audi pre sense basic) • Windscreen with band filter top • Luggage net on the front seat backrest • Trunk lid electr. operated (open + close) <i>Servoschliessung für Kofferraumdeckel</i> • Transmission 7-speed - dual-clutch S -tronic • Gloss package • Interior inlays Micro Metallic • • Steering wheel (leather) with multifunction • Light and rain sensor • Front center armrest • Multi-function display / onboard computer • Smokers Package • • • • Start / Stop system • • Xenon Plus (high and low beam) <i>Tagfahrlicht LED, Scheinwerfer-Reinigungsanlage (SRA)</i>	• Airbag driver / passenger side • Drive slip control (ASR) • Audi Drive Select • Mirrors aspheric, right • Braking system with energy recovery • Roof rails (aluminum) • Elektron. Differentialsperre (EDS) • Driving Assistance System Start-Off Assist (hold assist) • Electric windows front + rear • Velour floor mats • Luggage compartment separation (net) • Cruise control system (cruise control) • Cup holder in center console • LED Taillights • Isofix seats for child seat • • Steering column (steering wheel) mech . Height / length adjustment • Rear center armrest with compartment • Engine 2.0 ltr. - 140 kW 16V TDI • • Tire repair kit • • Low emissions Euro 6 emission standards • Power steering electro-mechanical • Socket (12V connection) in the boot / load compartment • •

special Features	
• Filing package • Bluetooth hands-free kit with voice recognition (Audi Phone Box) • Theft alarm system + Innenraumabsicherung / tow-away protection • Parking aid front and rear, optical (APS Plus) • Driving Assistance System and Lane Change . Lane Departure Prevention (side assist and active lane assist) incl. Pre sense rear <i>Frontkamera (Scheibe), Fahrassistenz-System: Spurwechselassistent (Side Assist) inkl. Audi pre sense rear, Fahrassistenz-System: Spurhalteassistent (active lane assist)</i> • Deluxe automatic air conditioning 4-zone • Multi-Media Interface MMI Navigation plus with MMI touch <i>Audi music interface, Fahrer-Informationen-System (FIS) mit Farbdisplay</i> • Set adapter cable Audi music interface • • Front sports seats <i>Lendenwirbelstützen vorn, elektr. verstellbar</i>	• Power side mirrors . folding, with auto dip <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Abblendautomatik, Außenspiegel mit Bordsteinautomatik, rechts, Innenspiegel mit Abblendautomatik</i> • Headliner fabric , black • Anti-theft wheel (wheel locks) • Driving Assistance System High-Beam Assistant • Driving Assistance System Speed ??Limit Display • LM rims 7.5x17 (6- arm) • Rear View Camera • Seat relation / upholstery fabric contour • Special paint Brilliant Black • Glazing behind darkened

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	MIL Fehlermeldung, Batterie Tiefentladen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
					examined limited
coupling:			unavailable	exhaust System:	
					examined limited
engine running:			Out of order	shock absorber:	
					examined limited
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen MIL Fehlermeldung Fehlerdiagnose durchführen lassen Schaden und Kosten Erweiterung möglich

damage



	component	Damage	Rep kind
1.	maintenance	Due	Replace
2.	proof of maintenance	Missing	Replace
3.		Missing	Replace
4.	battery	Defective	Replace
5.	Key with remote control	Missing	Replace
6.	MIL	Error message	Carry out a fault diagnosis
7.	Sidewall - Rear - Left	Delle	Smart repair
8.	Rim rear - left	Scratch(es)	Replace
9.	Rear door - left	Scrape	Smart repair
10.	Front door - left	Delle	Smart repair
11.	Windshield	Chipping from stones	Smart repair
12.	Front bumper	chipped paint	Smart repair
13.	Rim front - right	Scratch(es)	Replace
14.		Scrape	Smart repair
15.	Sidewall - Rear - right	Deformed (slightly)	Refurbish and paint
16.	exterior body	Surface scratch(es)	
17.		Wear and tear	acceptable
18.		Dirty	
19.		Odour	Ozone treatment
20.	Trunk Flooring	Damaged	Replace
21.	flooring	Burn hole	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .


photographic record




front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



6. MIL



7. Sidewall - Rear - Left



7. Sidewall - Rear - Left



8. Rim rear - left



8. Rim rear - left



8. Rim rear - left



9. Rear door - left



9. Rear door - left



10. Front door - left



10. Front door - left



11. Windshield



11. Windshield



12. Front bumper



12. Front bumper



13. Rim front - right



13. Rim front - right



14.



14.



15. Sidewall - Rear - right




15. Sidewall - Rear - right



16. exterior body



17.



17.



18.



18.



20. Trunk Flooring



20. Trunk Flooring



20. Trunk Flooring



21. flooring



21. flooring