

Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 728145530
reference:

vehicle data

Audi A6 Allroad quattro 3.0 TDI

Vehicle identification number	WAUZZZ4G6JN034826	mileage read:	161570 km
First Registration / construction year:	04.10.2017 / 2017	Visit Date / place of birth:	30.09.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0588//BBY
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2967 ccm / 200 kW (272 PS)	Engine:	four-wheel
paint:	black	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	11.2026 / 11.2026	cushion type:	leather
Service book available:	no	Interior Color:	gray
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Goodyear	235/55/R18/100V 4 mm
1st axis - right / states .	Goodyear	235/55/R18/100V 4 mm
2nd axis - Left / states .	Goodyear	235/55/R18/100V 5 mm
2nd axis - right / states .	Goodyear	235/55/R18/100V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Drive slip control (ASR) • Audi Drive Select • Mirrors aspheric, right • Exterior mirror body color • Braking system with energy recovery • roof rails • Door sills with aluminum inlays • Electron. Stability Program (ESP) • Driving Assistance System occupant protection system (Audi pre sense basic) • Electric windows front + rear • Luggage net on the front seat backrest • Cruise control system (cruise control) • Cup holder in center console • Interior inlays Seidenglanz • • • Steering column (steering wheel) mech . Height / length adjustment • Rear center armrest with compartment • Engine 3.0 ltr. - 200 kW V6 24V TDI • Smokers Package • • • • Start / Stop system • daytime running lights • •	• Anti-Blockier-System (ABS) • Drive all-wheel drive permanent • Mirrors aspherical, left • Power side mirrors . adjustable and heated, both • LED turn signals integrated into outside mirrors • brake Assist • roof spoiler • Elektron. Differentialsperre (EDS) • Driving Assistance System Start-Off Assist (hold assist) • Chassis (adaptive air suspension) • Windscreen laminated glass • Luggage compartment separation (net) • Transmission 7-speed - dual-clutch S -tronic • LED Taillights • Isofix seats for child seat • Contrast Paint • Fuel tank 75 Ltr . • Light and rain sensor • Front center armrest • Multi-function display / onboard computer • Tire repair kit • • Low emissions Euro 6 emission standards • Power steering electro-mechanical • Socket (12V connection) in the boot / load compartment • • Xenon Plus (high and low beam) <i>Scheinwerfer-Reinigungsanlage (SRA)</i>

special Features	
• Filing package • Audi music interface • Bluetooth hands-free kit with voice recognition (Audi Phone Box) • Driving Assistance System Speed Limit Display • Fixing set for rail system in the luggage compartment • Deluxe automatic air conditioning 4-zone • • Metallic paint • Rear View Camera • Seat cover / upholstery leather Milano • Glazing behind darkened	• Assistance package incl . Audi pre sense plus <i>Einparkhilfe vorn und hinten, optisch (APS Plus), Fahrassistenz-System: Spurwechselassistent (Side Assist) inkl. Audi pre sense rear, Fahrassistenz-System: Autom. Distanzregelung (Adaptive Cruise Control) mit Stop&Go inkl. Audi pre sense front, Frontkamera (Scheibe), Fahrassistenz-System: Bremsassistent (Audi pre sense front), Fahrassistenz-System: Spurhalteassistent (active lane assist)</i> • Power side mirrors . folding, with auto dip <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Bordsteinautomatik, rechts, Außenspiegel mit Abblendautomatik, Innenspiegel mit Abblendautomatik</i> • Headliner fabric , black • Driver Information System (FIS) with color display • Tailgate elektr . operated (open + close) <i>Servoschliessung für Kofferraumdeckel</i> • LM rims 7x18 (5- arm) • • Multi-Media Interface MMI Navigation plus with MMI touch • Rear side airbag •

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	MIL Fehlermeldung, Motor unnormale Geräusche

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted

repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

**Layers of paint thickness
measurement:**

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		examined limited			
air conditioning:		examined limited	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		Out of order	shock absorber:		examined limited
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light. It rattles were found.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen MIL Fehlermeldung Fehlerdiagnose durchführen lassen Motor unnormale Geräusche Schaden und Kosten Erweiterung möglich

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. maintenance	Due	Replace
3. proof of maintenance	Missing	Replace
4. MIL	Error message	Carry out a fault diagnosis
5. motor	Abnormal noises	Carry out a fault diagnosis
6. Rear bumper	Damaged	Replace
7. roof	Deformed	Refurbish and paint
8. Rear door - left	Scrape	Paint
9. Front door - left	Scrape	Paint
10. Door Rear - right	Scratch(es)	Paint
11. Sidewall - Rear - right	Deformed (slightly)	Smart repair
12. Rim rear - right	Scratch(es)	Paint
13.	Scrape	Replace
14. exterior body	Surface scratch(es)	
15.	Wear and tear	acceptable
16.	Dirty (strong)	
17.	Dirty (animal hair)	
18.	Odour	Ozone treatment
19.	Damaged	Replace
20. Bedieneinheit Hinten	Damaged	Replace
21. tailgate trim	Scrape	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. hood



4. MIL



6. Rear bumper




6. Rear bumper



6. Rear bumper



6. Rear bumper



7. roof



7. roof




7. roof




8. Rear door - left



8. Rear door - left




8. Rear door - left



9. Front door - left



9. Front door - left



9. Front door - left



10. Door Rear - right




10. Door Rear - right



11. Sidewall - Rear - right



11. Sidewall - Rear - right



11. Sidewall - Rear - right



12. Rim rear - right



12. Rim rear - right



13.



13.



13.




14. exterior body



15.



15.



16.



16.



17.



17.



19.



19.



20. Bedieneinheit Hinten



21. tailgate trim



21. tailgate trim