



status report

customer: Bank 11, Neuss
contract number: 886763130
reference:

vehicle data

Audi A6 Lim. 3.0 TDI quattro

Vehicle identification number	WAUZZZ4G9JN106716	mileage read:	163011 km
First Registration / construction year:	18.12.2018 / 2018	Visit Date / place of birth:	18.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	limousine	KBA no. :	0588//BBO
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2967 ccm / 200 kW (272 PS)	Engine:	four-wheel
paint:	Mythosschwarz Metallic	Number of previous owners:	3
Doors / seats:	4 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	3 - Average
documents:		condition inside:	3 - Average
visit condition:	-		
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	1	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Minerva	225/55/R17/97W 5 mm
1st axis - right / states .	Minerva	225/55/R17/97W 5 mm
2nd axis - Left / states .	Minerva	225/55/R17/97W 5 mm
2nd axis - right / states .	Minerva	225/55/R17/97W 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Adaptive brake lights • Anti-Blockier-System (ABS) • Drive all-wheel drive permanent • Mirrors aspherical, left • Exterior mirror body color • brake Assist • Electron. Stability Program (ESP) • Driving Assistance System occupant protection system (Audi pre sense basic) • Windscreen with band filter top • Luggage net on the front seat backrest • Transmission 7-speed - dual-clutch S -tronic • Gloss package • Isofix seats for child seat • • Steering column (steering wheel) mech . Height / length adjustment • Rear center armrest with compartment • Engine 3.0 ltr. - 200 kW V6 24V TDI • Tire repair kit • • • Start / Stop system • •	• Airbag driver / passenger side • Drive slip control (ASR) • Audi Drive Select • Mirrors aspheric, right • Braking system with energy recovery • Elektron. Differentialsperre (EDS) • Driving Assistance System Start-Off Assist (hold assist) • Electric windows front + rear • Velour floor mats • Cruise control system (cruise control) • Cup holder in center console • LED Taillights • • Steering wheel (leather) with multifunction • Light and rain sensor • Front center armrest • Multi-function display / onboard computer • • Low emissions Euro 6 emission standards • Power steering electro-mechanical • Socket (12V connection) in the boot / load compartment •

special Features	
• Trailer hitch (ball head pivots) • Audi connect \u0026 Audi Phone Box <i>Bluetooth-Freisprecheinrichtung mit Spracherkennung (Audi Phone Box), Audi connect (Internetbasierende Dienste)</i>	• Assistance package incl . Audi pre sense plus <i>Einparkhilfe vorn und hinten, optisch (APS Plus), Fahrassistenz-System: Spurwechselassistent (Side Assist) inkl. Audi pre sense rear, Fahrassistenz-System: Autom.</i>



- **Business Package**
Bluetooth-Freisprecheinrichtung mit Spracherkennung (Audi Phone Box), Multi-Media-Interface MMI Navigation, Multi-Media-Interface MMI Basic Plus / MMI Radio Plus, Sound-System DSP / Audi Sound-System, Audi music interface, Einparkhilfe vorn und hinten, optisch (APS Plus), Sitzheizung vorn, Lendenwirbelstützen vorn, elektr. verstellbar, Innenspiegel mit Abblendautomatik
- **Driving Assistance System High-Beam Assistant**
- **Head-Up Display**
- **Isofix seats for child seat on front passenger seat**
- **Deluxe automatic air conditioning 4-zone**
- **LM rims 7.5x18 (5- arm)**
-
- **Multi-Media Interface MMI Navigation plus with MMI touch**
Multi-Media-Interface MMI Basic Plus / MMI Radio Plus, Sound-System DSP / Audi Sound-System, Audi music interface, Fahrer-Information-System (FIS) mit Farbdisplay
- **Digital radio reception (DAB)**
- **Rear seat backrest split / folding**
- **Rear side airbag**
- **Electric front seats . adjustable (left with memory)**
Lendenwirbelstützen vorn, elektr. verstellbar
- **Front sports seats**

Distanzregelung (Adaptive Cruise Control) mit Stop&Go inkl. Audi pre sense front, Frontkamera (Scheibe), Fahrassistenten-System: Bremsassistent (Audi pre sense front), Fahrassistenten-System: Spurhalteassistent (active lane assist)

- **Electric wing mirror . adjustable , heated and folding , with auto dip and Memory**
Außenspiegel elektr. anklappbar, Außenspiegel elektr. klappbar, mit Abblendautomatik, Außenspiegel mit Abblendautomatik, Außenspiegel mit Bordsteinautomatik, rechts, Innenspiegel mit Abblendautomatik, Außenspiegel mit Abblendautomatik und Memoryfunktion, Außenspiegel mit Memoryfunktion
- **Headliner fabric , black**
- **Chassis (adaptive air suspension)**
- **Interior Decor inlays aluminum ellipse silver**
- **Climate comfort / acoustics - glazing including privacy glazing**
- **Convenience key with sensor-controlled tailgate release**
- **LM rims 8x18 (7 -twin-spoke)**
- **Metallic paint**
- **Non smoking package**
- **Rear View Camera**
- **LED headlights**
Tagfahrlicht LED, Scheinwerfer-Reinigungsanlage (SRA)
- **Seat cover / upholstery leather Milano**
- **BOSE sound system**
- **Glazing behind darkened**

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	
Note Road Safe:	Steinschlag im Sichtfeld, Unfallschaden Vorne Rechts

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. tailgate	Subsequently painted	acceptable
3. Sidewall - Rear - right	Subsequently painted	acceptable
4. Door Rear - right	Subsequently painted	acceptable
5. Roof frame - right	Subsequently painted	acceptable
6. A-pillar Front - right	Subsequently painted	acceptable
7. Sitz Vorne Links	Damaged	Smart repair
8. Sitz Vorne Rechts	Damaged	Smart repair
9. Mittelkonsole Blende	Damaged	Replace
10. Zweitschlüssel	Missing	Replace
11. proof of maintenance	Missing	Replace
12. Bodenbelag Fahrerseite	Burn hole	Smart repair
13. Bremsen	Worn	Replace
14. Rim rear - left	Scratch(es)	Smart repair
15. Rim rear - right	Scratch(es)	Smart repair
16. Unfallschaden Vorne Rechts Schadenserweiterung möglich	Accident damage	Replace
17. hood		Paint
18.	Scratch(es)	Paint
19. roof		Paint
20. Sitzreihe Hinten	Damaged	Smart repair
21. Sidewall - Rear - Left	Deformed	Refurbish and paint
22. tailgate		Smart repair
23. Rear bumper	Scratch(es)	Paint
24. Sidewall - Rear - right	Scratch(es)	Paint
25. Tür Hinten - Rechts Aschenbecher	Missing	Replace
26. Tankdeckel Fangband	Damaged	Replace
27. Windshield	Damaged	Replace
28. Side window - Front - right	Scratch(es)	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. hood



2. tailgate



3. Sidewall - Rear - right



4. Door Rear - right




5. Roof frame - right



6. A-pillar Front - right




7. Sitz Vorne Links



7. Sitz Vorne Links



8. Sitz Vorne Rechts



8. Sitz Vorne Rechts



9. Mittelkonsole Blende



9. Mittelkonsole Blende



12. Bodenbelag Fahrerseite



13. Bremsen



14. Rim rear - left



14. Rim rear - left



15. Rim rear - right



16. Unfallschaden Vorne Rechts Schadenserweiterung möglich



16. Unfallschaden Vorne Rechts Schadenserweiterung möglich



16. Unfallschaden Vorne Rechts Schadenserweiterung möglich



16. Unfallschaden Vorne Rechts Schadenserweiterung möglich



16. Unfallschaden Vorne Rechts Schadenserweiterung möglich



16. Unfallschaden Vorne Rechts Schadenserweiterung möglich



16. Unfallschaden Vorne Rechts Schadenserweiterung



16. Unfallschaden Vorne Rechts Schadenserweiterung

möglich



16. Unfallschaden Vorne Rechts Schadens-
erweiterung möglich

möglich



16. Unfallschaden Vorne Rechts Schadens-
erweiterung möglich



17. hood



17. hood



17. hood



18.



19. roof



19. roof



19. roof


20. Sitzreihe Hinten



20. Sitzreihe Hinten



21. Sidewall - Rear - Left



21. Sidewall - Rear - Left



21. Sidewall - Rear - Left



22. tailgate



23. Rear bumper




23. Rear bumper



23. Rear bumper



23. Rear bumper




24. Sidewall - Rear - right




25. Tür Hinten - Rechts Aschenbecher



26. Tankdeckel Fangband



27. Windshield



27. Windshield



27. Windshield



28. Side window - Front - right



28. Side window - Front - right



28. Side window - Front - right



28. Side window - Front - right