



status report

customer: Bank 11, Neuss
contract number:
reference:

vehicle data

Audi Q7 4.2 TDI quattro

Vehicle identification number	WAUZZZ4L8AD021742	mileage read:	123734 km
First Registration / construction year:	25.05.2010 / 2010	Visit Date / place of birth:	25.09.2025 Dahlwitz-Hoppegarten
Bodywork:	SUV	Re - import:	unknown
Body type:	hatchback	KBA no. :	0588//AKQ
Fuel / emission class:	diesel / -	transmission type:	automatic
Displacement / power:	4134 ccm / 250 kW (340 PS)	Engine:	four-wheel
paint:	lbisweiß	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	no / -	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Falken	225/55/R18/109V 4 mm
1st axis - right / states .	Falken	225/55/R18/109V 4 mm
2nd axis - Left / states .	Falken	225/55/R18/109V 6 mm
2nd axis - right / states .	Falken	225/55/R18/109V 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Anti-Blockier-System (ABS) • Drive all-wheel drive permanent • Mirrors aspherical, left • Exterior mirror body color • Durchladeeinrichtung (rear center armrest) • Electron. Stability Program (ESP) • Electric windows front + rear • Luggage compartment cover / shade • Cruise control system (cruise control) • LED Taillights • Interior inlays Walnut natural , shiny • • Contrast Paint • Steering wheel (leather) with multifunction • Headlamp leveling automatically • Engine 4.2 ltr. - 250 kW V8 32V TDI • Wheelbase 3002 mm • Tire repair kit • • Windscreen wipers with rain sensor • Controlled power steering electronically • •	• Airbag driver / passenger side • Drive slip control (ASR) • Automatic headlight activation (AS) • Mirrors aspheric, right • Roof rail chrome-plated • Elektron. Differentialsperre (EDS) • Chassis (adaptive air suspension) • Luggage compartment separation (net) • Trunk lid electr. operated (open + close) • Transmission Automatic - Tiptronic (6 stages) • rear window wiper • Isofix seats for child seat • Climate Control • • Steering column (steering wheel) mech . Height / length adjustment • LM rims • • Smokers Package • • Heated windshield washer nozzles • • Heated front seats • Reversible cargo floor

special Features	
• Trailer hitch (ball head electrically adjustable) • Headliner fabric , black • double glazing • Driving Assistance System Automatic Distance Control (Adaptive Cruise Control)	• Power side mirrors . adjustable , heating and folding , with memory • Plus leather design package with sports seats <i>Sitzbezug / Polsterung: Leder, Sportsitze vorn, Sitze vorn elektr. verstellbar, Lendenwirbelstützen vorn, elektr.</i>

• Rearview mirror with auto dip • Open Sky system (fully glazed roof surface - pushed) • Gearshift / selector lever wood • Special paint Ibis White • BOSE sound system • Provision mobile phone / cell phone, integrated in center armrest	<i>verstellbar</i> • Park distance control front and rear, optically with reversing camera (APS Advanced) • Driving Assistance System High-Beam Assistant • Multi-Media-Interface MMI Navigation Plus <i>Sound-System DSP / Audi Sound-System, Sprachsteuerungs-System, Fahrer-Informationen-System (FIS) mit Farbdisplay</i> • Digital radio reception (DAB) • Electric front seats . adjustable (with memory) <i>Sitze vorn elektr. verstellbar, Lendenwirbelstützen vorn, elektr. verstellbar, Sitz vorn links elektr. verstellbar (mit Memory)</i> • Roller blind on rear window • Auxiliary heating <i>Fernbedienung für Standheizung</i> • Xenon headlight Plus (dipped and high beam) <i>Tagfahrlicht, Scheinwerfer-Reinigungsanlage (SRA)</i>
--	---

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Fehlermeldung Bremsanlage

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage: -

-

reference:

Overview conducted technology audit					
Alternator / Generator:			not possible	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
					examined limited
coupling:			unavailable	exhaust System:	
					not possible
engine running:			not possible	shock absorber:	
					not possible
transmission:			not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) could not be verified .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system could not be checked during the inspection .
engine running:	A field test of the engine could not be performed
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*Motor startet nicht, größere Schäden möglich

damage



component	Damage	Rep kind
1. Front fender - right	Subsequently painted	acceptable
2. proof of maintenance	Missing	Replace
3. battery	Damaged	Replace
4. brake system	Error message	Carry out a fault diagnosis
5. motor	Not Jumps On	Carry out a fault diagnosis
6.	Dirty (animal hair)	
7. Cargo cover	Missing	Replace
8.	Not available	acceptable
9. Rear bumper	Scratch(es)	Paint
10. Sidewall - Rear - right	Corroded	Paint
11. Door Rear - right	Wear and tear	acceptable
12. Front door - right	Wear and tear	acceptable
13. Bi xenon headlights - left	Wear and tear	acceptable
14. Front bumper	Scratch(es)	Smart repair
15. Front door - left	Deformed (slightly)	Refurbish and paint
16. Spiegelblinker li.	Damaged	Replace
17. Rear door - left	Wear and tear	acceptable
18. Steering wheel (leather)	Damaged	Replace
19. roof	Corroded	Paint
20. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Front fender - right



4. brake system



6.



6.



9. Rear bumper



10. Sidewall - Rear - right



11. Door Rear - right



12. Front door - right



13. Bi xenon headlights - left



14. Front bumper



14. Front bumper



15. Front door - left



15. Front door - left



16. Spiegelblinker li.



17. Rear door - left



17. Rear door - left



18. Steering wheel (leather)



19. roof