



AUDI A5 I 2011 Cabriolet Diesel
A5 Cabrio 2.0 tdi Advanced 177cv
multitronic

VIN NO WAUZZZ8F3EN006134
Registration Number EY205HV



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-01-29	-	-	215882 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2015-01-29	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250919120853
Inspection Date / Place	2025-09-19 / BCA Lodi	Cosmetic Grade	3


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Sequential
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	2
Body Type	Convertible	Drive Train	Front
Seat Colour		No of Seats	4
Charging Cables		NEDC CO2 Rating (q/km)	132

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			







Equipment

Central locking	Alloys wheels	Electrically folding wing mirrors	Sunroof
Xenon headlamps	Remote central locking	Trip Computer	Stability control
Power assisted steering	Digital Radio	Satellite navigation	Volante multifuncion
Remote adjusting wing mirrors	Cruise control	Tyre Mobility Kit	


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	AVON	255/35//R19 - 96Y
	AVON	255/35//R19 - 96Y / 3 mm
	AVON	255/35//R19 - 96Y / 3 mm

Cosmetic Damage

14 Danni




1 Danni



Component		Damage	Comments
1	Seat / Front Left	Interior / Worn - out	
2	Rim / Front Right	Out of Bodywork / Scratch	
3	Fender / Front Right	Bodywork / Poor Previous Repair	
4	Hood	Bodywork / Poor Previous Repair	
5	Fender / Front Left	Paint / Scratch / Line	
6	Rim / Front Left	Out of Bodywork / Scratch	
7	Door / Front Left	Paint / Scratch / Line	
8	Windshield / Front	Glass Break	
9	Rim / Back Left	Out of Bodywork / Scratch	
10	Fender / Back Left	Paint / Scratch / Line	
11	Rim / Back Right	Out of Bodywork / Scratch	
12	Fender / Back Right	Bodywork / Poor Previous Repair	

13	Bumper / Back	Paint / Scratch / Line
14	Door / Front Right	Paint / Scratch / Line
15	Bumper / Front	Paint / Scratch / Line




1. Seat / Front Left
Interior / Worn - out -




2. Rim / Front Right
Out of Bodywork / Scratch -




3. Fender / Front Right
Bodywork / Poor Previous Repair -



4. Hood
Bodywork / Poor Previous Repair -



5. Fender / Front Left
Paint / Scratch / Line -



6. Rim / Front Left
Out of Bodywork / Scratch -



7. Door / Front Left
Paint / Scratch / Line -



8. Windshield / Front
Glass Break -



9. Rim / Back Left
Out of Bodywork / Scratch -



10. Fender / Back Left
Paint / Scratch / Line -




11. Rim / Back Right
Out of Bodywork / Scratch -




12. Fender / Back Right
Bodywork / Poor Previous Repair -



13. Bumper / Back
Paint / Scratch / Line -



14. Door / Front Right
Paint / Scratch / Line -



15. Bumper / Front
Paint / Scratch / Line -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			