



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Audi A5 Sportback 2.0 TDI quattro

Vehicle identification number	WAUZZZ8T7GA028458	mileage read:	110850 km
First Registration / construction year:	09.11.2015 / 2015	Visit Date / place of birth:	16.05.2025 Heidenheim
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0588//AYS
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 140 kW (190 PS)	Engine:	four-wheel
paint:	Sepangblau Perleffekt	Number of previous owners:	3
Doors / seats:	5 / 4	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	4 - moderate
documents:			
visit condition:	in the parking garage	condition inside:	4 - moderate
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / -	- / -

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Fulda	255/35/R19/96Y 4 mm
1st axis - right / states .	Fulda	255/35/R19/96Y 4 mm
2nd axis - Left / states .	Fulda	255/35/R19/96Y 4 mm
2nd axis - right / states .	Fulda	255/35/R19/96Y 4 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Drive slip control (ASR) • Mirrors aspherical, left • Exterior mirror body color • Door sills with aluminum inlays • Electron. Stability Program (ESP) • Transmission 7-speed - dual-clutch S -tronic • Gloss package • • Instrument cluster with clock • Steering column (steering wheel) mech . Height / length adjustment • facelift <i>Modellpflege / Facelift ab Modelljahr 2012</i> • Engine 2.0 ltr. - 140 kW 16V TDI • Tire repair kit • • Low emissions Euro 6 emission standards • • Start / Stop system •	• Anti-Blockier-System (ABS) • Drive all-wheel drive permanent • Mirrors aspheric, right • Outside temperature display • Elektron. Differentialsperre (EDS) • Electric windows front + rear • Cup holder in center console • Isofix seats for child seat • Climate Control • • Lighted make- up mirror • Monochrome display (6.5 inches) • • • • Heated windshield washer nozzles • Seats, front height adjustable •

special Features	
• Audi music interface • Power side mirrors . adjustable , heating and folding , with auto dip <i>Licht- und Regensensor</i> • Headliner fabric , black • Driving Assistance System Automatic Distance Control (Adaptive Cruise Control) • Driving Assistance System Lane Change Assist and	• Ausstattungs-Paket Sport Edition Plus • Business Package <i>Vorrüstung Mobiltelefon/Handy mit Bluetooth-Schnittstelle, Multi-Media-Interface MMI Navigation, Fahrer-Informations-System (FIS) mit Farbdisplay, Geschwindigkeits-Regelanlage (Tempomat), Mittelarmlehne vorn, Sitzheizung vorn, Lenkrad (Sport/Leder - 3-Speichen) mit Multifunktion</i> • Park distance control front and rear, optically with

Lane Keeping Assist (side assist and lane assist) <i>Fahrassistenz-System: Spurwechselassistent (Side Assist), Fahrassistenz-System: Spurhalteassistent (Lane Assist)</i> • Rearview mirror with auto dip • LM rims 9x19 (10-spoke Y - design) • Multi-Media-Interface MMI Navigation Plus • Digital radio reception (DAB) • Close / start system Advanced Key (convenience key) • Sound system Bang & Olufsen • Glazing behind darkened	reversing camera (APS Advanced) • Driving Assistance System High-Beam Assistant <i>Licht- und Regensensor</i> • Rear seats (3 seats) • LM rims 8,5x18 (5-spoke, V-design, for winter tires) • • Pearl effect paint • Tilting / sliding sunroof Electric . (Glass) with automatic pre-selection • Seat relation / upholstery fabric Atrium • Front sports seats <i>Lendenwirbelstützen vorn, elektr. verstellbar</i> • Xenon plus adaptive light (cornering integrated) <i>Heckleuchten LED, Tagfahrlicht LED, Scheinwerfer-Reinigungsanlage (SRA)</i>
--	---

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Partikelfilter fehler,Bremse Hinten links fehlt Belag

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established



On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	examined limited	
air conditioning:			examined limited	lighting system:	
coupling:			unavailable	examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	examined limited	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug war zum Zeitpunkt der Begutachtung Verschmutzt/Nass/Vereist/Zugeparkt oder wurde bei unzureichender bzw schlechter Beleuchtung besichtigt.Manche Bereiche waren unter Umständen verdeckt oder zugesagt.Unter Umständen waren nicht alle Fahrzeugsysteme und Ausstattung prüfbar.Versteckte Schäden oder Schadensenerweiterung möglich.

damage



component	Damage	Rep kind
1. Rear door - left	Subsequently painted	acceptable
2. Wartung	Due	Replace
3. Abdeckung Spiegel innen	Breakage	Replace
4. Front bumper	Crack	Replace
5. Kühlmittelbehälter	Missing	Carry out a fault diagnosis
6. Front grille top	Scratch(es)	Replace
7. Halogen headlights - right	Increase in play	Replace
8. Halogen headlights - left	Scratch(es)	Replace
9. hood		Smart repair
10. Front fender - left	Scratch(es)	Smart repair
11. Front door - left	Scratch(es)	Smart repair
12. Rear door - left	Scratch(es)	Smart repair
13. Felge vorn links	Scratch(es)	Replace
14. Bremse Komplett Hinten fehlt der Belag	Due	Replace
15. Rear bumper	Crack	Replace
16. Sidewall - Rear - right	Scratch(es)	Refurbish and paint
17. Door Rear - right	Scratch(es)	Paint
18. Front door - right	Scratch(es)	Paint
19. Front fender - right	Deformed	Refurbish and paint
20. Felge vorn rechts	Scratch(es)	Replace
21. Felge Hinten rechts	Scratch(es)	Replace
22. Reifen Hinten rechts	Damaged	Replace
23. Blinker Led vorn rechts	Breakage	Replace
24. Spiegelkappe rechts	Scratch(es)	Smart repair
25. Innenraum	Odour	Ozone treatment
26. Türeinstieg Vorne rechts	Scratch(es)	Smart repair
27. Innenraum	Formation of mould	
28. Dachhimmel	Dirty	
29. Motor	Error message	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



1. Rear door - left



2. Wartung



3. Abdeckung Spiegel innen



3. Abdeckung Spiegel innen



4. Front bumper



4. Front bumper



4. Front bumper



5. Kühlmittelbehälter



6. Front grille top



6. Front grille top



7. Halogen headlights - right



7. Halogen headlights - right



8. Halogen headlights - left



8. Halogen headlights - left



8. Halogen headlights - left



9. hood



9. hood



9. hood



10. Front fender - left



10. Front fender - left



10. Front fender - left



11. Front door - left



11. Front door - left



12. Rear door - left



12. Rear door - left



13. Felge vorn links



13. Felge vorn links



14. Bremse Komplett Hinten fehlt der Belag



14. Bremse Komplett Hinten fehlt der Belag



14. Bremse Komplett Hinten fehlt der Belag



15. Rear bumper



15. Rear bumper



15. Rear bumper




16. Sidewall - Rear - right



16. Sidewall - Rear - right



17. Door Rear - right




17. Door Rear - right



18. Front door - right



18. Front door - right



18. Front door - right



19. Front fender - right



19. Front fender - right



19. Front fender - right



20. Felge vorn rechts



20. Felge vorn rechts



21. Felge Hinten rechts



21. Felge Hinten rechts



22. Reifen Hinten rechts



22. Reifen Hinten rechts



22. Reifen Hinten rechts



22. Reifen Hinten rechts



23. Blinker Led vorn rechts



24. Spiegelkappe rechts



26. Türeinstieg Vorne rechts



26. Türeinstieg Vorne rechts



27. Innenraum



28. Dachhimmel



29. Motor



29. Motor