



AUDI A3

A3 1.4 TFSI Limousine

VIN NO WAUZZZ8V8G1109843
Registration Number V8G1109843



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-06-01	3	2	121438 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-08-30	120400	2016-06-03	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251001095833
Inspection Date / Place	2025-10-01 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	115
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Bluetooth telephone interface	Front parking sensors
Remote adjusting wing mirrors	Satellite navigation	Leather steering wheel	Rear parking sensors
Alloys wheels	Bi Xenon Headlamps	Cruise control	Heated wing mirrors
Remote central locking	Stability control	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage


9 Schäden



0 Schäden




Component		Damage	Comments
1	Fender / Front Left	Paint / Poor Previous Repair	
2	Rim / Front Left	Out of Bodywork / Scratch	
3	Fender / Back Left	Bodywork / Dent / Dent	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Bumper / Back	Paint / Scratch / Scuff	
6	Rim / Back Right	Out of Bodywork / Scratch	
7	Door / Front Right	Bodywork / Dent / Dent	
8	Rim / Front Right	Out of Bodywork / Scratch	
9	Bumper / Front	Bodywork / Breakage / Crack	



1. Fender / Front Left
Paint / Poor Previous Repair -




2. Rim / Front Left
Out of Bodywork / Scratch -




3. Fender / Back Left
Bodywork / Dent / Dent -




4. Bumper / Back
Paint / Scratch / Scuff -



5. Bumper / Back
Paint / Scratch / Scuff -



6. Rim / Back Right
Out of Bodywork / Scratch -



7. Door / Front Right
Bodywork / Dent / Dent -



8. Rim / Front Right
Out of Bodywork / Scratch -



9. Bumper / Front
Bodywork / Breakage / Crack -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
Clutch			
Clutch Functioning		✔	
General			
Test Driven Status		✔	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)