



AUDI A6  
A6 Avant 50 TDI quattro tiptronic

VIN NO WAUZZZF28NN043079  
Registration Number 28NN043079



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-06-01	1	2	92793 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2022-04-06	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922105720
Inspection Date / Place	2025-09-22 / BCA Neuss	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	2967
Engine Size	3.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	anthrazit	Seat Covering	Cloth/Leather
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents



Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			













## Equipment

Trafficsignrecognition	Airbag Status	Anti-lock braking	Cruise control
Digital Radio	Heated wing mirrors	Remote central locking	Satellite navigation
Sunroof	Electrictailgate	LED Headlamps	Rear parking sensors
USB Socket	Alloys wheels	Bluetooth telephone interface	Diesel particulate filter
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Stability control
Electrically folding wing mirrors	Leather steering wheel	Rain sensitive windscreen wipers	

## Equipment Details

Tow Ball Type	Pivoted	Air Conditioning	Four Zone Climate Control
Alloy Wheel Size	19	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front	Sunroof Type	Opening Panoramic


## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	3	Extra Wheel - 4 Tyre Depth	3




Cosmetic Damage

4 Schäden



2 Schäden



Component	Damage	Comments
1 Fender / Front Left	Paint / Poor Previous Repair	
2 Fender / Front Right	Paint / Poor Previous Repair	
3 Door / Front Left	Bodywork / Dent / Dent	
4 Door Handle / Front Left	Paint / Scratch / Scuff	
5 Panel Filling / Front Left	Interior / Scratched	
6 Center Console	Interior / Scratched	



1. Fender / Front Left  
Paint / Poor Previous Repair -



2. Fender / Front Right  
Paint / Poor Previous Repair -



3. Door / Front Left  
Bodywork / Dent / Dent -



4. Door Handle / Front Left  
Paint / Scratch / Scuff -



5. Panel Filling / Front Left  
Interior / Scratched -



6. Center Console  
Interior / Scratched -



## Mechanical Condition

### Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

### Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)