



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Audi A4 Avant basis

Vehicle identification number	WAUZZZF4XJA127374	mileage read:	210796 km
First Registration / construction year:	16.02.2018 / 2017	Visit Date / place of birth:	10.07.2025 Neuss
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0588//BFU
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1968 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	Florettsilber Metallic	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	08.2026 / 08.2026	cushion type:	substance
Service book available:	digital	Interior Color:	gray
smoking vehicle:	no	Last service km / on the:	205208 / 17.03.2025
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	2 - Good
visit condition:	-	condition inside:	2 - Good
state general:	2 - Good		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	digital / -	205208 / 17.03.2025

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Hankook	205/60/R16/92V 2 mm
1st axis - right / states .	Hankook	205/60/R16/92V 2 mm
2nd axis - Left / states .	Continental	205/60/R16/92V 3 mm
2nd axis - right / states .	Continental	205/60/R16/92V 3 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	Gebraucht	

standard equipment	
• Airbag driver / passenger side <i>Airbag Beifahrerseite abschaltbar</i> • Acceleration skid control (ASR) with EDS • Mirrors aspherical, left • Exterior mirror body color • Bluetooth interface (mobile phone) incl . Belt microphone • Roof spoiler • Door sills with aluminum inlays • Electron. Stability Program (ESP) • Driving Assistance System City Emergency Braking (Audi pre sense City) • Loading bay cover electrically • Speed ??Begrenzeranlage • Interior inlays diamond paint silver gray • • Bumper protection (stainless steel) • LM rims • Engine 2.0 ltr. - 110 kW 16V TDI • Smokers Package • • • Heated windshield washer nozzles • • Seat relation / upholstery fabric Index • Start / Stop system • LED daytime running lights • Reversible cargo floor	• Anti-Blockier-System (ABS) • • Mirrors aspheric, right • LED turn signals integrated into outside mirrors • brake Assist • roof rails • Elektron. Differentialsperre (EDS) • Electron. Stability control (ESC) • Driver assistance system drowsiness detection (break recommendation) • Luggage compartment separation (net) • Transmission 7-speed - dual-clutch S -tronic • Isofix seats for child seat • • Light and rain sensor • Front center armrest • Multi Media Interface MMI Basic Plus / MMI Radio Plus • Tire repair kit • • Low emissions Euro 6 emission standards • SCR (AdBlue technology) • Power steering electro-mechanical • Front seats manually adjustable • Bumper version base • •

special Features	
• Storage and luggage compartment package	• Trailer hitch (ball head pivots)

• Audi connect (emergency call and assistance system) • Electric wing mirror . adjustable , heated and folding , with auto dip and automatic parking <i>Außenspiegel mit Bordsteinautomatik, rechts</i> • Park distance control front and rear, both visually and sonically with selective display (GSP Plus) • Driving Assistance System Traffic Sign Recognition • Urea tank (SCR) 24 Ltr . • Comfort climate control 3 zones • LM rims 7x16 (Forge lightweight construction wheel for winter tires) • Steering wheel (leather) with multifunction plus • LED headlights <i>Heckleuchten LED mit dynamischem Blinklicht</i> • jack	• Equipment package Technology Selection <i>Audi Smartphone Interface, Kombiinstrument digital (virtual cockpit), Multi-Media-Interface MMI Navigation Plus mit MMI Touch, Bluetooth-Schnittstelle (Mobiltelefon) inkl. Gurtmikrofon, Audi connect (Internetbasierende Dienste), Fahrer-Informationen-System (FIS) mit Farbdisplay, Komfortschlüssel mit sensorgesteuerter Heckklappenentriegelung inkl. (öffnen + schliessen), Gepäckraumklappe elektr. betätigt (öffnen + schliessen)</i> • Headliner fabric , black • Driving Assistance System Speed ??Limit Display • <i>Geschwindigkeits-Begrenzeranlage</i> • Rearview mirror with auto dip • Fuel tank 54 Ltr . • • Metallic paint •
---	--

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	yes yes
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident

damages (other than the usual signs of use) .

reference:

Overview conducted technology audit			
Alternator / Generator:	✓ in order	Battery / accumulator:	✓ in order
oil loss:	✓ examined limited		
air conditioning:	✓ in order	lighting system:	✓ in order
coupling:	✗ unavailable	exhaust System:	✓ examined limited
engine running:	✓ in order	shock absorber:	✓ examined limited
transmission:	✓ in order		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission was examined during the test drive / pull test .
reference:	*Fahrzeug hat im gesamten eine Hohe Lackdicke Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1.	Dirty	
2.	Not okay	Replace
3. Türeinstieg Vorne - Links	Delle	Smart repair
4. Türeinstieg Hinten - Links	Damaged	Refurbish and paint
5. Heckdeckelverkleidung	Scratch(es)	Replace
6. Türeinstieg Hinten - Rechts		Refurbish and paint
7. Türeinstieg Vorne - Rechts		Refurbish and paint
8. hood	Rust	Paint
9. Front bumper	Damaged	Replace
10. Front fender - left	Scratch(es)	Smart repair
11. Rear bumper	Scratch(es)	Paint
12. Sidewall - Rear - right	Scratch(es)	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims




engine compartment



service book



Others



Navigation system




1.




1.




1.



1.



1.



1.



2.



2.



2.



3. Türeinstieg Vorne - Links



3. Türeinstieg Vorne - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



4. Türeinstieg Hinten - Links



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



5. Heckdeckelverkleidung



6. Türeinstieg Hinten - Rechts



6. Türeinstieg Hinten - Rechts




7. Türeinstieg Vorne - Rechts




7. Türeinstieg Vorne - Rechts



7. Türeinstieg Vorne - Rechts



8. hood



8. hood



8. hood



9. Front bumper



9. Front bumper



9. Front bumper



10. Front fender - left



10. Front fender - left



11. Rear bumper



11. Rear bumper



11. Rear bumper




11. Rear bumper



12. Sidewall - Rear - right



12. Sidewall - Rear - right



12. Sidewall - Rear - right