

Vehicle details

VIN	WAUZZZF56 MA036017	Brand	AUDI	Maintenance date	-
Licence Plate	K8-30-XH	Model	A5 Sportback 40 TFSI S tronic Business Edition 5d	Maintenance mileage	-
Registration date	31/03/2021	Year	2021	Exterior Color	Black Metallic
Odometer	84 297 km	Engine size	1984	interior Color	Grey
Fuel	Petrol	Body Type	Coupe	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	12/08/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Remote key	✓
Sat Nav CD ROM Software	✓
Spare key	✗


Tyres

Continental 255/35/19 Summer 4.5 mm		Continental 255/35/19 Summer 5.0 mm	
Continental 255/35/19 Summer 6.0 mm		Continental 255/35/19 Summer 6.0 mm	

Exterior

3		Part Alloy wheel 19" Position Front left Damages Scratched Severity - Repair mode Lumpsum repair	4		Part Door Position Back left Damages Dented Severity Diameter (mm) > 20 Repair mode Repair
5		Part Bumper Position Back right Damages Scratched Severity Length (cm) > 10 Repair mode Repair	6		Part Wing Position Back right Damages Dent & Chips Severity Diameter (mm) > 20 Repair mode Repair
7		Part Door Position Back right Damages Dented Severity Diameter (mm) > 20 Repair mode Repair	8		Part Door Position Front right Damages Dented Severity Diameter (mm) > 20 Repair mode Smart Repair
9		Part Alloy wheel 19" Position Front right Damages Scratched Severity - Repair mode Lumpsum repair	10		Part Wing Position Front right Damages Dent & Chips Severity - Repair mode Repair
11		Part Bumper Position Front Damages Scratched Severity Length (cm) > 10 Repair mode Repair	13		Part Sill cover Position Right Damages Scratched Severity Length (cm) > 10 Repair mode Repair

Interior damage

1		Part Spare key Position - Damages Missing Severity - Repair mode Replace	2		Part Interior roof lining Position Front left Damages Burnt Severity - Repair mode Smart Repair
12		Part Interior complete Position Centre Damages Stained/dirty Severity - Repair mode Cleaning			