



status report

customer:	BCA Autoauktionen GmbH
contract number:	
reference:	

vehicle data			
Audi Q5 50 TDI quattro S line			
Vehicle identification number	WAUZZZFY2P2045029	mileage read:	32543 km
..			
First Registration / construction year:	27.12.2022 / 2022	Visit Date / place of birth:	16.09.2025 Dorfmark
Bodywork:	SUV	Re - import:	yes
Body type:	hatchback	KBA no. :	0588//BXH
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2967 ccm / 210 kW (286 PS)	Engine:	four-wheel
paint:	gray	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	12.2025 / 12.2025	cushion type:	Leather / fabric
Service book available:	digital	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	digital / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Pirelli	235/60/R18/103W 5 mm
1st axis - right / states .	Pirelli	235/60/R18/103W 5 mm
2nd axis - Left / states .	Pirelli	235/60/R18/103W 7 mm
2nd axis - right / states .	Pirelli	235/60/R18/103W 7 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag driver / passenger side • Anti-Blockier-System (ABS) • • Exterior mirror body color • Roof rails black • Driving Assistance System City Emergency Braking (Audi pre sense City) • Velour floor mats • Trunk lid electr. operated (open + close) • Transmission Automatic - Tiptronic (8-step) • Isofix seats for child seat • • Bumper protection (stainless steel) • LM rims • Mild-Hybrid 210 kW (Motor 3.0 Ltr. - 210 kW V6 24V TDI) • facelift • Non smoking package • Digital radio reception (DAB) • Tire repair kit • • Low-emission according to the Euro 6d exhaust gas standard • • Start / Stop system • LED daytime running lights •	• All-wheel clutch • Drive all-wheel drive • Audi Drive Select • Roof edge spoiler S -line • • Acoustic windshield glass • Luggage compartment separation (net) • Cruise control system (cruise control) <i>Geschwindigkeits-Begrenzeranlage</i> • Cup holder • • Fuel tank 65 ltr. • Steering column (steering wheel) mech . Height / length adjustment • Auxiliary air heater electrically • • Multifunction camera • Electro-mechanical parking brake • Wheelbase 2819 mm • • • SCR (AdBlue technology) • Power steering electro-mechanical • Bumper Sport design • Universal Interface Bluetooth •

special Features	
• Storage and luggage compartment package <i>Gepäckraum-Abtrennung (Netz), Gepäcknetz an</i>	• Ambient lighting •



<i>Vordersitzlehne, Getränkehalter hinten</i> • Trailer hitch (ball head pivots) • Audi connect (internet based services) • Anti-theft wheel (wheel locks) • Driving assistance system occupant protection system proactive <i>Einparkhilfe vorn und hinten, optisch (APS Plus), Fahrassistenz-System: Insassen-Schutzsystem (Audi pre sense basic), Rückfahrkamera</i> • Chassis (adaptive air suspension) • Gloss package • Rearview mirror with auto dip • Child Safety Pack <i>Kindersicherung elektr. betätigt, Isofix-Aufnahmen für Kindersitz</i> • Comfort climate control 3 zones • • Audi Matrix LED headlights <i>Heckleuchten LED (pro) mit dynamischer Lichtinszenierung und mit dynamischem Blinklicht, Scheinwerfer-Reinigungsanlage (SRA), Multifunktionskamera</i> • Multi-Media Interface MMI Navigation plus with MMI touch • Electric front seats . adjustable (left with memory) • Sound system DSP / Audi sound system	• Electric wing mirror . adjustable , heated and folding , with auto dip and Memory <i>Außenspiegel mit Bordsteinautomatik, rechts</i> • Driving Assistance System Start Assist (hold assist) • Driving Assistance System Lane Departure Prevention (active lane assist) <i>Fahrassistenz-System: Fernlichtassistent, Fahrassistenz-System: Verkehrszeichenerkennung</i> • Vehicles without Audi Phone Box • Urea tank (SCR) 24 Ltr . • Interior-Paket S line <i>Einstiegsleisten mit Aluminiumeinlage und Schriftzug, beleuchtet, Innenausstattung: Dekoreinlagen Aluminium Matt, Innenausstattung: Dekoreinlagen Akzentteile schwarz glänzend, Pedale und Fußstütze in Edelstahl, Dachhimmel Stoff, schwarz, Fußmatten Velours, Sitzbezug / Polsterung: Leder / Stoff Sequenz mit Logo-Prägung in Vordersitzlehnen, Sportsitze vorn, Lenkrad (Leder - 3-Speichen) mit Multifunktion plus und Schaltfunktion</i> • Instrument cluster digital (virtual cockpit plus) • Convenience key with sensor-controlled tailgate release <i>Start-Stop-Knopf</i> • • Front center armrest Comfort Equipment • Pearl effect paint • • Auxiliary heating
--	--

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Unfallschaden Stoßfänger Hinten, Kotflügel VL, Tür HR Schaden und Kosten Erweiterung möglich Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. maintenance	Due	Replace
2. proof of maintenance	Missing	Replace
3. Rear bumper	Damaged	Replace
4.	Scrape	Smart repair
5. Front fender - left	Deformed	Refurbish and paint
6.	Scrape	Smart repair
7. Front bumper	Damaged	Replace
8. Door Rear - right	Deformed	Refurbish and paint
9.	Scrape	Smart repair
10. exterior body	Surface scratch(es)	
11.	Wear and tear	acceptable
12.	Dirty	
13.	Odour	Ozone treatment
14.	Damaged	Replace
15. tailgate trim	Scrape	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



3. Rear bumper



3. Rear bumper



3. Rear bumper



3. Rear bumper



3. Rear bumper



4.



4.



5. Front fender - left



5. Front fender - left



6.



6.



7. Front bumper



7. Front bumper



8. Door Rear - right



8. Door Rear - right



8. Door Rear - right



9.




9.



9.



10. exterior body



11.



11.



12.



12.



14.



14.



15. tailgate trim



15. tailgate trim