

Vehicle details

VIN	WAUZZZGE9 MB020208	Brand	AUDI	Maintenance date	-
Licence Plate	K9-43-JR	Model	e-tron Sportback 50 quattro edition	Maintenance mileage	-
Registration date	30/12/2020	Year	2020	Exterior Color	Black Solid
Odometer	107 071 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	06/10/2025	Inspection loc.	Dekra Ayvens		
					
					
					

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
4x4	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓


Removable element

Vehicle charger	✓
Load cover	✗
Wireless charger	✗

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 235/55/19 Summer 4.2 mm		Continental 235/55/19 Summer 4.0 mm	
Continental 235/55/19 Summer 4.3 mm		Continental 235/55/19 Summer 4.2 mm	

Exterior

4



Part

Step plate

Position

Back left

Damages

Dent & Chips

Severity

-

Repair mode

For info

●

●

5



Part

Door

Position

Front right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

6



Part

Wing

Position

Front right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

7



Part

Bonnet

Position

-

Damages

Hail damaged

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

8



Part

Windscreen

Position

-

Damages

Stone impact

Severity

-

Repair mode

For info

●

●

9



Part

Door

Position

Back left

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

10



Part

Door

Position

Front left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

11



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

Interior damage

1



●

Part	Load cover
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

3



● ● ● ●

Part	Interior complete
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

2



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info