

BMW 2er Active Tourer 218d Active Tourer Aut.

VIN NO WBA2C11050V337641 Registration Number 050V337641



MOT Date

Number of Owners

Number of Keys Odometer Reading

☆-

23 3

22

2 181831 km

Last Service

Last Service Mileage

First Registration Date Cour

Country First Registered

=

į

= 2014-11-20

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250903085150
Inspection Date / Place	2025-09-03 / BCA Oberndorf	Cosmetic Grade	2

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	109
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			































Equipment

Tinted Glass	USB Socket	Alloys wheels	Anti-lock braking
Bluetooth telephone interface	e Diesel particulate filter	Front parking sensors	Remote adjusting wing mirrors
Roof rails	Split folding rear seats	CD Player	Electrically folding wing mirrors
Leather steering wheel	Radio	Tow ball	Airbag Status
Ambientlighting	Auxiliary Socket	Cruise control	Front fog lamps
Head up Display	Remote central locking	Satellite navigation	Stability control
Central locking	Electrictailgate	LED Headlamps	Rear parking sensors


Equipment Details

Tow Ball Type	Detachable	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	16	Seat Heating	No

Wheels & Tyres

Left Front Tyre Depth	4	Right Rear Tyre Depth	4
Left Rear Tyre Depth	4	Right Front Tyre Depth	4

Cosmetic Damage



	Component	Damage	Comments
1	Windshield / Front	Glass Break / Impact	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Mirror / Front Left	Paint / Scratch / Scuff	
4	Rim / Back Left	Out of Bodywork / Scratch	
5	Bumper / Back	Paint / Scratch / Scuff	



1. Windshield / Front Glass Break / Impact -

2. Bumper / Front Paint / Scratch / Scuff -



3. Mirror / Front Left Paint / Scratch / Scuff -



4. Rim / Back Left Out of Bodywork / Scratch -



5. Bumper / Back Paint / Scratch / Scuff -

Mechanical Condition

Equipments Test			
Central Locking	⊘	Electric Windows	⊘
Audio Equipment	⊘	AC / Heating System	⊘
Main & Spare Keys Functioning	•	Parking Sensors / Cameras Functioning	•
Other Equipments	•		
Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	⊘	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•	Display Defect	•
Service Light	•	Tire Pressure Monitoring System	•
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	⊘		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** Not Performed No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide