



status report

customer:	Bank 11, Neuss
contract number:	
reference:	

vehicle data			
BMW Baureihe X1 sDrive 18 i			
Vehicle identification number	WBA31AA0903M88505	mileage read:	89953 km
..			
First Registration / construction year:	03.03.2021 / 2020	Visit Date / place of birth:	24.09.2025 Dorfmark
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	0005//CKQ
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1499 ccm / 100 kW (136 PS)	Engine:	front-wheel drive
paint:	white	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	09.2025 / 09.2025	cushion type:	substance
Service book available:	digital	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	77401 / 06.11.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	digital / -	77401 / 06.11.2024
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Kumho	225/55/ZR17/101W 5 mm
1st axis - right / states .	Kumho	225/55/ZR17/101W 5 mm
2nd axis - Left / states .	Kumho	225/55/ZR17/101W 5 mm
2nd axis - right / states .	Kumho	225/55/ZR17/101W 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Filing package • Anti- lock braking system (ABS) • front armrest • AUX - IN port (AUX -IN) • brake Assist • Anti-theft device for wheels (rim locks) • Fahrassistentz-System Active Guard (Bremsassistent) • Driving Assistance System Performance Control • • Body 5-door • Rear curtain airbag system • Foldable cargo compartment floor • LM rims • Engine 1.5 ltr. - 100 kW 12V • • Wheelbase 2670 mm • Rear seatback split / folding (402040) • Heated windshield washer nozzles • Front Side Airbags • Service system Intelligent Emergency incl . TeleServices • Power steering Servotronic • Start / Stop System (Function) • Tinted heat insulating glass	• Airbag Driver / passenger side • Drive type front-wheel drive • Equipment package ConnectedDrive Services • board computer • • Dynamic Stability Control (DSC) • Driving Assistance System Collision Warning with braking function • Velour floor mats • Isofix admissions for child seat in back seat • air Conditioning • Head airbag system front • Load compartment floor variable • model refinement • Multifunction for steering wheel • Parking brake electrically • Tire Pressure Monitoring System • Low in emissions according to the Euro 6d emissions standard • Windscreen wipers with rain sensor • Service-System ConnectedDrive Services • • Seat cover / upholstery fabric grid • immobilizer • Central locking with remote control

special Features	
• Alpine white paint (Uni) • Anti-theft alarm system with interior protection • Cruise control system with brake function • Navigation System Navigation (USB)	• Roof rails black • Handsfree Bluetooth with advanced smartphone connectivity • Steering wheel (sports / leather)

- Tyre repair kit (Mobility -Pack)
- Headlight LED
- Heated front seats

- Park Distance Control (PDC)
- Rear View Camera
- Headlight cleaning system (SRA)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Bremsanlage Fehlermeldung, Motor Klappergeräusche

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Tür und Seitenteil HR. Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:		examined limited	Battery / accumulator:		examined limited
oil loss:		examined limited			
air conditioning:		examined limited	lighting system:		examined limited
coupling:		unavailable	exhaust System:		examined limited
engine running:		Out of order	shock absorber:		examined limited
transmission:		examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **It rattles were found.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Bremsanlage Fehlermeldung Fehlerdiagnose durchführen lassen Unfallschaden Tür und Seitenteil HR Karosserie Außen teilweise Nachlackiert Motorhaube lässt sich nicht öffnen Fahrzeug nur eingeschränkt prüfbar Motor Klappergeräusche Schaden und Kosten Erweiterung möglich

damage



component	Damage	Rep kind
1. Sidewall - Rear - right	Subsequently painted	acceptable
2. Roof frame - right	Subsequently painted	acceptable
3. maintenance		acceptable
4. brake system	Error message	Carry out a fault diagnosis
5. Rear bumper	Damaged	Replace
6. roof	Dented	Smart repair
7. Rear door - left	Deformed (slightly)	Refurbish and paint
8. Rim rear - left	Damaged	Paint
9. Front door - left	Deformed (slightly)	Refurbish and paint
10. Front bumper	Scrape	Paint
11. Rim front - right	Damaged	Paint
12. Door Rear - right	Accident damage	Replace
13.	Accident damage	Replace
14. Sidewall - Rear - right	Accident damage	Refurbish and paint
15. exterior body	Surface scratch(es)	
16.	Wear and tear	acceptable
17.	Dirty	
18.	Odour	Ozone treatment
19.	Dirty (animal hair)	
20. flooring	Burn hole	Replace
21. hood	Not open	Carry out a fault diagnosis
22. Kappe Heckwischer	Missing	Replace
23. motor	Abnormal noises	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



1. Sidewall - Rear - right



2. Roof frame - right



4. brake system



4. brake system



5. Rear bumper



5. Rear bumper



5. Rear bumper




5. Rear bumper




5. Rear bumper




6. roof




6. roof



6. roof



6. roof



6. roof



6. roof



6. roof



7. Rear door - left



7. Rear door - left




8. Rim rear - left



8. Rim rear - left



9. Front door - left



9. Front door - left



10. Front bumper



10. Front bumper



10. Front bumper



10. Front bumper




11. Rim front - right



11. Rim front - right



12. Door Rear - right



12. Door Rear - right



12. Door Rear - right



12. Door Rear - right




13.



13.



14. Sidewall - Rear - right




14. Sidewall - Rear - right



15. exterior body



16.



16.



17.



17.



19.



19.



20. flooring



20. flooring



20. flooring



20. flooring



21. hood



22. Kappe Heckwischer