


DEKRA Automotive Solutions

Vehicle details

VIN	WBA31CG08 NCJ29561	Brand	BMW	Maintenance date	31/10/2024
Licence Plate	HUY38U	Model	Serie-5-Touring-G31-2017	Maintenance mileage	115 874 km
Registration date	02/12/2021	Year	2021	Exterior Color	Other
Odometer	120 683 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	16/01/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Load cover	✓
Towing hook	✓
Refill emergency kit	✗


Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓
Charging kit	✓
Type 2 charging cables	✓

DEKRA Automotive Solutions

Tyres

Pirelli 245/45/18 Y Summer 4.0 mm



Pirelli 245/45/18 Y Summer 4.0 mm




Pirelli 245/45/18 Y Summer 4.0 mm



Pirelli 245/45/18 Y Summer 4.0 mm

Winter kit

Pirelli 245/45/18 H Winter 9.0 mm



Pirelli 245/45/18 H Winter 9.0 mm



Pirelli 245/45/18 H Winter 9.0 mm



Pirelli 245/45/18 H Winter 9.0 mm

Damages

1



Part	Alloy wheel
Position	-
Damages	Scratched
Severity	-
Repair mode	For info

2



Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

3



Part	Bumper
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum repair
Paint cracked	

4



Part	Headlight
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info

5



Part	Headlight
Position	Front left
Damages	Stone impact
Severity	-
Repair mode	For info

6



Part	Bumper grille
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace

7



Part	Wing
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

8



Part	Door
Position	Front left
Damages	Dented
Severity	-
Repair mode	For info

9



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

10



Part	Sill
Position	Right
Damages	Scratched
Severity	-
Repair mode	For info

DEKRA Automotive Solutions

11



●●

Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

12



●●●

Part	Windscreen
Position	Front
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

13



●●●

Part	Bonnet
Position	Front
Damages	Stone impact
Severity	-
Repair mode	For info