



status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

BMW Baureihe 3 Touring 316 i

Vehicle identification number	WBA3G11010KR69269	mileage read:	158969 km
First Registration / construction year:	07.07.2015 / 2015	Visit Date / place of birth:	02.09.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	station wagon	KBA no. :	0005//BOY
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1598 ccm / 100 kW (136 PS)	Engine:	rear-wheel drive
paint:	MINERALGRAU METALLIC	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	digital	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	78744 / 28.02.2020
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained: digital / 6	78744 / 28.02.2020
<input checked="" type="checkbox"/> Fernbed . Auxiliary heating	<input checked="" type="checkbox"/> partition net	<input checked="" type="checkbox"/> Wind Deflector	<input checked="" type="checkbox"/> AHK fixed
<input checked="" type="checkbox"/> AHK removable	<input checked="" type="checkbox"/> AHK swivel	<input checked="" type="checkbox"/> AHK key	<input checked="" type="checkbox"/> Fernbed . entertainment
<input checked="" type="checkbox"/> headphone	<input checked="" type="checkbox"/> Load compartment cover	<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> navigation system
<input checked="" type="checkbox"/> Persenning	<input checked="" type="checkbox"/> Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Bridgestone	205/60/R16/96H 4 mm
1st axis - right / states .	Bridgestone	205/60/R16/96H 4 mm
2nd axis - Left / states .	Bridgestone	205/60/R16/96H 4 mm
2nd axis - right / states .	Bridgestone	205/60/R16/96H 4 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
<ul style="list-style-type: none"> • Airbag switched off • Anti- lock braking system (ABS) • Body color door mirrors • board computer • Brake Energy Regeneration • Rev counter • Dynamic brake light • Driving Assistance System Driving Experience Control • Handsfree with USB interface • Automatic transmission - (8-step) • LED Taillights • Isofix admissions for child seat in back seat • Rear curtain airbag system • Rear headrests folding • Steering column (steering wheel) mechan. adjustable • Engine 1.6 ltr. - 100 kW 16V • Non smoking package • Low emissions Euro 6 emission standards • Heated windshield washer nozzles • Service system Intelligent Emergency incl . TeleServices • Seat cover / upholstery fabric Move • Start-stop button • immobilizer 	<ul style="list-style-type: none"> • Airbag Driver / passenger side • AUX - IN port (AUX -IN) • White direction indicator lights • brake Assist • Check Control System • Durchladeeinrichtung (rear center armrest) <i>Rücksitzlehne geteilt/klappbar (40:20:40)</i> • Dynamic Stability Control (DSC) <i>Dynamische Traction Control (DTC)</i> • Electric windows front + rear • Velour floor mats • Tailgate automatically • Interior interior trim Satin Silver , matt • Body 5-door • Head airbag system front • Steering wheel (leather) • Light and rain sensor • Fog Lights • Tyre Defect Indicator • Shift Indicator • Front Side Airbags • Power steering Servotronic • Seats, front height adjustable • Start / Stop System (Function) • Central locking with remote control

special Features	
<ul style="list-style-type: none"> • Adaptive Headlights • Bi -xenon headlights <i>Scheinwerfer-Reinigungsanlage (SRA)</i> 	<ul style="list-style-type: none"> • Audio Navigation system Business <i>Audiosystem BMW Professional (Radio/CD-Player MP3-fähig)</i> • Comfort Package













<ul style="list-style-type: none"> • Driving Assistance System High-Beam Assistant • Seat lumbar support , front left and right, electr. adjustable • Metallic paint • Multifunction for steering wheel • Park Distance Control (PDC) front and rear 	<p><i>Licht-Paket, Ambiente-Beleuchtung, Fußraumbeleuchtung vorn, Ausstiegsleuchten in Türverkleidung unten, Leseleuchten vorn, Leseleuchten hinten, Ablage-Paket, Klimaautomatik 2-Zonen mit autom. Umluft-Control, Sitzheizung vorn, Innenspiegel mit Abblendautomatik</i></p> <ul style="list-style-type: none"> • Instrument cluster (extended range) • heated steering wheel • Front center armrest adjustable • Panoramic sunroof (glass) • Sun protection glazing
--	---

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	no no
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Oberflächenkratzer/Kratzer rundum

damage



component	Damage	Rep kind
1. roof	Subsequently painted	acceptable
2. Rear door - left	Subsequently painted	acceptable
3. Front door - left	Subsequently painted	acceptable
4. Front fender - left	Subsequently painted	acceptable
5. hood	Subsequently painted	acceptable
6. Front fender - right	Subsequently painted	acceptable
7. maintenance	Due	Replace
8.	Not available	acceptable
9. Front bumper	Scrape	Paint
10. Front fender - left	Execution defect	Paint
11. Front fender - left	Wear and tear	acceptable
12.	Dirty	

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record




front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. roof



2. Rear door - left



3. Front door - left



4. Front fender - left



5. hood



6. Front fender - right



7. maintenance



9. Front bumper



9. Front bumper



10. Front fender - left



11. Front fender - left



11. Front fender - left



12.



12.