



status report

customer: Bank 11, Neuss
contract number: 592748030
reference:

vehicle data

BMW Baureihe 3 Gran Turismo 330 d xDrive

Vehicle identification number	WBA3Z51000D398573	mileage read:	206985 km
First Registration / construction year:	09.09.2014 / 2014	Visit Date / place of birth:	02.10.2025 Heidenheim
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	0005//BUG
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2993 ccm / 190 kW (258 PS)	Engine:	four-wheel
paint:	MINERALGRAU METALLIC	Number of previous owners:	Unbekannt
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	digital	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	digital / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Anderer	235/45/ZR18/98W 5 mm
1st axis - right / states .	Anderer	235/45/ZR18/98W 5 mm
2nd axis - Left / states .	Anderer	235/45/ZR18/98W 5 mm
2nd axis - right / states .	Anderer	235/45/ZR18/98W 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Airbag switched off • active Bonnet • Anti- lock braking system (ABS) • Exhaust system (2-pipe system) with chrome screens • Power side mirrors . adjustable and heated • LED indicator lights • brake Assist • Check Control System • Durchladeeinrichtung (rear center armrest)
<i>Mittelarmlehne hinten, Rücksitzlehne geteilt/klappbar (40:20:40)</i> • Dynamic Stability Control (DSC)
<i>Dynamische Traktions Control (DTC)</i> • Electric windows front + rear • Velour floor mats • Automatic transmission - (8-step) • LED Taillights • Body 5-door • Head airbag system front • Steering column (steering wheel) mechan. adjustable • Fog Lights • Tyre Defect Indicator • Low emissions Euro 6 emission standards • Heated windshield washer nozzles • Front Side Airbags • Power steering Servotronic • Start-stop button • Body color bumpers • Central locking with remote control | <ul style="list-style-type: none"> • Airbag Driver / passenger side • Active rear spoiler (electrically retractable) • Drive xDrive (all-wheel) • AUX - IN port (AUX -IN) • Body color door mirrors • board computer • Brake Energy Regeneration • Rev counter • Dynamic brake light • Driving Assistance System Driving Experience Control • Handsfree Bluetooth with USB audio interface • Luggage compartment cover / shade • Tailgate automatically • Isofix admissions for child seat in back seat • Rear curtain airbag system • Rear headrests folding • Engine 3.0 ltr. - 190 kW turbodiesel • Tire Pressure Monitoring System • Rußpartikelfilter • Shift Indicator • Rear side airbag • Service system Intelligent Emergency incl . TeleServices • Seat cover / upholstery fabric Move • Start / Stop System (Function) • immobilizer |
|---|--|

special Features	
• Filing package • alarm system • Bi -xenon headlights <i>Tagfahrlicht LED, Scheinwerfer-Reinigungsanlage (SRA)</i> • Driving Assistance System High-Beam Assistant • Handsfree Bluetooth with advanced smartphone connectivity • Rearview mirror with auto dip • Automatic climate control with 2-zone automatic . Recirculated air control <i>Sensor Scheibenbeschlagerkennung</i> • Seat lumbar support , front left and right, electr. adjustable • Light package <i>Ambiente-Beleuchtung, Fußraumbeleuchtung vorn, Leseleuchten vorn, Leseleuchten hinten</i> • Front center armrest adjustable • Smokers Package • Rear View Camera • Electric front seats . adjustable (left with memory) <i>Außenspiegel mit Memoryfunktion und Bordsteinautomatik</i>	• Adaptive Headlights <i>Abbiegelicht</i> • Audio navigation system Professional <i>Audiosystem BMW Professional (Radio / DVD-Laufwerk MP3-fähig), Freisprecheinrichtung Bluetooth mit USB-/Audio-Schnittstelle</i> • Design and equipment line Luxury <i>Luftauslass (Air Breather) Chrom, Lufteinlassblende Chrom, Sitzbezug / Polsterung: Stoff Move, Innenausstattung: Edelholz Finition, LM-Felgen, Lenkrad (Sport/Leder)</i> • Driving Assistance System Parking Assist <i>Park-Distance-Control (PDC) vorn und hinten</i> • Cruise control system , active with Stop & Go function <i>Geschwindigkeits-Regelanlage mit Bremsfunktion</i> • Instrument cluster (extended range) • Comfort Access (close / start system) <i>Heckklappenbetätigung automatisch</i> • Light and rain sensor • Metallic paint • Panoramic sunroof (glass) • Run-flat tire system (run flat) • Service system ConnectedDrive • Sun protection glazing

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:		 in order	Battery / accumulator:		 in order
oil loss:		 examined limited			
air conditioning:		 in order	lighting system:		 in order
coupling:		 unavailable	exhaust System:		 examined limited
engine running:		 in order	shock absorber:		 not checked
transmission:		 not checked			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission has not been tested for visiting time .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen. Fahrzeug mit bestehendem Hagelschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Hagelschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

damage



	component	Damage	Rep kind
1.	Rim front - left	Scratch(es)	Paint
2.	Front door - left	Execution defect	Refurbish and paint
3.	Front fender - left	Execution defect	Refurbish and paint
4.	Rear door - left	Execution defect	Paint
5.	Sidewall - Rear - Left	Execution defect	Refurbish and paint
6.	Sidewall - Rear - right	Execution defect	Refurbish and paint
7.	Door Rear - right	Execution defect	Refurbish and paint
8.	Front door - right	Execution defect	Refurbish and paint
9.	Front fender - right	Execution defect	Refurbish and paint
10.	hood	Hail damage	Refurbish and paint
11.	roof	Hail damage	Refurbish and paint
12.		Damaged	Replace
13.		Damaged	Replace
14.	Roof frame - left	Execution defect	Refurbish and paint
15.	Roof frame - right	Hail damage	Refurbish and paint
16.	tailgate	Hail damage	Refurbish and paint
17.	Front bumper	Damaged	Replace
18.	Rear bumper	Damaged	Replace
19.	Rim rear - right	Scratch(es)	Paint
20.	Rim rear - left	Scratch(es)	Paint
21.	Front door - left	Sticker	Paint
22.		Damaged	Replace
23.		Damaged	Replace
24.	instrument cluster	Error message	Carry out a fault diagnosis
25.	maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. Rim front - left



1. Rim front - left



2. Front door - left



2. Front door - left



3. Front fender - left



3. Front fender - left



3. Front fender - left



3. Front fender - left



3. Front fender - left



4. Rear door - left



4. Rear door - left



5. Sidewall - Rear - Left



5. Sidewall - Rear - Left



5. Sidewall - Rear - Left



5. Sidewall - Rear - Left



5. Sidewall - Rear - Left



6. Sidewall - Rear - right



6. Sidewall - Rear - right



6. Sidewall - Rear - right



6. Sidewall - Rear - right



7. Door Rear - right



7. Door Rear - right



7. Door Rear - right



8. Front door - right



8. Front door - right



9. Front fender - right




9. Front fender - right




9. Front fender - right



10. hood



10. hood



10. hood



10. hood




11. roof




11. roof



11. roof



11. roof



11. roof



12.



12.



12.



13.



13.



13.



14. Roof frame - left



14. Roof frame - left



15. Roof frame - right




15. Roof frame - right




15. Roof frame - right




16. tailgate



16. tailgate



16. tailgate



16. tailgate



17. Front bumper



17. Front bumper



17. Front bumper



17. Front bumper



17. Front bumper



18. Rear bumper



18. Rear bumper



18. Rear bumper



18. Rear bumper



19. Rim rear - right



19. Rim rear - right



20. Rim rear - left



20. Rim rear - left



20. Rim rear - left



21. Front door - left



21. Front door - left



22.



22.




23.



23.



23.



24. instrument cluster