



status report

customer: Bank 11, Neuss
contract number: 1330806830
reference:

vehicle data

BMW Baureihe 4 Gran Coupe 420 d xDrive Advantage

Vehicle identification number	WBA4K51010BP30329	mileage read:	183418 km
First Registration / construction year:	01.10.2018 / 2018	Visit Date / place of birth:	14.08.2025 Heidenheim
Bodywork:	cars	Re - import:	no
Body type:	limousine	KBA no. :	0005//CBJ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1995 ccm / 140 kW (190 PS)	Engine:	four-wheel
paint:	MINERALWEISS METALLIC	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	substance
Service book available:	digital	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	176532 / 21.06.2024
Vehicle roadworthy:	no	Vehicle roadworthy:	yes
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	1	maintained:	176532 / 21.06.2024
		digital / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Goodyear	225/50/R17/98H 2 mm
1st axis - right / states .	Goodyear	225/50/R17/98H 2 mm
2nd axis - Left / states .	Goodyear	225/50/R17/98H 2 mm
2nd axis - right / states .	Goodyear	225/50/R17/98H 2 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Filing package • Airbag switched off • Anti- lock braking system (ABS) • front armrest • Exhaust system (2-pipe system) with chrome screens • AUX - IN port (AUX -IN) • heated exterior mirrors • board computer <i>Außentemperaturanzeige</i> • Brake Energy Regeneration • Roof car color • Rev counter • Dynamic brake light • Dynamic Traction Control (DTC) • Driving Assistance System Start Assist • Color monitor (6.5-inch) • Handsfree with USB interface • Windscreen with band filter above • Begrenzeranlage speed (Speed ??Limit Device) • Gear sport automatic - with Steptronic (8-step) • Tailgate automatically • Rearview mirror with auto dip • Body 4 doors • Head airbag system front • Light and rain sensor • Air outlet (Air Breather) black mat • model refinement • LED Fog Lights • Personalization System (personnel profiles) • RuÃpartikelfilter	• Advantage • Airbag Driver / passenger side • Drive xDrive (all-wheel) • Audio system BMW Professional (Radio / CD player with MP3 capability) • Automatic seat belts , front and rear • Power side mirrors . adjustable • Body color door mirrors • brake Assist • Check Control System • Anti-theft device for wheels (rim locks) • Durchladeeinrichtung (rear center armrest) • Dynamic Stability Control (DSC) • First aid kit / first aid kit • Driving Assistance System Driving Experience Control • Electric windows front + rear • Heated front window • Velour floor mats • Cruise control system with brake function • cup holders • Interior interior trim Satin Silver , matt • Isofix admissions for child seat in back seat • Rear curtain airbag system • Steering column (steering wheel) mechan. adjustable • LM rims • Rear center armrest • Engine 2.0 ltr. - 140 kW 16V Turbo Diesel • Non smoking package • Tire Pressure Monitoring System

• Low emissions Euro 6 emission standards • Windshield washer nozzles and heated exterior mirrors • Service-System ConnectedDrive Services • • Seat feature 5 - seater • Front seats mechanically adjustable • Start / Stop System (Function) • Body color bumpers • immobilizer • Central locking with remote control	• Rear seat backrest split / folding • Shift Indicator • Front Side Airbags • Service system Intelligent Emergency incl . TeleServices • Power steering Servotronic • Seat cover / upholstery fabric Move • Start-stop button • Socket (12V connection) in addition • warning triangle • Tinted heat insulating glass
---	--

special Features	
• Trailer hitch (ball head pivots) • CD drive • Exterior parts car color • Cruise control system , active with Stop & Go function <i>Geschwindigkeits-Regelanlage mit Bremsfunktion</i> • Automatic climate control with 2-zone automatic . Recirculated air control • Steering wheel (leather M -Technic) • Metallic paint • Run-flat tire system (run flat) • LED headlights with adaptive light distribution <i>Nebelscheinwerfer LED, Fahrassistentz-System: Fernlichtassistent</i> • Sun protection glazing • <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Bordsteinautomatik, rechts</i>	• Business Package <i>Außen-/Innenspiegel mit Abblendautomatik, Innenspiegel mit Abblendautomatik, Audio-Navigationssystem Business, Audiosystem BMW Professional (Radio/CD-Player MP3-fähig), Farbmonitor (6,5 Zoll), Sitzheizung vorn, Lendenwirbelstütze Sitz vorn links und rechts</i> • DAB tuner (digital radio reception) • Vehicle without model lettering • Instrument cluster (extended range) • Seat lumbar support , front left and right, electr. adjustable • Light package <i>Ambiente-Beleuchtung, Fußraumbeleuchtung vorn, Ausstiegsleuchten in Türverkleidung unten, Leseleuchten vorn, Leseleuchten hinten, Gepäckraumbeleuchtung</i> • Park Distance Control (PDC) front and rear • Rear View Camera • Infotainment system BMW Real Time Traffic Information (RTTI) • HiFi Speaker System Harman Kardon • Sports suspension (with adaptive damping system)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.

Hoist or lifting means not available .

Mileage plausible: **yes**
 yes

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **no detectable**

As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

found

At the unrepared vehicle accident damage were observed on visual examination on the body skin .

reference:

Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			not checked	Battery / accumulator:	
					Out of order
oil loss:			examined limited		
air conditioning:			not possible	lighting system:	
					not checked
coupling:			unavailable	exhaust System:	
					not possible
engine running:			not possible	shock absorber:	
					not checked
transmission:			not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was not tested.
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge.
oil loss:	The vehicle could be checked only limited to oil leaks . *Starten vom Fahrzeug nicht möglich.
air conditioning:	The air conditioning could not be checked during the inspection .
lighting system:	The lighting system has not been tested visiting time .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system could not be checked during the inspection .
engine running:	A field test of the engine could not be performed
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Rim front - left	Scratch(es)	Paint
2. Roof frame - left	Deformed (slightly)	Refurbish and paint
3. Windshield	Chipping from stones in field of view	Replace
4. Front door - left	Scrape	Refurbish and paint
5. Sidewall - Rear - Left	Deformed (slightly)	Refurbish and paint
6. Rim rear - left	Scratch(es)	Paint
7. Rear spoiler	Clear lacquer chipping off	Replace
8. Rear bumper	chipped paint	Paint
9. Front door - right		Smart repair
10. Front bumper	Accident damage	Replace
11. Front door - left		Smart repair
12. maintenance	Due	Replace
13. key	Missing	Replace
14. battery	Empty battery	Replace
15. motor	Not okay	Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. Rim front - left



2. Roof frame - left



2. Roof frame - left



3. Windshield



3. Windshield



4. Front door - left



4. Front door - left



5. Sidewall - Rear - Left



5. Sidewall - Rear - Left



6. Rim rear - left



7. Rear spoiler



7. Rear spoiler




7. Rear spoiler



8. Rear bumper



8. Rear bumper



9. Front door - right



9. Front door - right



10. Front bumper



10. Front bumper



10. Front bumper



10. Front bumper



10. Front bumper



10. Front bumper



10. Front bumper




10. Front bumper



10. Front bumper



11. Front door - left



11. Front door - left