

DEKRA Automotive Solutions

Vehicle details

VIN	WBA51AJ0X MCG56444	Brand	BMW	Maintenance date	08/07/2024
Licence Plate	ADD52Y	Model	Serie-5-Touring-G31-2017	Maintenance mileage	98 010 km
Registration date	16/03/2021	Year	2021	Exterior Color	Other
Odometer	127 336 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	8		

Inspection Details

Inspection date	11/09/2025	Inspection loc.	Eurotransport Kungsängen		
-----------------	------------	-----------------	--------------------------	--	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Leather	✓
GPS system	✓
Bluetooth	✓
Sliding roof	✓
Panoramic roof	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
4x4	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Load cover	✓
Towing hook	✓
Refill emergency kit	✗

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Key	✓
Remote key	✓

DEKRA Automotive Solutions

Tyres

Goodyear 245/40/19 Y Summer 7.0 mm		Goodyear 245/40/19 Y Summer 7.0 mm	
Goodyear 275/35/19 Y Summer 4.0 mm		Goodyear 275/35/19 Y Summer 4.0 mm	

Winter kit

Nokian 245/40/19 T Winter 7.0 mm		Nokian 245/40/19 T Winter 7.0 mm	
Nokian 275/35/19 T Winter 8.0 mm		Nokian 275/35/19 T Winter 8.0 mm	

Damages

1



Part	Refill emergency kit
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement

2



Part	Alloy wheel
Position	-
Damages	Missing
Severity	-
Repair mode	Lumpsum replacement
Winter rim missing	

3



Part	Engine cover
Position	-
Damages	Broken
Severity	-
Repair mode	Lumpsum replacement

4



Part	Fabric seat
Position	Front left
Damages	Worn out
Severity	-
Repair mode	For info

5



Part	Door sill
Position	Back left
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

6



Part	Bumper
Position	Back
Damages	Dented
Severity	-
Repair mode	Lumpsum repair

7



Part	Alloy wheel
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum replacement

8



Part	Exterior door mirror shell
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumsum Paintworks

9



Part	Registration plates
Position	Front
Damages	Dented
Severity	-
Repair mode	Lumpsum replacement

10



Part	Windscreen
Position	Front
Damages	Stone impact
Severity	-
Repair mode	Smart Repair

DEKRA Automotive Solutions

11



Part

Windscreen

Position

Front

Damages

Stone impact

Severity

-

Repair mode

Smart Repair

●

●

12



Part

Door sill

Position

Back right

Damages

Scratched

Severity

-

Repair mode

For info

●

●

13



Part

Door

Position

Back left

Damages

Scratched

Severity

-

Repair mode

For info

●

●