



Hüsges Gruppe®
Die Gutachter

status report

customer: Bank 11, Neuss
contract number: 944693130
reference:

vehicle data

BMW 330i

Vehicle identification number	WBA5R11080FH35290	mileage read:	96834 km
First Registration / construction year:	23.07.2019 /	Visit Date / place of birth:	25.09.2025 Riedstadt- Goddelau
Bodywork:	cars	Re - import:	unknown
Body type:	limousine	KBA no. :	0005//CTT
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1998 ccm / 190 kW (258 PS)	Engine:	rear-wheel drive
paint:	blue	Number of previous owners:	3
Doors / seats:	4 / 5	number keys:	3
Next HU / AU:	08.2026 / 08.2026	cushion type:	leather
Service book available:	digital	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	82736 / 28.08.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle	-	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
-	3	maintained:	82736 / 28.08.2024
		digital / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Bridgestone	225/40/R19/93Y 2 mm
1st axis - right / states .	Bridgestone	225/40/R19/93Y 2 mm
2nd axis - Left / states .	Bridgestone	255/35/R19/96Y 4 mm
2nd axis - right / states .	Bridgestone	255/35/R19/96Y 4 mm
traffic Safety:	roadworthy	
spare wheel:	RunFlatTire	
state spare wheel:	Vollwertig	

standard equipment	
• Ablage-Paket (4706) Aerodynamik-Paket M-Technic (2701) Airbag Beifahrerseite abschaltbar (26909) Airbag Fahrer-/Beifahrerseite (26803) Aktive Motorhaube (10715) Ambiente-Beleuchtung (37603) Anti-Blockier-System (ABS) (40000) Armauflage vorn (27108) Außenausstattung Shadow-Line Hochglanz (8702) Außenspiegel elektr. verstell- und heizbar (15200) Bordcomputer (25508) Bremsassistent (40801) Dachhimmel Anthrazit (BMW Individual) (27810) Diebstahlsicherung für Räder (Felgenschlösser) (51299) Durchladeeinrichtung (Mittelarmlehne hinten) (33901) Dynamische Bremsleuchte (18898) Dynamische Stabilitäts-Control (DSC) (70100) Dynamische Traction Control (DTC) (70105) Erste Hilfe-Kasten / Verbandkasten (39530) Fahrassistenten-System Active Guard (Bremsassistent) (40800) Fahrassistenten-System Active Guard Plus (Spurhalteassistent, Frontkollisionswarnung) (40954) Fahrassistenten-System Speed-Limit-Anzeige, Geschwindigkeits-Begrenzeranlage (Speed Limit Device) Fahrassistenten-System Aufmerksamkeits-Assistent (42926) Fahrassistenten-System Fahrerlebnisschalter (70518) Freisprecheinrichtung mit USB-Schnittstelle (24833) Frontscheibe Akustikglas (22515) Fußmatten Velours (28402) Geschwindigkeits-Regelanlage mit Bremsfunktion (26710) Getriebe Sport-Automatic - mit Steptronic (8-Stufen) (75916) Getränkehalter (38908) Heckleuchten LED (18802) Innenausstattung Interieurleisten Aluminium	• Parkbremse elektrisch (40803) Personalisierungssystem (Personal Profile) (39870) Reifendruck-Kontrollsystem (25903) Rücksitzlehne geteilt/klappbar (402040) (33512) Schadstoffarm nach Abgasnorm Euro 6d-TEMP (77273) Seitenairbag vorn (26903) Service-System ConnectedDrive Services (25150) Service-System Gesetzlicher Notruf (25149) Service-System Intelligenter Notruf inkl. TeleServices (25151) Servolenkung Servotronic (69811) Sport Boost Fahrmodusschalter (25869) Sport-Fahrwerk (M-Technic) (42004) Variable Sportlenkung Sportsitze vorn (31901) Start-Stop-Knopf (35513) Start/Stop-Anlage (Funktion) (77601) Warndreieck (38999) Wegfahrsperre (38105)

Tetragon (26263) Innenspiegel mit
Abblendautomatik (37901) Isofix-Aufnahmen für
Kindersitz an Rücksitz (39308) Karosserie 4-türig
(10004) Klimaautomatik 3-Zonen mit autom. Umluft-
Control (28983) Kopf-Airbag-System hinten (26805)
Kopf-Airbag-System vorn (26804) Kopfstützen
hinten klappbar (34909) Lenkrad (Sport/Leder) mit
Multifunktion (69306) Licht- und Regensensor
(18909) M Sport (97741) Mittellarmlehne hinten
(27300) Motor 2,0 Ltr. - 190 kW 16V (96574)
Nebelscheinwerfer LED (18313) Otto-Partikelfilter
(OPF) (77640) Park-Distance-Control (PDC) vorn
und hinten (25800)

special Features

- | | |
|--|---|
| <ul style="list-style-type: none"> • Außenausstattung Shadow-Line Hochglanz (erweiterter Umfang) • Bremsanlage M Sportbremsen (Bremssättel lackiert) • Entertainment-Paket • Heckklappenbetätigung automatisch • Innovations-Paket • LM-Felgen vorn/hinten 8x19 / 8,5x19 (Doppelspeiche 791 M, Jet Black) • Parkassistent-Paket Plus • Sitzbezug / Polsterung Leder Vernasca mit Kontraststeppung M • Sitzheizung vorn hinten • Winterfreude-Paket | <ul style="list-style-type: none"> • Bedienelemente galvanisiert • Business-Paket Professional • Fahrassistenz-System Driving Assistant Professional • Heckspoiler (M-Technic) • Instrumententafel lederbezogen • Metallic-Lackierung • Sicherheitsgurte M • Sitze vorn elektr. verstellbar (links mit Memory) • Sonnenschutzverglasung (hinten abgedunkelt) |
|--|---|

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	yes yes

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: Expertly repaired

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit

Alternator / Generator:	✓ examined limited	Battery / accumulator:	✓ in order
oil loss:	✓ examined limited		
air conditioning:	✓ examined limited	lighting system:	✓ examined limited
coupling:	✗ unavailable	exhaust System:	✓ examined limited
engine running:	✓ examined limited	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



	component	Damage	Rep kind
1.	Front door - left	Subsequently painted	acceptable
2.	Sitz Vorne Links	Wear and tear	acceptable
3.	Rim front - right	Scratch(es)	Paint
4.	Front bumper	Wear and tear	acceptable
5.	Front door - left	Scratch(es)	
6.	tailgate	Scratch(es)	Paint
7.	Rear bumper	Wear and tear	acceptable
8.	Sidewall - Rear - right	Wear and tear	acceptable
9.	Front fender - right	Wear and tear	acceptable
10.	hood	Wear and tear	acceptable
11.	Windshield	Chipping from stones	Smart repair
12.	maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



1. Front door - left



2. Sitz Vorne Links



2. Sitz Vorne Links



3. Rim front - right



3. Rim front - right



4. Front bumper



5. Front door - left



6. tailgate



6. tailgate



7. Rear bumper



8. Sidewall - Rear - right



9. Front fender - right



10. hood



10. hood



10. hood



11. Windshield



11. Windshield