



BMW 2-Reeks Active Tourer (UKL): 2ABS693

Vinnnummer:	WBA6T510807H91138	Versionname:	216d Active Tourer (F45) 1.5d 116pk/cv 5p
First Registrationdate:	11/02/2021	Fiscalpower:	
Expertise Mileage:	136424	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	wel remmen en olie		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/60/16/96 H			
Winter tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Semperit: 7 mm	Re.R.	Semperit: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/60 R 16 96 H
Tyre size FR				205/60 R 16 96 H
Tyre size RL				205/60 R 16 96 H
Tyre size RR				205/60 R 16 96 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2477
Tyre make FR				2477
Tyre make RL				2477
Tyre make RR				2477

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Gear shift lever knob, Worn, Acceptable



Dashboard, Scratch(es), Acceptable



Windscreen, Crack, Replace



Bumper moulding F, Missing, Replace




Bumper F, Broken, Replace and paint



Alloy rim FL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Roof pillar L, Dent(s), Paintless dent repair



Wing RL, Dent(s), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Paint measurement, Acceptable

