



BMW 1 HATCH: 1XRB667			
Vinnumber:	WBA7K310005R56698	Versionname:	118i (103 kW)
First Registrationdate:	12/03/2020	Fiscalpower:	
Expertise Mileage:	62167	Power Kw:	103
Bodytype:		Body colour	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1507
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	01/08/2025		
Maintenance	390.0		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options			
Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Sport seats			
Type of GPS storage	HD		

Limited Technical Inspection

Degree of wear

225/45/17/94 Y				
Summer tyres:	Fr.L.	Bridgestone: 5,2 mm	Fr.R.	Bridgestone: 5,5 mm
	Re.L.	Bridgestone: 6,5 mm	Re.R.	Bridgestone: 6,8 mm
Tyre profile depth FL				5.2
Tyre profile depth FR				5.5
Tyre profile depth RL				6.5
Tyre profile depth RR				6.8
Tyre size FL				225/45 R 17 94 Y
Tyre size FR				225/45 R 17 94 Y
Tyre size RL				225/45 R 17 94 Y
Tyre size RR				225/45 R 17 94 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment			
Number of charging cables (normal)	0	Runflat	No
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2956,96
Ignition key, Not functioning (well), Acceptable	0,00



Roof liner, Burned, Smart repair

113,74



Interior covering A pillar L, Burned, Replace

66,62



Floor covering FL, Worn, Acceptable

0,00



Bumper F, Scratch(es), Spot repair

144,58



Bonnet, Dent(s), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

199,04



Alloy rim RL polished, Scratch(es), Repair and paint (complete)

199,04



Door FL, Scratch(es), Acceptable

0,00



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

480,90



Sill trim L, Scratch(es), Repair and paint (complete)

423,79



Wing RL, Dent(s) and scratch(es), Acceptable

0,00



Tyre repair kit, Missing, Check

0,00



Boot lid covering R, Worn, Acceptable

0,00



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Bumper moulding R, Broken, Replace

183,96



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Door FR, Deformed / Strained, Replace and paint

0,00



Sill trim R, Scratch(es), Repair and paint (complete)

0,00



Outside rear-view mirror base R, Scratch(es), Repair and paint (complete)

0,00



Roof, Chemical polution, Repair and paint (complete)

657,18

