



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

BMW Baureihe 3 Touring 320 d M Sport Shadow

Vehicle identification number	WBA8H91080A899860	mileage read:	175771 km
First Registration / construction year:	20.05.2019 / 2019	Visit Date / place of birth:	23.09.2025 Heidenheim
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	0005//CDK
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1995 ccm / 140 kW (190 PS)	Engine:	rear-wheel drive
paint:	BLACK SAPPHIRE METALLIC	Number of previous owners:	4
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	digital	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	118585 / 13.07.2023
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	digital / -	118585 / 13.07.2023

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Semperit	205/55/R16/91H 3 mm
1st axis - right / states .	Semperit	205/55/R16/91H 3 mm
2nd axis - Left / states .	Semperit	205/55/R16/91H 3 mm
2nd axis - right / states .	Semperit	205/55/R16/91H 3 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Aerodynamics package M -Technic • Airbag Driver / passenger side • Audio system BMW Professional (Radio / CD player with MP3 capability) • AUX - IN port (AUX -IN) • Power side mirrors . adjustable and heated • Outside temperature display • brake Assist • Headlining anthracite (BMW Individual) • Dynamic brake light • Dynamic Traction Control (DTC) • Color monitor (6.5-inch) • Handsfree Bluetooth with USB audio interface • Luggage compartment partition (net) • Begrenzeranlage speed (Speed ??Limit Device) • Gear sport automatic - with Steptronic (8-step) • Tailgate automatically • Interior interior trim Satin Silver , matt • Body 5-door • Rear curtain airbag system • Rear headrests folding • Steering column (steering wheel) mechan. adjustable • Light package • M Sport Shadow • Front center armrest adjustable • Engine 2.0 ltr. - 140 kW 16V Turbo Diesel • NOx storage catalyst (BMW Blue Performance) • Tire Pressure Monitoring System • Low emissions Euro 6 emission standards • Front Side Airbags	• Airbag switched off • Anti- lock braking system (ABS) • Exhaust system (2-pipe system) with chrome screens • Outside amenities Shadow -Line High gloss • Body color door mirrors • board computer • Check Control System • Durchladeeinrichtung (rear center armrest) • Dynamic Stability Control (DSC) • Driving Assistance System Driving Experience Control • Remote unlock tailgate • Velour floor mats • Luggage compartment cover / shade • Cruise control system with brake function • cup holders • LED Taillights • Isofix admissions for child seat • Automatic climate control with 2-zone automatic . Recirculated air control • Head airbag system front • Steering wheel (leather M -Technic) • Light and rain sensor • LM rims • Rear center armrest • model refinement • Multifunction for steering wheel • Personalization System (personnel profiles) • RuÃpartikelfilter • Rear side airbag

• Power steering Servotronic • Sport chassis (M -Technic) • Start-stop button • Socket (12V connection) in addition • immobilizer • Central locking with remote control	• Service system Intelligent Emergency incl . TeleServices • Heated front seats • Front sports seats • Start / Stop System (Function) • LED daytime running lights • Tinted heat insulating glass
---	--

special Features	
• Filing package • DAB tuner (digital radio reception) • Instrument cluster (extended range) • LED Fog Lights • Run-flat tire system (run flat) • Service system ConnectedDrive • Seat cover / leather upholstery Dakota • <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Bordsteinautomatik, rechts</i>	• Business Package <i>Außen-/Innenspiegel mit Abblendautomatik, Dachreling schwarz, Audio-Navigationssystem Business, Sitzheizung vorn, Lendenwirbelstütze Sitz vorn links und rechts, elektr. verstellbar</i> • HiFi speaker system • Metallic paint • Park Distance Control (PDC) front and rear • Headlight LED <i>Blinkleuchten LED</i> • Infotainment system BMW Remote Services • Sun protection glazing

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .

**Layers of paint thickness
measurement:**

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

-
-

reference:

Overview conducted technology audit

Alternator / Generator:	✓ in order	Battery / accumulator:	✓ in order
oil loss:	✓ examined limited		
air conditioning:	✓ in order	lighting system:	✓ in order
coupling:	✓ examined limited	exhaust System:	✓ examined limited
engine running:	✓ in order	shock absorber:	✓ examined limited
transmission:	✓ examined limited		

Performed testing technology

Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. hood	Chipping from stones	Paint
2.	Damaged	Replace
3. Front bumper	Damaged	Refurbish and paint
4.	Damaged	Replace
5. Reifen Winter	Due	Replace
6. Rear bumper	Clearance not exact	Uninstall/install
7. Rear bumper	Damaged	Refurbish and paint
8.	Damaged	Replace
9.	Damaged	Replace
10.	Wear and tear	acceptable
11. maintenance	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims



rims



engine compartment



service book



Others



Navigation system



1. hood



1. hood



1. hood



1. hood



2.



2.



3. Front bumper



3. Front bumper



3. Front bumper



3. Front bumper



4.



4.



6. Rear bumper



6. Rear bumper



6. Rear bumper




7. Rear bumper



7. Rear bumper



7. Rear bumper



8.



8.



8.



9.



9.



10.



10.



10.