



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

BMW Baureihe 3 Cabrio 320d

Vehicle identification number	WBADY31010E828357	mileage read:	262248 km
First Registration / construction year:	16.04.2013 / 2012	Visit Date / place of birth:	19.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	Convertible	KBA no. :	0005//AUJ
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1995 ccm / 135 kW (184 PS)	Engine:	rear-wheel drive
paint:	BLACK SAPPHIRE METALLIC	Number of previous owners:	Unbekannt
Doors / seats:	2 / 4	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	beige
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	-	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
-	2	maintained:	- / -
		no / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Anderer	225/45/R17/94V 1 mm
1st axis - right / states .	Anderer	225/45/R17/94V 1 mm
2nd axis - Left / states .	Anderer	225/45/R17/94V 2 mm
2nd axis - right / states .	Anderer	225/45/R17/94V 0 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag Driver / passenger side • Anti- lock braking system (ABS) • heated exterior mirrors • Body color door mirrors • White direction indicator lights • Brake Energy Regeneration • Chrome Line Exterior • Rev counter • Easy-entry function • Windscreen with band filter above • Hardtop (electr. Retractable) • The interior lighting package • Body 2-door • Steering wheel (sports / leather) with multifunction <i>Multifunktion für Lenkrad</i> • LM rims • Engine 2.0 ltr. - 135 kW turbodiesel KAT • Tire Pressure Monitoring System • Run-flat tire system (run flat) • Folding rear seat back • Heated windshield washer nozzles • Electric front seats . adjustable (left with memory) • Start-stop button • Daytime running lights • Xenon headlights <i>Scheinwerfer-Reinigungsanlage (SRA)</i>	• Active head restraints • Power side mirrors . adjustable • Exterior mirrors with automatic curb , right • Outside temperature display • board computer • Check Control System • Headlining anthracite • Dynamic Stability Control (DSC) • Power windows • Automatic transmission - with Steptronic (6 stages) • Interior interior trim Satin Silver • Isofix admissions for child seat in back seat • Rear headrests • Steering column (steering wheel) mechan. adjustable • model refinement • Fog Lights • Tyre Defect Indicator • RuÄÿpartikelfilter • Shift Indicator • Front Side Airbags <i>Kopf-Airbag-System vorn</i> • Soft Close Automatic for trunk / tailgate • Body color bumpers • Heat -insulating glass (windshield with band filter above)

special Features	
• External / internal mirror with auto dip <i>Außenspiegel elektr. anklappbar, alle Spiegel mit</i>	• Comfort Package <i>Licht-Paket, Ablage-Paket, Automatische Fahrlichtschaltung,</i>



Abblendautomatik, Außenspiegel mit Bordsteinautomatik, rechts, Außenspiegel mit Memoryfunktion und Bordsteinautomatik, Innenspiegel mit Abblendautomatik

- By charging device integrated with transport bag
- HiFi speaker system
- Metallic paint
- Park Distance Control (PDC) front and rear
- Controlled power steering electronically
- Heated front seats
- Wind protection

Licht- und Regensensor, Scheibenwischer mit Regensensor, Audiosystem BMW Professional (Radio/CD-Player), Park-Distance-Control (PDC), Mittelarmlehne vorn verstellbar, Klimaautomatik erweiterter Umfang, Innenspiegel mit Abblendautomatik

- Cruise control system (cruise control)
- Innovations Package
Xenon-Scheinwerfer, Scheinwerfer-Reinigungsanlage (SRA), LED-Lichtelemente, Fahrassistent-System: Fernlichtassistent, Adaptives Kurvenlicht, Komfortzugang (Öffnungs- und Schließsystem)
- Navigation package Professional
Audio-Navigationssystem Professional mit integrierter Handyvorrüstung, Audiosystem BMW Professional (Radio/CD-Player), Sprachbediensystem, Vorrüstung Mobiltelefon/Handy Business mit Bluetooth Schnittstelle
- Smokers Package
- Seat cover / leather upholstery Dakota
- USB interface

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:

not possible

A visit to the underside of your vehicle could not be performed.
Hoist or lifting means not available .

Mileage plausible:

not testable

not testable
Wartungsnachweise fehlen

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: Expertly repaired

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness

measurement:

Existing collision damage:

reference:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **It rattles were found.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. Motor Klappert beim Gasgeben	Damaged	Carry out a fault diagnosis
3. Innenraum, Sitze, Gurte, etc.	Dirty	
4. Front door trim - left	Damaged	Smart repair
5. Sitz Vorne Links	Damaged	Smart repair
6. steering wheel	Damaged	Smart repair
7. Mittelarmlehne	Damaged	Smart repair
8. Getränkehalter Armaturenbrett	Damaged	Replace
9. Innenverkleidung Hinten Links und Rechts	Damaged	Smart repair
10. proof of maintenance	Missing	Replace
11. maintenance	Due	Replace
12. Rim front - left	Scratch(es)	Smart repair
13. Rim rear - left	Scratch(es)	Smart repair
14. Rim rear - right	Scratch(es)	Smart repair
15. Rim front - right	Scratch(es)	Smart repair
16. 4x Reifen	Worn	Replace
17. Scheinwerferreinigungsanlage Links	Damaged	Replace
18. Front bumper	Scrape	Paint
19. hood	Wear and tear	acceptable
20. Front door - left	Damaged	Refurbish and paint
21. 2x Rückleuchte Heckklappe	Damaged	Replace
22. tailgate	Scratch(es)	Paint
23. Rear bumper	Damaged	Refurbish and paint
24.	Dirty	
25. roof	Wear and tear	acceptable
26. side skirt - right	Scrape	Paint
27. Front door - right	Scratch(es)	Paint
28. Sidewall - Rear - right	Scratch(es)	
29.	Breakage	Replace
30. Motorabdeckung	Missing	Replace
31.	Damaged	Replace
32. Sitzreihe Hinten Mitte Klappe	Damaged	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. hood



3. Innenraum, Sitze, Gurte, etc.



3. Innenraum, Sitze, Gurte, etc.



3. Innenraum, Sitze, Gurte, etc.



3. Innenraum, Sitze, Gurte, etc.



3. Innenraum, Sitze, Gurte, etc.




3. Innenraum, Sitze, Gurte, etc.



4. Front door trim - left



5. Sitz Vorne Links



5. Sitz Vorne Links



6. steering wheel



7. Mittelarmlehne



8. Getränkehalter Armaturenbrett



9. Innenverkleidung Hinten Links und Rechts



9. Innenverkleidung Hinten Links und Rechts



9. Innenverkleidung Hinten Links und Rechts



11. maintenance



12. Rim front - left



12. Rim front - left



13. Rim rear - left



13. Rim rear - left



14. Rim rear - right



14. Rim rear - right



15. Rim front - right



15. Rim front - right



16. 4x Reifen



16. 4x Reifen



16. 4x Reifen



16. 4x Reifen




17. Scheinwerferreinigungsanlage Links



18. Front bumper



18. Front bumper



19. hood



20. Front door - left



20. Front door - left



20. Front door - left




21. 2x Rückleuchte Heckklappe



21. 2x Rückleuchte Heckklappe



21. 2x Rückleuchte Heckklappe




22. tailgate



22. tailgate



23. Rear bumper



23. Rear bumper



23. Rear bumper



24.



25. roof



25. roof



26. side skirt - right



26. side skirt - right



27. Front door - right



27. Front door - right



28. Sidewall - Rear - right



29.



29.



30. Motorabdeckung



31.



32. Sitzreihe Hinten Mitte Klappe