



status report

customer: Bank 11, Neuss
contract number: 69656031
reference:

vehicle data

BMW Baureihe 5 Lim. 520 i Sport Line

Vehicle identification number	WBAJK51020BX22422	mileage read:	111191 km
..			
First Registration / construction year:	27.03.2019 / 2018	Visit Date / place of birth:	18.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	yes
Body type:	limousine	KBA no. :	0005//CPG
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1998 ccm / 135 kW (184 PS)	Engine:	rear-wheel drive
paint:	MEDITERRANBLAU METALLIC	Number of previous owners:	Unbekannt
Doors / seats:	4 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	digital	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	6 / 01.04.2019
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	-	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	digital / -	6 / 01.04.2019
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Michelin	245/45/R18/100Y 3 mm
1st axis - right / states .	Michelin	245/45/R18/100Y 3 mm
2nd axis - Left / states .	Michelin	245/45/R18/100Y 3 mm
2nd axis - right / states .	Michelin	245/45/R18/100Y 3 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light LED • Airbag Driver / passenger side • Ambient lighting • front armrest • Exhaust system (2-pipe system , left / right) with chrome screens • Power side mirrors . adjustable and heated • board computer • Brake Energy Regeneration • Durchladeeinrichtung (rear center armrest) • Dynamic Stability Control (DSC) • First aid kit / first aid kit • Driver Assistance System Attention Assistant • Driver assistance system Personal warning with braking function • Fund -oriented center console • Velour floor mats • Cruise control system with brake function • Cupholders front and rear • Interior interior trim black , high-gloss • Isofix admissions for child seat • Automatic climate control with 2-zone automatic . Recirculated air control • Rear curtain airbag system • Steering column (steering wheel) mechan. adjustable • Rear center armrest • Multifunction for steering wheel • Rear fog light (s) • • Parking brake electrically	• Airbag switched off • alarm system • Anti- lock braking system (ABS) • Audio Navigation System Business • Outside amenities Shadow -Line High gloss • LED indicator lights • brake Assist • Anti-theft device for wheels (rim locks) • Dynamic brake light • Dynamic Traction Control (DTC) • Driving Assistance System Collision Warning with braking function • Driving Assistance System Driving Experience Control • Electric windows front + rear • Handsfree Bluetooth with USB audio interface • Begrenzeranlage speed (Speed ??Limit Device) • Automatic transmission - with shift paddles (8-step) • LED Taillights • Rearview mirror with auto dip • Body 4 doors • Knee airbag driver side • Head airbag system front • Headlamp range control (automatic) • Engine 2.0 ltr. - 135 kW • LED Fog Lights • Non smoking package • Park Distance Control (PDC) front and rear • Personalization System (personnel profiles) •

• Tire Pressure Monitoring System • Heated windshield washer nozzles • LED headlights • Service-System ConnectedDrive Services • • Seat feature 5 - seater • Front seats teilelekt. . adjustable • Sportline • Start-stop button • LED daytime running lights • immobilizer • Central locking with remote control	• Windscreen wipers with rain sensor <i>Licht- und Regensensor</i> • Front Side Airbags • Service system Intelligent Emergency incl . TeleServices • Power steering Servotronic • Seat cover / upholstery fabric / leather combination Plectoid, anthracite • Heated front seats • Front sports seats • Start / Stop System (Function) • warning triangle • Combined heat / sun protection glazing
--	---

special Features	
• Power side mirrors . folding , mirror with auto dip all <i>Außenspiegel mit Bordsteinautomatik, rechts</i> • Vehicle without model lettering • LM-rims 8x18 (V-spoke 684) • Metallic paint • Rear View Camera	• Driving Assistance System High-Beam Assistant • • Steering wheel (leather M -Technic) • Run-flat tire system (run flat) • Sun protection glazing

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable Wartung Fällig, Wartungsnachweise nicht gepflegt
reference:	
Note Road Safe:	Windschutzscheibe Bruch, Bremsen Verschlissen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

found

At the unrepaired vehicle accident damage were observed on visual examination on the body skin .

reference:

Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			Out of order	lighting system:	
			Out of order		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning was not okay for visiting time . *Keine Kühlwirkung
lighting system:	For sightseeing timing defects in the lighting system were noted . *Unfallschaden Vorne Rechts Schadensenerweiterung möglich.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Sitz Vorne Links Kissen	Damaged	Replace
2. steering wheel	Damaged	Smart repair
3. Key with remote control	Damaged	Replace
4. headlining	Damaged	Smart repair
5.	Damaged	Smart repair
6. Mittelkonsole Zierleiste	Damaged	Replace
7. Reifendruckkontrollleuchte	Error message	Carry out a fault diagnosis
8. maintenance	Due	Replace
9. Bremsen Vorne	Worn	Replace
10. Klimaanlage keine Kühlwirkung	Damaged	Carry out a fault diagnosis
11. Rim rear - left	Damaged	Replace
12. Rim rear - right	Damaged	Replace
13. Rim front - right	Damaged	Replace
14. Unfallschaden Vorne Rechts Schadenserweiterung möglich	Accident damage	Replace
15. Windshield	Breakage	Replace
16. Außenspiegel - Links mit Blinker	Damaged	Replace
17. side skirt - left	Scrape	Paint
18. Front door - left	Delle	Refurbish and paint
19. Rear door - left	Damaged	Paint
20.	Damaged	Replace
21. Türeinstieg Hinten - Links	Deformed	Refurbish and paint
22. Sidewall - Rear - Left	Deformed	Refurbish and paint
23. Rear bumper	Scratch(es)	Paint
24. Sidewall - Rear - right	Deformed	Refurbish and paint
25. Taillight right	Wear and tear	acceptable
26. side skirt - right	Scrape	Paint
27. Door trim Rear - right	Damaged	Smart repair
28. Front door - right	Scratch(es)	Smart repair
29.	Scratch(es)	Paint
30. Sitz Vorne Rechts	Damaged	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Sitz Vorne Links Kissen



1. Sitz Vorne Links Kissen



2. steering wheel



3. Key with remote control



4. headlining



4. headlining




5.



6. Mittelkonsole Zierleiste



7. Reifendruckkontrollleuchte



9. Bremsen Vorne



11. Rim rear - left



12. Rim rear - right



13. Rim front - right



14. Unfallschaden Vorne Rechts Schadenserweiterung möglich



14. Unfallschaden Vorne Rechts Schadenserweiterung möglich



14. Unfallschaden Vorne Rechts Schadenserweiterung möglich



14. Unfallschaden Vorne Rechts Schadenserweiterung möglich



14. Unfallschaden Vorne Rechts Schadenserweiterung



14. Unfallschaden Vorne Rechts Schadenserweiterung

möglich



15. Windshield

möglich



15. Windshield



16. Außenspiegel - Links mit Blinker



16. Außenspiegel - Links mit Blinker



17. side skirt - left



17. side skirt - left



18. Front door - left



18. Front door - left



19. Rear door - left



19. Rear door - left



19. Rear door - left



20.



21. Türeinstieg Hinten - Links



21. Türeinstieg Hinten - Links



22. Sidewall - Rear - Left



22. Sidewall - Rear - Left



22. Sidewall - Rear - Left



22. Sidewall - Rear - Left



23. Rear bumper



23. Rear bumper



23. Rear bumper



23. Rear bumper



24. Sidewall - Rear - right



24. Sidewall - Rear - right



24. Sidewall - Rear - right



25. Taillight right



26. side skirt - right



26. side skirt - right



27. Door trim Rear - right




28. Front door - right



28. Front door - right



29.



30. Sitz Vorne Rechts



30. Sitz Vorne Rechts