

status report

customer: Bank 11, Neuss
contract number: 796354830
reference:

vehicle data

BMW Baureihe 5 Touring 520 d M Sport

Vehicle identification number	WBAJM71020G961512	mileage read:	182599 km
First Registration / construction year:	24.07.2018 / 2018	Visit Date / place of birth:	01.09.2025 Dorfmark
Bodywork:	cars	Re - import:	unknown
Body type:	hatchback	KBA no. :	0005//COR
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1995 ccm / 140 kW (190 PS)	Engine:	rear-wheel drive
paint:	white	Number of previous owners:	-
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	03.2026 / 03.2026	cushion type:	Cloth / Alcantara
Service book available:	digital	Interior Color:	Multicolor
smoking vehicle:	no	Last service km / on the:	87698 / 03.06.2022
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
-	2	maintained:	87698 / 03.06.2022
		digital / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Hankook	245/45/R18/100V 5 mm
1st axis - right / states .	Hankook	245/45/R18/100V 5 mm
2nd axis - Left / states .	Hankook	275/40/R18/103V 4 mm
2nd axis - right / states .	Hankook	275/40/R18/103V 4 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light LED • Airbag switched off • active Bonnet • Ambient lighting • front armrest • Exhaust system trapezoidal, left / right • Power side mirrors . adjustable and heated • board computer • Brake Energy Regeneration • Headlining anthracite (BMW Individual) • Durchladeeinrichtung (rear center armrest) • Dynamic Stability Control (DSC) • First aid kit / first aid kit • Driver Assistance System Attention Assistant • Driver assistance system Personal warning with braking function • Fund -oriented center console • Velour floor mats • Luggage compartment cover / shade • Cruise control system with brake function • cup holders • Tailgate automatically • Rearview mirror with auto dip • Isofix admissions for child seat in back seat • Knee airbag driver side • Head airbag system front • Steering column (steering wheel) mechan. adjustable • LM rims • Air suspension rear axle • Rear center armrest	• Aerodynamics package M -Technic • Airbag Driver / passenger side • alarm system • Anti- lock braking system (ABS) • Exhaust system (2-pipe system , left / right) with chrome screens • Outside amenities Shadow -Line High gloss • LED indicator lights • brake Assist • Chrome Line Exterior • Anti-theft device for wheels (rim locks) • Dynamic brake light • Dynamic Traction Control (DTC) • Driving Assistance System Collision Warning with braking function • Driving Assistance System Driving Experience Control • Electric windows front + rear • Handsfree Bluetooth with USB audio interface • Luggage compartment partition (net) • Begrenzeranlage speed (Speed ??Limit Device) • Automatic transmission - with shift paddles (8-step) • Cupholders front and rear • LED Taillights • Instrument cluster (extended range) • Body 5-door • Rear curtain airbag system • Steering wheel (leather M -Technic) • Headlamp range control (automatic) • Air outlet (Air Breather) high-gloss black

• LED Fog Lights • Non smoking package • Parking brake electrically • Tire Pressure Monitoring System • Rear seatback split / folding (402040) • Shift Indicator • Windscreen wipers with rain sensor <i>Licht- und Regensensor</i> • Front Side Airbags • Service system Intelligent Emergency incl . TeleServices • Power steering Servotronic • Seat cover / upholstery fabric Rhombicle / Alcantara • Heated front seats • Start-stop button • warning triangle • Combined heat / sun protection glazing	• M Sport • Engine 2.0 ltr. - 140 kW 16V Turbo Diesel • Rear fog light (s) • NOx storage catalyst (BMW Blue Performance) • Personalization System (personnel profiles) • RuÄÿpartikelfilter • Low emissions Euro 6 emission standards • Heated windshield washer nozzles • LED headlights • Service-System ConnectedDrive Services • • Seat feature 5 - seater • Front seats teilelekt. . adjustable • Sport chassis (M -Technic) • Start / Stop System (Function) • immobilizer • Central locking with remote control
--	--

special Features	
• Business Package <i>Außenspiegel elektr. anklappbar, alle Spiegel mit Abblendautomatik, Dachreling schwarz, Park-Distance-Control (PDC) vorn und hinten, Klimaautomatik 2-Zonen mit autom. Umluft-Control, erweiterter Umfang, Sitzheizung vorn, Durchladeeinrichtung (Mittelarmlehne hinten)</i> • Head-up display • Instrument display , multifunctional • Navigation package ConnectedDrive <i>Sprachbediensystem, Audio-Navigationssystem Professional, Service-System: Remote Services, Service-System: Concierge Services, Service-System: Real Time Traffic Information (RTTI), Alarmanlage, Induktionsladeschale für Smartphone (Wireless Charging)</i> • Service System Apple CarPlay Information (Preparation) • Sun protection glazing • Integrated universal remote control	• Vehicle without model lettering • • Comfort Access (close / start system) • Parkassistent-Paket More <i>Parkassistent-Paket, Fahrassistentz-System: Park-Assistent, Rückfahrkamera, Surround-Kamerasystem (Surround View)</i> • Electric front seats . adjustable (left with memory) • Uni paint

We remind you that the data provided were taken from the DAT database.\\n\\nNo liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible

A visit to the underside of your vehicle could not be performed.
 Hoist or lifting means not available .

Mileage plausible: **not testable**
 not testable

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: **Expertly repaired**

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Out of tolerance

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Dachrahmen links Nachlackiert

damage



component	Damage	Rep kind
1. Roof frame - left	Subsequently painted	acceptable
2. maintenance	Due	Replace
3. proof of maintenance	Missing	Replace
4. Felge (Aluminium) hinten links	Scratch(es)	Paint
5. Felge (Aluminium) vorne links	Scratch(es)	Paint
6. Front bumper	chipped paint	Smart repair
7. Felge (Aluminium) hinten rechts	Scratch(es)	Paint
8. exterior body	Surface scratch(es)	
9.	Wear and tear	acceptable
10.	Dirty	
11. Rear door trim - left	Damaged	Replace
12. Türeinstieg Hinten - Links	Damaged	Smart repair
13. Türeinstieg Hinten - Rechts	Scrape	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



1. Roof frame - left



4. Felge (Aluminium) hinten links




4. Felge (Aluminium) hinten links



5. Felge (Aluminium) vorne links



5. Felge (Aluminium) vorne links



6. Front bumper



6. Front bumper



7. Felge (Aluminium) hinten rechts



7. Felge (Aluminium) hinten rechts



8. exterior body



9.



9.



10.



10.



11. Rear door trim - left



11. Rear door trim - left




12. Türeinstieg Hinten - Links



12. Türeinstieg Hinten - Links



13. Türeinstieg Hinten - Rechts



13. Türeinstieg Hinten - Rechts