



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

BMW Baureihe 7 740d xDrive

Vehicle identification number	WBAKC01030DR96530	mileage read:	204820 km
..			
First Registration / construction year:	30.08.2011 / 2011	Visit Date / place of birth:	30.09.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	limousine	KBA no. :	0005//AZC
Fuel / emission class:	diesel / € 5	transmission type:	automatic
Displacement / power:	2993 ccm / 225 kW (306 PS)	Engine:	four-wheel
paint:	MINERALWEISS METALLIC	Number of previous owners:	5
Doors / seats:	4 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	beige
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	Eg II (veh - letter)	state outside:	3 - Average
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / 6	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Goodride	245/45/R19/102W 6 mm
1st axis - right / states .	Goodride	245/45/R19/102W 6 mm
2nd axis - Left / states .	Maxxis	275/40/R19/105W 6 mm
2nd axis - right / states .	Maxxis	275/40/R19/105W 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag Driver / passenger side • Anti- lock braking system (ABS) • Automatic headlight activation • Power side mirrors . heating and folding • Outside temperature display • White direction indicator lights • brake Assist • Dynamic Damper Control (Dynamic Damping Control) • Dynamic Traction Control (DTC) • Control for central locking • Automatic transmission - with Steptronic (8-step) • The interior lighting package • Body 4 doors • Head airbag system front • LM rims • Engine 3.0 ltr. - 225 kW turbodiesel KAT • Wheelbase 3070 mm • Run-flat tire system (run flat) • Low emissions Euro 5 emissions standard • Windscreen wipers with rain sensor • Front Side Airbags • Electric front seats . adjustable (with memory) • Sun protection glazing • Daytime running lights • Tinted heat insulating glass	• Active head restraints • Drive xDrive (all-wheel) • External / internal mirror with auto dip • Body color door mirrors • Bi -xenon headlights • board computer • <i>Check-Control-System</i> • Rev counter • Dynamic Stability Control (DSC) • Electric windows front + rear • Velour floor mats • Cupholders front and rear • Isofix admissions for child seat • Rear curtain airbag system • Steering column (steering wheel) electr. adjustable • Rear center armrest • Fog Lights • Tyre Defect Indicator • RuÃpartikelfilter • Heated windshield washer nozzles • Headlamp cleaning system SRA (high pressure) • Power steering Servotronic • Heated front seats • Body color bumpers • immobilizer • Central locking with theft and crash sensor

special Features	
• Alarm system with remote control • Audio navigation system Professional with integrated Handyvorrüstung	• Ambient lighting • Equipment package ambience and sound <i>HiFi-Lautsprechersystem Professional, Instrumententafel</i>



Vorrüstung Mobiltelefon/Handy Business mit Bluetooth Schnittstelle, Audio-Navigationssystem Professional • Speed Limit Display • Tailgate automatically • Innovations Package Fahrassistenz-System: Spurwechselassistent, Fahrassistenz-System: Fernlichtassistent, Adaptives Kurvenlicht, Head-up-Display, Geschwindigkeits-Regelanlage, Aktiv, Fahrassistenz-System: Spurwechsel-Warnsystem • Steering wheel (sports / leather) with multifunction • MP3 interface for mobile phone / cell phone • Multimedia Apple iPhone applications (apps) • Smokers Package • Sliding / tilt sunroof electric (glass) • Soft - Close function for doors and trunk / tailgate • Voice control system • USB interface	lederbezogen, Innenausstattung: Keramik-Applikationen für Bedienelemente, Klimaautomatik 4-Zonen mit autom. Umluft-Control, Sitzbezug / Polsterung: Exklusiv-Leder Nappa (erweiterter Umfang), Komfortsitze vorn elektr. verstellbar (mit Memory), Lendenwirbelstütze Sitz vorn links und rechts, elektr. verstellbar, Aktive Sitzbelüftung vorn • Dynamic Handling System (Dynamic Drive) • Interior Features hardwood Fineline Nature • Comfort Access (close / start system) • heated steering wheel • Metallic paint • Park Distance Control (PDC) front and rear • Rear View Camera • Heated rear • Rear window sun screen + side windows electr. • Auxiliary heating
---	--

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Fehlermeldung Bremsanlage

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness	Out of tolerance

measurement:	At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Spurplatten verbaut Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Front fender - left	Subsequently painted	acceptable
2. Front fender - right	Subsequently painted	acceptable
3. proof of maintenance	Missing	Replace
4. brake system	Error message	Carry out a fault diagnosis
5.	Damaged	Replace
6. maintenance	Missing	Replace
7.	Wear and tear	acceptable
8. elektr. Heckklappe	Not open	Carry out a fault diagnosis
9.	Scratch(es)	Paint
10. Zierleisten	Damaged	Replace
11.	Scratch(es)	Paint
12.	Clear lacquer chipping off	Paint
13. Front bumper	Damaged	Paint
14.	Scratch(es)	Paint
15. Front door - left	Wear and tear	acceptable
16. Steering wheel (leather)	Wear and tear	acceptable
17. side skirt - right	Scratch(es)	Paint

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Front fender - left



2. Front fender - right



4. brake system



5.



5.



7.



7.



8. elektr. Heckklappe



9.



10. Zierleisten



10. Zierleisten



11.



12.



13. Front bumper



14.



15. Front door - left



16. Steering wheel (leather)



17. side skirt - right