



status report

customer: Bank 11, Neuss
contract number: 1068154031
reference:

vehicle data

BMW Baureihe X6 xDrive 40 d

Vehicle identification number	WBAKV410200P70830	mileage read:	182717 km
First Registration / construction year:	24.04.2015 / 2015	Visit Date / place of birth:	07.10.2025 Heidenheim
Bodywork:	SUV	Re - import:	unknown
Body type:	limousine	KBA no. :	0005//BYF
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2993 ccm / 230 kW (313 PS)	Engine:	four-wheel
paint:	BLACK SAPPHIRE METALLIC	Number of previous owners:	4
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	digital	Interior Color:	black
smoking vehicle:	no	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	in the parking garage	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	digital / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Pirelli	285/35/R21/105V 5 mm
1st axis - right / states .	Pirelli	285/35/R21/105V 5 mm
2nd axis - Left / states .	Pirelli	325/30/R21/108V 5 mm
2nd axis - right / states .	Pirelli	325/30/R21/108V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag switched off • Anti- lock braking system (ABS) • Drive xDrive (all-wheel) • Audio system BMW Professional (Radio / CD player with MP3 capability) • AUX - IN port (AUX -IN) • Body color door mirrors • board computer • Chrome Line Exterior • Dynamic Stability Control (DSC) <i>Fahrassistenten-System: Anfahr-Assistent</i> • Exterior parts car color • Driving Assistance System Driving Assistant <i>Fahrassistenten-System: Spurwechselassistent, Fahrassistenten-System: Auffahrwarnsystem</i> • Power windows Rear • Handsfree with USB interface • Cruise control system with brake function • Cupholders front and rear • LED Taillights • Instrument cluster (extended range) • Isofix admissions for child seat in back seat • Automatic climate control with 2-zone automatic . Recirculated air control , extended scope • Head airbag system front • Light and rain sensor • Air outlet (Air Breather) Chrome • Engine 3.0 ltr. - 230 kW turbodiesel • LED Fog Lights • NOx storage catalyst (BMW Blue Performance) • Wheelbase 2933 mm	• Airbag Driver / passenger side • Drive all-wheel drive permanent • front armrest • Exhaust system (left / right) with chrome screens • Power side mirrors . adjustable <i>Außenspiegel heizbar, Blinkleuchte in Außenspiegel integriert</i> • Outside temperature display • brake Assist • Dynamic brake light • Dynamic Traction Control (DTC) • Driving Assistance System Hill Descent Control (HDC) • Driving Assistance System Driving Experience Control • Electric windows front • Velour floor mats • Gear sport automatic - with Steptronic (8-step) • Tailgate automatically • Rearview mirror with auto dip • Instrument panel leather look • Body 5-door • Rear curtain airbag system • Steering column (steering wheel) mechan. adjustable • Light package <i>Ambiente-Beleuchtung, Fußraumbeleuchtung vorn, Fußraumbeleuchtung hinten, Ausstiegsleuchten in Türverkleidung unten, Leseleuchten vorn, Leseleuchten hinten</i> • Rear center armrest • Multifunction for steering wheel • Rear fog light (s)

- RuÅÿpartikelfilter
- Low emissions Euro 6 emission standards
- Headlight cleaning system (SRA)
- Front Side Airbags
- Power steering Servotronic
- Seat cover / leather upholstery Dakota
- Heated front seats
- Start / Stop System (Function)
- Heat -insulating glass (windshield with band filter above)

- Parking brake electrically
- Tire Pressure Monitoring System
- Rear seatback split / folding (402040)
- Heated windshield washer nozzles
- SCR (AdBlue technology)
- Service system Intelligent Emergency incl . TeleServices
- Seat feature 5 - seater
- Electric front seats . adjustable (left with memory)
- Start-stop button
- immobilizer
- Central locking with remote control

special Features

- Filing package
- External / internal mirror with auto dip
Außenspiegel elektr. anklappbar, Außenspiegel mit Bordsteinautomatik, rechts
- Roof rails black
- Driving Assistance System Parking Assist
- Driving Assistance System Lane Change Warning System
- Instrument display , multifunctional
- Comfort Access (close / start system)
- Metallic paint
- Park Distance Control (PDC) front and rear
- LED headlights with adaptive light distribution
- Soft -Close function for doors
- HiFi Speaker System Harman Kardon

- Trailer hitch (ball head pivots)
- DAB tuner (digital radio reception)
- Driving Assistance System Driving Assistant Plus
Fahrassistenz-System: Auffahrwarnsystem mit Bremsfunktion, Fahrassistenz-System: Stauassistent
- Speed ??Limit Display
- Head-up display
- Comfort seats, front electric . adjustable (with memory)
Außenspiegel mit Memoryfunktion und Bordsteinautomatik, Lendenwirbelstütze Sitz vorn links und rechts, elektr. verstellbar, Lenksäule (Lenkrad) elektr. verstellbar und Fahrerairbag
- LM rims front / rear 10x20 / 11x20 (star spoke 491)
- Navigation package ConnectedDrive
Ausstattungs-Paket: ConnectedDrive Services, BMW-Online: Internetbasierende Dienste (BMW Live), Freisprecheinrichtung Bluetooth mit erweiterte Smartphone-Anbindung, Sprachbediensystem, Audio-Navigationssystem Professional, Audiosystem BMW Professional (Radio / DVD-Laufwerk MP3-fähig), Service-System: Remote Services, Service-System: Concierge Services, Service-System: Real Time Traffic Information (RTTI)
- Rear View Camera
- Sliding / tilt sunroof electric (glass)
- Sun protection glazing
- Sport Package M / M -Technic
Aerodynamik-Paket M-Technic, Außenausstattung: Shadow-Line Hochglanz, Luftauslass (Air Breather) schwarz hochglänzend, Dachhimmel Anthrazit (BMW Individual), Innenausstattung: Interieurleisten Aluminium Hexagon,

Sportsitze vorn, Sport-Fahrwerk (mit adaptivem Dämpfersystem), LM-Felgen, Lenkrad (Leder M-Technic), Lenkrad mit Schaltwippen/-tasten

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	- -
reference:	

Overview conducted technology audit					
Alternator / Generator:		 in order	Battery / accumulator:		 in order
oil loss:		 examined limited			
air conditioning:		 in order	lighting system:		 in order
coupling:		 unavailable	exhaust System:		 examined limited
engine running:		 in order	shock absorber:		 not checked
transmission:		 examined limited			

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The lighting system was to tour date in order.
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine was performed.
shock absorber:	The shocks were not examined during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. Sidewall - Rear - right	Subsequently painted	acceptable
2. Door Rear - right	Subsequently painted	acceptable
3. Front door - right	Subsequently painted	acceptable
4. Front bumper	Damaged	Refurbish and paint
5. Rim rear - left	Damaged	Replace
6. Outside mirror - right	Damaged	Replace
7. Rim rear - right	Damaged	Paint
8. Sidewall - Rear - Left	Damaged	Refurbish and paint
9. Rear door - left	Damaged	Paint
10. Rim rear - left	Damaged	Paint
11. Front door - left	Damaged	Paint
12. hood	Damaged	Smart repair
13. Rim front - left	Damaged	Paint
14.	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



1. Sidewall - Rear - right



2. Door Rear - right



3. Front door - right



4. Front bumper



4. Front bumper



4. Front bumper



5. Rim rear - left



5. Rim rear - left



5. Rim rear - left



6. Outside mirror - right



6. Outside mirror - right



6. Outside mirror - right



7. Rim rear - right



7. Rim rear - right



7. Rim rear - right



7. Rim rear - right



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



9. Rear door - left



9. Rear door - left



10. Rim rear - left



10. Rim rear - left



10. Rim rear - left




11. Front door - left



11. Front door - left




11. Front door - left



12. hood



12. hood



12. hood



13. Rim front - left



13. Rim front - left



13. Rim front - left



14.



14.



14.