

BMW 3er 320d DPF Touring Aut.

BCA

VIN NO WBAVU51000A322098 Registration Number 000A322098

MOT Date

★ 2026-04-01

Last Service

=-

Number of Owners

4

Last Service Mileage

Number of Keys

P2

First Registration Date

2008-06-06

Odometer Reading

279262 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250911104534
Inspection Date / Place	2025-09-11 / BCA Oberndorf	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	146
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			





























Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Cruise control
Front fog lamps	Remote central locking	Split folding rear seats	Sunroof
CD Player	Electrically adjustable seats	Leather steering wheel	Rear parking sensors
Tow ball	Alloys wheels	Auxiliary Socket	Diesel particulate filter
Remote adjusting wing mirrors	Roof rails	Stability control	Xenon headlamps
Central locking	Electrically folding wing mirrors	Radio	


Equipment Details

Tow Ball Type	Detachable	Air Conditioning	Three Zone Climate Control
Alloy Wheel Size	18	Extra Wheel / Tyre Set	Winter Tyres - Steel
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4
Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage



13	Fender / Front Right	Paint / Scratch / Line
14	Other	Paint / Scratch / Scuff
15	Tailgate	Paint / Corrosion



1. Anomalyon Element -

2. Bumper / Front Paint / Scratch / Scuff -



3. Headlight Nozzle / Front Left Paint / Poor Previous Repair -

4. Hood Bodywork / Dent / Dent -



5. Roof Bodywork / Dent / Dent -

6. Fender / Front Left Paint / Scratch / Line -



7. Seat / Front Left Interior / Scratched -

8. Panel Filling / Front Right Interior / Scratched -



9. Fender / Back Left Paint / Scratch / Line -

10. Bumper / Back Bodywork / Dent / Dent -



11. Fender / Back Right Paint / Scratch / Line -

12. Interior door handle Back right Interior / Scratched -



13. Fender / Front Right Paint / Scratch / Line -

14. Paint / Scratch / Scuff -



15. Tailgate Paint / Corrosion -

Mechanical Condition

Control Lights			
ABS Warning Light	•	ESP Fault/Traction Control Malfunction Light	•
Diesel Particulate Filter Light	•	Airbag Warning Light	•
Oil Pressure Warning Light	•	Brake Warning Light	•
Power Steering Warning Light	•	Alternator / Battery	•
No Dashboard Lights	•	Display Defect	•
Service Light	•		
Engine			
Engine Status / EML	•	Engine Leak Visible	
Engine Starts	⊘		
Gearbox			
Gear Box	•		
Equipments Test			
Audio Equipment	•	AC / Heating System	•
Central Locking	•	Main & Spare Keys Functioning	•
Electric Windows	•	Parking Sensors / Cameras Functioning	•
Other Equipments	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** Not Performed No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide