

BMW 3er 320d DPF Touring Aut.

VIN NO WBAVU51080A317991 Registration Number 080A317991



MOT Date

Number of Owners

P2

Odometer Reading

₩-

2

233166 km

Last Service

Last Service Mileage

First Registration Date

Country First Registered

2008-02-13

Number of Keys

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250508132400
Inspection Date / Place	2025-05-08 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1995
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	146
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available -	Next Service Mileage	km
Previous Usage	Imported	No
Manufacturer Warrenty		






























Equipment

Tinted Glass	Alloys wheels	Bluetooth telephone interface	e Diesel particulate filter
Remote adjusting wing mirrors	Roof rails	Sunroof	Leather steering wheel
Rear parking sensors	Airbag Status	Anti-lock braking	Cruise control
Front fog lamps	Remote central locking	Stability control	CD Player
Radio			


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage




6/12 - Report Number P20250508132400

14	Rocker Panel / Center Right	Paint / Scratch / Scuff
15	Bumper / Front	Paint / Scratch / Scuff
16	Bumper / Front	Paint / Scratch / Scuff
17	Rim / Front Left	Out of Bodywork / Scratch



1. Hood Paint / Poor Previous Repair -

2. Pillar / Front Left Bodywork / Dent / Dent -



3. Door / Front Left Bodywork / Dent / Dent -




4. Door / Back Left Paint / Scratch / Scuff -



5. Door / Back Left Bodywork / Dent / Dent -




6. Panel Filling / Back Left Interior / Scraped -



7. Rim / Back Left Out of Bodywork / Scratch -

8. Bumper / Back Paint / Scratch / Scuff -



9. Side Panel / Back Right Bodywork / Dent / Dent -

10. Door / Back Right Bodywork / Dent / Dent -



11. Panel Filling / Back Right Interior / Scraped -

12. Panel Filling / Front Right Interior / Distorted -



13. Door / Front Right Bodywork / Dent / Dent -

14. Rocker Panel / Center Right Paint / Scratch / Scuff -



15. Bumper / Front Paint / Scratch / Scuff -

17. Rim / Front Left
Out of Bodywork / Scratch -

16. Bumper / Front Paint / Scratch / Scuff -

Mechanical Condition

Control Lights			
Display Defect	•	ABS Warning Light	⊘
ESP Fault/Traction Control Malfunction Light	⊘	Diesel Particulate Filter Light	•
Airbag Warning Light	⊘	Oil Pressure Warning Light	⊘
Brake Warning Light	⊘	Power Steering Warning Light	•
Alternator / Battery	⊘	No Dashboard Lights	•
Tire Pressure Monitoring System	•		
Equipments Test			
Central Locking	⊘	Main & Spare Keys Functioning	•
Electric Windows	⊘	Parking Sensors / Cameras Functioning	•
Engine			
Engine Status / EML	•	Engine Leak Visible	⊘
Engine Starts	•		
Gearbox			
Gear Box	⊘		

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer

User Guide

Please also note the "UserGuide condition report", which shows the scope of the vehicle