



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

BMW Baureihe X4 xDrive 30 d

Vehicle identification number	WBAXX310400K82344	mileage read:	215540 km
First Registration / construction year:	26.02.2015 / 2014	Visit Date / place of birth:	16.05.2025 Riedstadt-Goddelau
Bodywork:	SUV	Re - import:	no
Body type:	Road /	KBA no. :	0005//BVO
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2993 ccm / 190 kW (258 PS)	Engine:	four-wheel
paint:	BLACK SAPPHIRE METALLIC	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
Hard Disk Drive	2	maintained:	- / -
		no / -	
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	Winter tires	aluminum
1st axis - Left / states .	Goodyear	245/45/R18/100H 5 mm
1st axis - right / states .	Goodyear	245/45/R18/100H 5 mm
2nd axis - Left / states .	Goodyear	245/45/R18/100H 5 mm
2nd axis - right / states .	Goodyear	245/45/R18/100H 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag switched off • Anti- lock braking system (ABS) • Drive xDrive (all-wheel) • Audio system BMW Professional (Radio / CD player with MP3 capability) • Chrome exhaust tips • Power side mirrors . adjustable and heated • Bi -xenon headlights <i>Leuchtweitenregelung (automatisch), Heckleuchten LED, Tagfahrlicht LED, Scheinwerfer-Reinigungsanlage (SRA)</i> • White direction indicator lights • brake Assist • Check Control System • Dynamic brake light • Dynamic Traction Control (DTC) • Driving Assistance System Driving Experience Control • Electric windows front + rear • Velour floor mats • Gear sport automatic - with Steptronic (8-step) <i>Lenkrad mit Schaltwippen/-tasten</i> • Tailgate automatically • Isofix admissions for child seat in back seat • Rear curtain airbag system • Steering wheel (sports / leather) • Rear center armrest • LED Fog Lights • NOx storage catalyst (BMW Blue Performance) • Personalization System (personnel profiles) • Tire Pressure Monitoring System • Rear seatback split / folding (402040)	• Airbag Driver / passenger side • Drive all-wheel drive permanent • front armrest • Exhaust system (2-pipe system) with chrome screens • AUX - IN port (AUX -IN) • Outside temperature display • Indicator integrated into mirrors • board computer • Brake Energy Regeneration • Control panel with color monitor (6.5-inch) • Dynamic Stability Control (DSC) • Driving Assistance System Hill Descent Control (HDC) • Driving Assistance System Performance Control • Handsfree with USB interface • Luggage compartment cover / shade • Cupholders front and rear • Interior interior trim Satin Silver , matt • Body 5-door • Head airbag system front • Light package <i>Ambiente-Beleuchtung, Fußraumbeleuchtung vorn, Fußraumbeleuchtung hinten, Ausstiegsleuchten in Türverkleidung unten, Leseleuchten vorn, Leseleuchten hinten</i> • Engine 3.0 ltr. - 190 kW turbodiesel • Non smoking package • Parking brake electrically • Wheelbase 2810 mm • Rußpartikelfilter • Low emissions Euro 6 emission standards

• Heated windshield washer nozzles • Service system Intelligent Emergency incl . TeleServices • Front seats mechanically adjustable • Start / Stop System (Function) • immobilizer • Central locking with remote control	• Front Side Airbags • Power steering Servotronic • Start-stop button • Variable Sports Steering • Tinted heat insulating glass
---	---

special Features	
• Audio-Navigationssystem Professional • Roof rails aluminum satin finish • Driving Assistance System Parking Assist • Innovations Package <i>Adaptives Kurvenlicht, Fahrassistenz-System: Fernlichtassistent, Abbiegelicht, Head-up-Display, Fahrassistenz-System: Speed-Limit-Anzeige, Fahrassistenz-System: Driving Assistant, Fahrassistenz-System: Spurwechselassistent, Fahrassistenz-System: Auffahrwarnsystem</i> • Comfort Access (close / start system) • Seat lumbar support , front left and right, electr. adjustable • Metallic paint • Rear View Camera • Heated front seats • Front sports seats	• External / internal mirror with auto dip <i>Außenspiegel mit Bordsteinautomatik, rechts, Innenspiegel mit Abblendautomatik</i> • Driving Assistance System Driving Assistant Plus <i>Geschwindigkeits-Regelanlage, Aktiv mit Stop&Go-Funktion, Geschwindigkeits-Regelanlage mit Bremsfunktion, Multifunktion für Lenkrad, Fahrassistenz-System: Auffahrwarnsystem mit Bremsfunktion, Fahrassistenz-System: Driving Assistant, Fahrassistenz-System: Spurwechselassistent, Fahrassistenz-System: Auffahrwarnsystem</i> • Driving Assistance System Lane Change Warning System • Automatic climate control with 2-zone automatic . Recirculated air control • • Light and rain sensor • Park Distance Control (PDC) front and rear • Seat cover / upholstery fabric / leather combination Pearlpoint • HiFi Speaker System Harman Kardon • Surround Camera System (Surround View)

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable

reference:

Note Road Safe:

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross: Expertly repaired

On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.

Layers of paint thickness measurement:

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Fahrzeug komplett nachlackiert außer das Dach

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			in order	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	A function of the air conditioning was found to visiting time .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. Front fender - left	Subsequently painted	acceptable
3. Front door - left	Subsequently painted	acceptable
4. Rear door - left	Subsequently painted	acceptable
5. Sidewall - Rear - Left	Subsequently painted	acceptable
6. tailgate	Subsequently painted	acceptable
7. Sidewall - Rear - right	Subsequently painted	acceptable
8. Door Rear - right	Subsequently painted	acceptable
9. Front door - right	Subsequently painted	acceptable
10. Front fender - right	Subsequently painted	acceptable
11. Rear door - left	Rust	Refurbish and paint
12. Roof frame - left		Refurbish and paint
13. Front bumper	Scratch(es)	Paint
14. Radlaufleiste Rechts	Damaged	Replace
15. Windschutzscheibe Leiste Links	Damaged	Replace
16. Rear bumper	Scratch(es)	Paint
17. Door Rear - right	chipped paint	Paint
18. maintenance	Due	Replace
19. proof of maintenance	Missing	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk




instrument cluster



mileage



filler cap



rims




rims




rims



rims



engine compartment



service book



Others



1. hood



2. Front fender - left



3. Front door - left



4. Rear door - left



5. Sidewall - Rear - Left



6. tailgate



7. Sidewall - Rear - right



8. Door Rear - right



9. Front door - right



10. Front fender - right



11. Rear door - left



11. Rear door - left



11. Rear door - left



11. Rear door - left



12. Roof frame - left



12. Roof frame - left



12. Roof frame - left



12. Roof frame - left



12. Roof frame - left



12. Roof frame - left




12. Roof frame - left




13. Front bumper



13. Front bumper



13. Front bumper




13. Front bumper



14. Radlaufleiste Rechts




14. Radlaufleiste Rechts



14. Radlaufleiste Rechts



15. Windschutzscheibe Leiste Links



15. Windschutzscheibe Leiste Links



15. Windschutzscheibe Leiste Links




15. Windschutzscheibe Leiste Links



16. Rear bumper



16. Rear bumper



16. Rear bumper




16. Rear bumper



16. Rear bumper



17. Door Rear - right



17. Door Rear - right



17. Door Rear - right



17. Door Rear - right