



status report

customer: Bank 11, Neuss
contract number: 972174630-AKR
reference:

vehicle data

BMW Baureihe M4 Coupe Competition

Vehicle identification number	WBS31AZ070CF72163	mileage read:	29364 km
First Registration / construction year:	27.11.2020 / 2020	Visit Date / place of birth:	12.09.2025 Knautnaundorf
Bodywork:	cars	Re - import:	no
Body type:	coupe	KBA no. :	7909//ACX
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	2993 ccm / 375 kW (510 PS)	Engine:	rear-wheel drive
paint:	SAO PAULO GELB	Number of previous owners:	2
Doors / seats:	2 / 4	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	4 - moderate
documents:		condition inside:	4 - moderate
visit condition:	-		
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	polished aluminum
1st axis - Left / states .	Pirelli	275/35/ZR19/100Y 4.5 mm
1st axis - right / states .	Continental	275/35/ZR19/100Y 4 mm
2nd axis - Left / states .	Continental	275/35/R20/102Y 3.5 mm
2nd axis - right / states .	Continental	275/35/R20/102Y 4 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Filing package • Airbag switched off • alarm system • Anti- lock braking system (ABS) • Exterior equipment Shadow-Line high gloss (extended scope) • Galvanized controls • board computer • • Headlining anthracite (BMW Individual) • Durchladeeinrichtung (rear center armrest) • Individual seats in the rear • Fahrassistenz-System Active Guard (Bremsassistent) • Power windows • Velour floor mats • Begrenzeranlage speed (Speed ??Limit Device) • Automatic transmission - complete with Steptronic and Drivelogic (8-step) • LED Taillights • Instrument cluster (extended range) • Body 2-door • • Rear curtain airbag system • Lightweight roof (carbon fiber reinforced plastic, CFRP) • Steering column (steering wheel) electr. adjustable • Headlamp leveling • M Drive Professional (driving profile selection) • Rear fog light (s) • Parking brake electrically	• Adaptive suspension M -Technic • Airbag Driver / passenger side • Ambient lighting • Equipment package Connected Professional <i>Ausstattungs-Paket: Connected Teaser, Service-System: Remote Services, Service-System: Concierge Services, Service-System: Real Time Traffic Information (RTTI), Service-System: Remote 3D View</i> • Power side mirrors . adjustable and heated • BMW Live Cockpit Professional • • carbon roof • Anti-theft device for wheels (rim locks) • Dynamic Stability Control (DSC) with extended scope • First aid kit / first aid kit • Driver Assistance System Attention Assistant • Handsfree Bluetooth with USB audio interface • Luggage compartment lighting • Cruise control system with brake function • cup holders • Rearview mirror with auto dip • Isofix admissions for child seat in back seat • License plate lighting LED • Knee airbag driver side • Head airbag system front • Steering wheel (leather) with multifunction M -Technic • Steering column (steering wheel) mechan. adjustable • M Drive



• Tyre Defect Indicator • Shift Indicator • Front Side Airbags • Service system Legal emergency call • Electric front seats . adjustable (with memory) <i>Lendenwirbelstütze Sitz vorn links und rechts, elektr. verstellbar</i> • Smartphone integration (Apple CarPlay and Android Auto) • Sportdifferential • Start / Stop System (Function) • immobilizer • Combined heat / sun protection glazing	• Motor 3,0 Ltr. - 375 kW 24V TwinTurbo KAT (S58) <i>Motor 3,0 Ltr. - 375 kW 24V</i> • • Tire Pressure Monitoring System • Low in emissions according to the Euro 6d emissions standard • Windscreen wipers with rain sensor • Service-System ConnectedDrive Services • Service system Intelligent Emergency incl . TeleServices • Heated front seats • Mirror package <i>Außenspiegel elektr. anklappbar, Außenspiegel mit Abblendautomatik, links, Außenspiegel mit Bordsteinautomatik, rechts</i> • Start-stop button • warning triangle • Heat/sun control glazing • Central locking with remote control
--	--

special Features	
• BMW Drive Recorder (Dashcam) • Interior interior trim Carbon • LM rims front/rear 9.5x19 / 10.5x20 (double spokes 825 M, Orbit gray matt) • M bucket seats carbon • BMW Individual Shadow-Line headlights • Security System Active Protection • Sun protection glazing • Solid paint finish Sao Paolo Yellow	• Brake system Compound - M brake system (brake calipers black) • Innovations Package <i>Scheinwerfer Laserlicht, Fahrassistenz-System: Fernlichtassistent, Head-up-Display, Komfortzugang (Öffnungs- und Schließsystem), Fahrassistenz-System: Driving Assistant, Fahrassistenz-System: Spurwechselassistent, Fahrassistenz-System: Frontkollisionswarnung, Fahrassistenz-System: Heckaufprall-Vermeidung (Prävention Heckkollision), Fahrassistenz-System: Querverkehrs-Assistent, Fahrassistenz-System: Spurwechsel-Warnsystem</i> • heated steering wheel • Parkassistent-Paket More <i>Service-System: Remote 3D View, Rückfahrkamera (Top View), Surround-Kamerasystem (Surround View), Fahrassistenz-System: Rückfahr-Assistent</i> • Seat belts M • Seat cover / upholstery full-leather Merino, bicolor • HiFi Speaker System Harman Kardon

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and

correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Frontscheibe Steinschlag, diverse Fehlermeldungen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			not possible	Battery / accumulator:	
			Out of order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			not possible		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) could not be verified . *Fehlermeldung Energieversorgung
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Found corrosion on the battery.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Das Fahrzeug hat starke Alters- und Gebrauchsspuren

damage



component	Damage	Rep kind
1. hood	Subsequently painted	acceptable
2. Batterie	Not okay	Replace
3. diverse Fehlermeldungen (Lenkung, Energieversorgung, Sitz, Reifen, Wischwasser...)	Error message	Carry out a fault diagnosis
4. Wartung (Bremsflüssigkeit, Fahrzeug-Check, Motoröl, Fahrzeuguntersuchung)	Error message	Replace
5. Kofferraum und Innenraum	Wear and tear	acceptable
6. Sitz - Vorne - Links: Lehnverkleidung	Scrape	Replace
7. Sitz - Vorne - Rechts: Lehnverkleidung	Scrape	Replace
8. Türverkleidung Vorne - Links	Scrape	Smart repair
9.	Scrape	Smart repair
10. center console - flap	Scrape	Smart repair
11.	Scrape	Smart repair
12.	Scrape	Smart repair
13. Door trim Front - right	Scrape	Smart repair
14.	Damaged	Replace
15.	Damaged	Replace
16.	Scrape	Smart repair
17.	Damaged	Replace
18. Sidewall - Rear - right		Smart repair
19.	Scratch(es)	Paint
20. A-pillar Front - right	Chipping from stones	Smart repair
21. Front fender - right	Chipping from stones	Smart repair
22. hood	Chipping from stones	Smart repair
23. Stoßfänger Vorne: Schrauben	Rust	Replace
24. Front bumper	Scrape	Smart repair
25. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Verschmutzungen)	Not okay	
26. Rear bumper	Scrape	Smart repair
27. Windshield	Chipping from stones in field of view	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims




engine compartment



service book



Others



Navigation system




1. hood




3. diverse Fehlermeldungen (Lenkung, Energieversorgung, Sitz, Reifen, Wischwasser...)




3. diverse Fehlermeldungen (Lenkung, Energieversorgung, Sitz, Reifen, Wischwasser...)



3. diverse Fehlermeldungen (Lenkung, Energieversorgung, Sitz, Reifen, Wischwasser...)





3. diverse Fehlermeldungen (Lenkung,



3. diverse Fehlermeldungen (Lenkung,

Energieversorgung, Sitz, Reifen, Wischwasser...)

Energieversorgung, Sitz, Reifen, Wischwasser...)



3. diverse Fehlermeldungen (Lenkung, Energieversorgung, Sitz, Reifen, Wischwasser...)

3. diverse Fehlermeldungen (Lenkung, Energieversorgung, Sitz, Reifen, Wischwasser...)



4. Wartung (Bremsflüssigkeit, Fahrzeug-Check, Motoröl, Fahrzeuguntersuchung)

5. Kofferraum und Innenraum



5. Kofferraum und Innenraum



5. Kofferraum und Innenraum




6. Sitz - Vorne - Links: Lehnverkleidung



6. Sitz - Vorne - Links: Lehnverkleidung



7. Sitz - Vorne - Rechts: Lehnverkleidung



7. Sitz - Vorne - Rechts: Lehnverkleidung



8. Türverkleidung Vorne - Links



8. Türverkleidung Vorne - Links




9.



9.



10. center console - flap



10. center console - flap



11.



11.



11.



12.



13. Door trim Front - right



13. Door trim Front - right



13. Door trim Front - right



14.



14.



15.



15.



15.



15.



16.



16.



16.



17.



17.




17.




17.



18. Sidewall - Rear - right



18. Sidewall - Rear - right



19.



19.



19.



19.



20. A-pillar Front - right



20. A-pillar Front - right



20. A-pillar Front - right



21. Front fender - right



21. Front fender - right




21. Front fender - right




21. Front fender - right



22. hood



22. hood



22. hood



23. Stoßfänger Vorne: Schrauben



23. Stoßfänger Vorne: Schrauben



23. Stoßfänger Vorne: Schrauben



23. Stoßfänger Vorne: Schrauben



23. Stoßfänger Vorne: Schrauben



23. Stoßfänger Vorne: Schrauben



24. Front bumper



24. Front bumper



25. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Verschmutzungen)



25. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Verschmutzungen)



26. Rear bumper



26. Rear bumper



27. Windshield



27. Windshield