MACMDAM

BMW iX1 / 2022 / 5P / SUV

Vehicle information

Make:BMWLicense:GS738LTGearbox:AutomaticBody color:Black

Model: **iX1 / 2022 / 5P / SUV** VIN: **WBY61EF0805X78575**

Fuel type: Electric Power: 230 kW

Version: xDrive30 M Sport First registration 17/11/2023

Mileage: 116769 km N° of doors:

Damage summary

| Front | Interior 1 |
|---------------|------------|
| Left 1 | Rear 3 |
| Wheels | |

Commercial pictures




























Options according to the inspector

| Headlights Xenon/LED/Laser | Yes | Panoramic roof | Yes | Rear view camera | Yes |
|----------------------------|-----|-------------------------|-----------------------|------------------|-----|
| Sun Roof electric | Yes | Type of climate control | Autom climate control | | |

Damages

Alloy rim FL bitone/polychrome

Scratch(es)

Repair/replace (lump sum)

Wheels











Bumper F Scratch(es) Paint Front







Compressor

Missing

Repair/replace (lump sum)

Rear










Door RL
Dent(s)
Repair and paint (complete)
Left





Interior covering B pillar L

Scratch(es)
Repair/replace (lump sum)
Interior







Tailgate / Boot

Dent(s)
Paintless dent repair
Rear





Tyre repair kit

Missing

Repair/replace (lump sum)

Rear





| Tyres | | | | | |
|-------------|--------|-----|-----------------|-------------|--------|
| Location | Туре | Rim | Measures | Make | Depth |
| Front Left | Summer | | 225/55/18/102/Y | Bridgestone | 4.5 mm |
| Front Right | Summer | | 225/55/18/102/Y | Bridgestone | 4.4 mm |
| Rear Left | Summer | | 225/55/18/102/Y | Continental | 4.3 mm |
| Rear Right | Summer | | 225/55/18/102/Y | Continental | 4.1 mm |

| Checks | | | |
|--|-----------|------------------------------------|---------------|
| Body colour | Black | Category | Passenger Car |
| Compressor | No | Engine functioning | Yes |
| Fuel Level | 25 | Jack | N/A |
| Luggage cover | Yes | Number head rests | 5 |
| Number keys remote | 2 | Number of charging cables (normal) | 1 |
| Number of charging cables (rapid charge) | 1 | Number of keys total | 2 |
| Number of seats | 5 | Paint type | Metalic |
| Registration Certificate | No | Registration Certificate | N/A |
| Repair kit | No | Runflat | No |
| Service book | N/A | Spare wheel | N/A |
| Type of rims (mounted) | Aluminium | User's manual | N/A |
| Warning lights (maintenance, pollution, etc) ? | No | | |

Information on the content and the scope of the inspection report:

- $\bullet\hspace{0.4cm}$ The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.