



status report

customer: BCA Autoauktionen GmbH

reference:

vehicle data

Mercedes-Benz Sprinter II Kasten 310/311/313/314/316 CDI

Vehicle identification number	WDB9066331P334142	mileage read:	246686 km
..			
First Registration / construction year:	20.10.2016 / 2016	Visit Date / place of birth:	06.10.2025 Hoppegarten
Bodywork:	transporter	Re - import:	unknown
Body type:	van	KBA no. :	1313//EFY
Fuel / emission class:	diesel / € 6	transmission type:	manual transmission
Displacement / power:	2143 ccm / 120 kW (163 PS)	Engine:	rear-wheel drive
paint:	obsidianschwarz metallic	Number of previous owners:	2
Doors / seats:	5 / 3	number keys:	1
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	Eg II (veh - letter)	state outside:	5 - neglected
documents:			
visit condition:	-	condition inside:	3 - Average
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	no / -	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	All season tires	steel
1st axis - Left / states .	Continental	235/65/16/115/113R 3 mm
1st axis - right / states .	Continental	235/65/16/115/113R 3 mm
2nd axis - Left / states .	Anderer	235/65/16/115/113R 3 mm
2nd axis - right / states .	Anderer	235/65/16/115/113R 3 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3rd brake light • Airbag driver • Drive Rear Wheel Drive • Power side mirrors . adjustable and heated, both • Battery 74 Ah • Brake system with ABS + ASR • Electron. Stability Program (ESP) • Transmission 6-speed - TSG (Eco Gear) • Body / Structure box • Cargo space partition continuously • Headlamp leveling • Engine 2.1 ltr. - 120 kW CDI KAT • Wheelbase 3665 mm • Sliding load / passenger compartment right • Seat belt system with alarm • Seats in the cab driver's seat with armrest • Service interval indicator Assyst • Central locking with remote control	• Adaptive brake lights • Anti- lock braking system (ABS) • Display for wash water level • Exterior mirrors with integral indicators • brake Assist • Roof panel in the cab • Power windows 2 times • Lockable glove compartment • childlock • Load anchoring / Lashing • model refinement • particle filter • Low emissions Euro 6 emissions standard • power steering • Seats in the cab passenger seat with armrest • Steel rims 6,5x16 • immobilizer • Perm. Total weight of 3.50 t

special Features	
• Airbag • 13-pin trailer socket • Equipment package Driver Comfort <i>Nebelscheinwerfer, Parktronic-System (PTS), Geschwindigkeits-Regelanlage (Tempomat), Sitze im Fahrerhaus: Fahrersitz heizbar, Sitze im Fahrerhaus: Schwingsitz Komfort, Fahrerseite, Sitzausstattung: Komfort- Kopfstütze, Fahrersitz, Lenkrad mit Multifunktion inkl. Reiserechner, Lenkrad (Lenksäule mech. verstellbar)</i> • Overhead control panel with reading light Driver / passenger side	• Towbar fixed ball head • Audio System Audio 15 (radio with color display) • Bi -Xenon headlights with static cornering lights <i>Scheinwerfer-Reinigungsanlage (SRA)</i> • Ceiling light in the hold • Driver assistance system Lane Keeping Assist • Master key in addition • Wood floor in the cargo area • Fuel filter with water separator • Light and rain sensor • Spare wheel

• Theft alarm system + Innenraumabsicherung / tow-away protection • Generator 180 A • Tailgate (opening angle 270 degrees) • Hinged lid for storage compartment • Fuel tank main tank 100 ltr. • Metallic paint • Spare wheel holder under frame end incl . Jack • Sliding load / passenger compartment left • Seats in the cab passenger double seat • Reinforced rear stabilizer bar • reinforced shock absorbers • Rear wall panel	• Reversing Aid (rear camera) • Seat cover / leatherette upholstery (cab) • Seats in the cab passenger double seat folded down with backrests • Reinforced Front stabilizer bar • Tread rear door • Heat -insulating glass (windshield with band filter above)
---	---

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen Verschleißgrenze erreicht

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	-

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			Out of order		
oil loss:			examined limited		
air conditioning:			unavailable	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			Out of order	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The vehicle has no air conditioning.
lighting system:	The Lichtenanlage could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light.
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*

damage



component	Damage	Rep kind
1. tailgate	Subsequently painted	acceptable
2. Sidewall - Rear - Left	Subsequently painted	acceptable
3. motor	Error message	Carry out a fault diagnosis
4.	Missing	Replace
5. proof of maintenance	Missing	Replace
6. maintenance	Due	Replace
7. Key with remote control	Missing	Replace
8. PDC	Error message	Carry out a fault diagnosis
9. Luftausströmer	Damaged	Replace
10. Reifen 4x	Not safe for road traffic	Replace
11. battery	Not okay	Replace
12.	Wear and tear	acceptable
13. Tailgate left	Damaged	Refurbish and paint
14. Tailgate right	Damaged	Refurbish and paint
15. Rear bumper	Damaged	Replace
16. Sidewall - Rear - right	Damaged	Refurbish and paint
17. Door Rear - right	Deformed	Refurbish and paint
18. side skirt - right	Scratch(es)	Paint
19. B-pillar center - right	Corroded	Paint
20. Front fender - right	Deformed (slightly)	Refurbish and paint
21.	Wear and tear	acceptable
22.	Missing	Replace
23. hood	Deformed	Replace
24. Sidewall - Rear - Left	Damaged	Refurbish and paint
25. Rear door seal - left	Damaged	Replace
26. Rear door - left	Wear and tear	acceptable
27. Windshield	Chipping from stones	Smart repair
28. Türeinstieg Vorne - Links	Scrape	Paint
29.	Damaged	Replace
30. Front door - left	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right




rear Left



rear Right



inside




inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. tailgate



2. Sidewall - Rear - Left



3. motor



6. maintenance



8. PDC



9. Luftausströmer



12.



12.




12.



12.



13. Tailgate left



13. Tailgate left



14. Tailgate right



14. Tailgate right



15. Rear bumper



16. Sidewall - Rear - right



16. Sidewall - Rear - right



17. Door Rear - right



17. Door Rear - right



17. Door Rear - right



18. side skirt - right



18. side skirt - right



19. B-pillar center - right



20. Front fender - right



21.



22.



23. hood



23. hood



23. hood



23. hood



24. Sidewall - Rear - Left



24. Sidewall - Rear - Left



24. Sidewall - Rear - Left



25. Rear door seal - left



26. Rear door - left



26. Rear door - left



27. Windshield



28. Türeinstieg Vorne - Links



29.



30. Front door - left



30. Front door - left