

## MERCEDES-BENZ M-Klasse ML 350 4MATIC (BlueEFFICIENCY) 7G-**TRONIC**



VIN NO WDC1660571A007638 Registration Number 571A007638

**Number of Owners** 

**MOT Date** 

Number of Keys

**Odometer Reading** 

₩-

2

**2**2

223731 km

**Last Service** 

Last Service Mileage

First Registration Date

**Country First Registered** 

**2**011-11-30

**=**-

### **Inspection Report Summary**

| Customer                | BCA Online          | Report Number  | P20250725094810 |
|-------------------------|---------------------|----------------|-----------------|
| Inspection Date / Place | 2025-07-25 / Extern | Cosmetic Grade | 4               |

### Vehicle Summary

| Vehicle Condition  | Runner    | VAT Type               | Margin                    |
|--------------------|-----------|------------------------|---------------------------|
| Fuel Type          | Petrol    | Road Worthy            | Unknown                   |
| Colour             | Black     | Engine Size (cc)       | 3498                      |
| Engine Size        | 3.5       | No of Doors            | 5                         |
| Body Type          | SUV       | Drive Train            | All-Wheel-Drive permanent |
| Seat Colour        |           | No of Seats            | 5                         |
| Seat Covering Name |           | Seat Covering          | Synthetic Leather         |
| Charging Cables    |           | NEDC CO2 Rating (q/km) | 199                       |
| Gearbox Type       | Automatic |                        |                           |

### Vehicle History & Documents

| Service Book Available | Present | Next Service Mileage | km |
|------------------------|---------|----------------------|----|
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |




















































# Equipment

| Tinted Glass          | USB Socket                    | Alloys wheels                     | Bluetooth telephone interface |
|-----------------------|-------------------------------|-----------------------------------|-------------------------------|
| Front parking sensors | Remote central locking        | Satellite navigation              | Stability control             |
| Xenon headlamps       | Electrically adjustable seats | Electrictailgate                  | Radio                         |
| Rear parking sensors  | Tow ball                      | Airbag Status                     | Anti-lock braking             |
| Cruise control        | Remote adjusting wing mirrors | Roof rails                        | Split folding rear seats      |
| Sunroof               | CD Player                     | Electrically folding wing mirrors | Leather steering wheel        |
| Rear DVD system       |                               |                                   |                               |


# **Equipment Details**

| Tow Ball Type    | Pivoted        | Air Conditioning       | Dual Zone Climate Control |
|------------------|----------------|------------------------|---------------------------|
| Alloy Wheel Size | 19             | Extra Wheel / Tyre Set | Winter Tyres - Alloy      |
| Seat Heating     | Front and Rear | Sunroof Type           | Tilt/Slide Glass          |

# Wheels & Tyres

| Right Front Tyre Depth     | 5 | Left Front Tyre Depth      | 5 |
|----------------------------|---|----------------------------|---|
| Right Rear Tyre Depth      | 5 | Left Rear Tyre Depth       | 5 |
| Extra Wheel - 1 Tyre Depth | 3 | Extra Wheel - 2 Tyre Depth | 3 |
| Extra Wheel - 3 Tyre Depth | 4 | Extra Wheel - 4 Tyre Depth | 4 |

## Cosmetic Damage




|    | Component              | Damage                      | Comments |
|----|------------------------|-----------------------------|----------|
| 1  | Roof Upholstery        | Interior / Dirty            |          |
| 2  | Floor Carpet           | Interior / Dirty            |          |
| 3  | Center Console         | Interior / Scraped          |          |
| 4  | B Pillar / Center Left | Paint / Scratch / Scuff     |          |
| 5  | Bumper / Back          | Bodywork / Breakage / Crack |          |
| 6  | Bumper / Back          | Paint / Scratch / Scuff     |          |
| 7  | Bumper / Back          | Paint / Scratch / Scuff     |          |
| 8  | Back Light / Left      | Bodywork / Breakage         |          |
| 9  | Side Panel / Back Left | Bodywork / Dent / Dent      |          |
| 10 | Door / Back Left       | Bodywork / Dent / Dent      |          |
| 11 | Bumper / Front         | Paint / Scratch / Scuff     |          |
| 12 | Windshield / Front     | Glass Break / Impact        |          |
| 13 | Door / Back Right      | Bodywork / Dent / Dent      |          |

| 14 | Door / Front Right      | Bodywork / Dent / Dent |
|----|-------------------------|------------------------|
| 15 | Side Panel / Back Right | Bodywork / Dent / Dent |
| 16 | Side Panel / Back Right | Bodywork / Dent / Dent |
| 17 | Other                   | Anomalyon Element      |



1. Roof Upholstery Interior / Dirty -

2. Floor Carpet Interior / Dirty -



3. Center Console Interior / Scraped -

4. B Pillar / Center Left Paint / Scratch / Scuff -




5. Bumper / Back Bodywork / Breakage / Crack -

6. Bumper / Back Paint / Scratch / Scuff -



7. Bumper / Back Paint / Scratch / Scuff -

8. Back Light / Left Bodywork / Breakage -



9. Side Panel / Back Left Bodywork / Dent / Dent -

10. Door / Back Left Bodywork / Dent / Dent -



11. Bumper / Front Paint / Scratch / Scuff -




12. Windshield / Front Glass Break / Impact -



13. Door / Back Right Bodywork / Dent / Dent -

14. Door / Front Right Bodywork / Dent / Dent -



15. Side Panel / Back Right Bodywork / Dent / Dent -

16. Side Panel / Back Right Bodywork / Dent / Dent -



17. Anomalyon Element -

#### **Mechanical Condition**

| Control Lights                           |          |   |          |
|--|----------|---|----------|
| Display Defect                           | •        | Service Light                                   |          |
| ABS Warning Light                        | <b>②</b> | ESP Fault/Traction Control<br>Malfunction Light | <b>⊘</b> |
| Airbag Warning Light                     | <b>⊘</b> | Oil Pressure Warning Light                      | <b>⊘</b> |
| Brake Warning Light                      | •        | Power Steering Warning<br>Light                 | •        |
| Alternator / Battery                     | <b>⊘</b> | All - wheel Drive                               | <b>⊘</b> |
| No Dashboard Lights                      | •        |   |          |
| Equipments Test                          |          |   |          |
| Central Locking                          | •        | Electric Windows                                | <b>⊘</b> |
| Navigation System                        | •        | Audio Equipment                                 | •        |
| Parking Sensors / Cameras<br>Functioning | <b>②</b> | AC / Heating System                             | <b>⊘</b> |
| Engine                                   |          |   |          |
| Engine Status / EML                      | •        | Engine Leak Visible                             | NA       |
| Engine Starts                            | •        |   |          |
| Gearbox                                  |          |   |          |
| Gear Box                                 | •        |   |          |
| Levels                                   |          |   |          |
| Coolant Fluid                            | •        |   |          |

#### **Test Drive Inspection**

