



Hüsges Gruppe®
Die Gutachter

status report

customer:	BCA Autoauktionen GmbH
reference:	

vehicle data			
Mercedes-Benz CLA -Klasse CLA 250 4Matic Sport (117.351)			
Vehicle identification number	WDD1173511N516572	mileage read:	109787 km
..			
First Registration / construction year:	11.04.2017 / 2017	Visit Date / place of birth:	11.08.2025 Hoppegarten
Bodywork:	cars	Re - import:	no
Body type:	limousine	KBA no. :	1313//EST
Fuel / emission class:	gasoline / € 6	transmission type:	automatic
Displacement / power:	1991 ccm / 160 kW (218 PS)	Engine:	four-wheel
paint:	NACHTSCHWARZ - UNILACK	Number of previous owners:	3
Doors / seats:	4 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	leather
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	Eg II (veh - letter)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	no / -	- / -
☒ Fernbed . Auxiliary heating	☒ partition net	☒ Wind Deflector	☒ AHK fixed
☒ AHK removable	☒ AHK swivel	☒ AHK key	☒ Fernbed . entertainment
☒ headphone	☒ Load compartment cover	☒ LED headlights	☒ navigation system
☒ Persenning	☒ Xenon headlights		



available



not available

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Michelin	235/35/ZR19/91Y 6 mm
1st axis - right / states .	Michelin	235/35/ZR19/91Y 6 mm
2nd axis - Left / states .	Pirelli	235/35/ZR19/91Y 6 mm
2nd axis - right / states .	Pirelli	235/35/ZR19/91Y 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Adaptive brake lights • active Bonnet • Acceleration skid control (ASR) • Power side mirrors . adjustable and heated, both • Pelvic airbags (pelvisbag) • brake Assist • Chrome package • Off switch for headlights • Driver assistance system active brake assist <i>Fahrassistenz-System: Auffahrwarnsystem mit Bremsfunktion (Collision Prevention Assist)</i> • Hill Start Assist • Parking brake electrically • Transmission 7 - speed dual - clutch transmission DCT • Heated rear window (ESG) • Headliner Fabric • Body 4 doors • Knee airbag , driver's side • Steering column (steering wheel) mechan. adjustable • Mercedes- Benz emergency call system • 2.0 Ltr motor. - 160 kW KAT • Tire Pressure Monitoring System • Rear seat backrest split / folding • Side airbags (side airbag), front • Seat occupancy detection for airbag passenger side • / Storage shelf under the load compartment floor • Body color bumpers • Exterior door handles body color • Alarm / status indicator for seat belts in the rear	• Airbag Driver / passenger side • Anti- lock braking system (ABS) • Front armrest with compartment • Outside temperature display • Indicator integrated into mirrors • Painted brake calipers red • Design and equipment line AMG Line <i>AMG-Optic-/Styling-Paket 1, Sitz-Komfort-Paket, Kühlergrill Diamant-Optik, Innenausstattung: Zierteile Aluminium, Edelstahlpedale Sportdesign, Sitzbezug / Polsterung: Ledernachbildung Artico / Dinamica, Sportsitze vorn, Schalt-/Wählhebelgriff Leder Nappa, Sport-Fahrwerk, Lenkrad (Leder), Lenkrad (Sport) mit Multifunktion, Fahrassistenz-System: Agility Select / Dynamic Select (Fahrmodusschalter)</i> • Electron. Stability Program (ESP) • Driving Assistance System Attention Assist (fatigue detection sensor) • Electric windows front + rear • Windscreen laminated glass • LED Taillights • Infotainment system Connect ME • Isofix admissions for child seat in back seat • air Conditioning • Head airbag system (Windowbag) • LM rims <i>LM-Felgen</i> • Model maintenance with code • speed-sensitive steering • trip computer • Low emissions Euro 6 emission standards • designo seat belts • Start / Stop system

• Wärmeschutzverglasung	• Socket (12V) port in the trunk / cargo area • cruise control • USB / AUX - IN connection • immobilizer
---	--

special Features	
• Folding rear armrest with through-loading facility (removable) • Exclusive package (AMG) <i>Armaturentafel in Ledernachbildung Artico, Edelstahlpedale Sportdesign, Sitzheizung vorn, Sitzbezug / Polsterung: Leder, Lendenwirbelstützen vorn, elektr. verstellbar, Zentralverriegelung mit Infrarot - / Komfortbedienung, Schalt-/Wählhebelgriff Leder Nappa</i> • Light and Sight package <i>Scheibenwischer mit Regensensor, Ambiente-Beleuchtung, Sonnenblenden mit Spiegel (beleuchtet)</i> • Night package <i>Außenspiegel schwarz lackiert, Seitenscheiben hinten und Heckscheibe abgedunkelt</i> • Headlamp LED High Performance • TFT color display (8.0 inches)	• Equipment package business <i>Audiosystem Audio 20 mit Vorbereitung Garmin MAP Pilot, Fahrassistentz-System: aktiver Park-Assistent, Navigationsmodul Garmin MAP Pilot, Sitzheizung vorn</i> • Keyless Start system and central locking <i>Keyless Go Startanlage</i> • Media Interface (Universal Interface for iPod / AUX / USB / MP3) • Rear View Camera • Sound system Harman-Kardon Logic 7 surround sound system with

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	Conducted limited To investigate the vehicle (ä . Lift o .) Were not lifting means even a ramp or pit available. For this reason, a visit to the vehicle's underside was limited.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage

**Layers of paint thickness
measurement:**

could be detected .

Within the tolerances

At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes . Evidence that points to a repaired accident damage or repainting carried out , were identified.

Existing collision damage:

-
-

reference:

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
oil loss:			examined limited	 examined limited	
air conditioning:			examined limited	lighting system:	
coupling:			unavailable	 examined limited	
engine running:			examined limited	exhaust System:	
transmission:			examined limited	 examined limited	

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Oberflächenkratzer/Kratzer rundum

damage



component	Damage	Rep kind
1. proof of maintenance	Missing	Replace
2. maintenance	Missing	Replace
3. Rear bumper	Damaged	Replace
4. tire rear - right	Wear and tear	acceptable
5. Door Rear - right	Wear and tear	acceptable
6. Türeinstieg Hinten - Rechts	Wear and tear	acceptable
7. Zierleisten	Wear and tear	acceptable
8. Front door - right	Wear and tear	acceptable
9.	Scratch(es)	Paint
10. Front bumper	Wear and tear	acceptable
11. hood		Paint
12. Front fender - left		Paint
13. Roof frame - left	Wear and tear	acceptable
14. Fahrersitz	Wear and tear	acceptable

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims




rims



engine compartment



service book



Others



Navigation system



3. Rear bumper



3. Rear bumper



3. Rear bumper



4. tire rear - right



5. Door Rear - right



6. Türeinstieg Hinten - Rechts



7. Zierleisten



8. Front door - right



9.



10. Front bumper



11. hood



11. hood



12. Front fender - left



13. Roof frame - left



14. Fahrsitz



14. Fahrsitz