

MERCEDES-BENZ C-Klasse C 200 T CDI DPF Automatik

VIN NO WDD2042011F510517 Registration Number 011F510517

MOT Date

Number of Owners

P2

Odometer Reading

☆-

3

2 192727 km

Last Service

2023-04-28

Last Service Mileage

First Registration Date

Country First Registered

167844

2010-05-06

Number of Keys

=-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250520112152
Inspection Date / Place	2025-05-20 / BCA Heidenheim	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	2143
Engine Size	2.1	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	153
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









































Equipment

Trip Computer	Alloys wheels	Bluetooth telephone interface	e Diesel particulate filter
Front parking sensors	Remote central locking	Satellite navigation	Stability control
Electrically folding wing mirrors	Radio	Airbag Status	Anti-lock braking
Cruise control	Front fog lamps	Remote adjusting wing mirrors	Roof rails
Split folding rear seats	CD Player	Leather steering wheel	Rear parking sensors


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Summer Tyres - Alloy	Seat Heating	Front

Wheels & Tyres

Left Front Tyre Depth	3	Right Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6
Extra Wheel - 1 Tyre Depth	2	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	3	Extra Wheel - 4 Tyre Depth	4

Cosmetic Damage





1. Seat / Front Left Interior / Holed -

2. Hood Bodywork / Dent / Dent -




3. Hood Bodywork / Dent / Dent -

4. Corner Bumper / Front Right Bodywork / Dent / Dent -



5. Rim / Front Right Paint / Corrosion -

6. Door / Back Right Bodywork / Dent / Dent -



7. Rim / Back Right Paint / Corrosion -

8. Corner Bumper / Back Right Bodywork / Breakage / Hole -



9. Tailgate Bodywork / Dent / Dent -

10. Rim / Back Left Paint / Corrosion -



11. Door / Back Left Bodywork / Dent / Dent -

12. Door / Front Left Paint / Scratch / Scuff -



13. Mirror Shell / Front Left Bodywork / Breakage / Crack -

Mechanical Condition

Control Lights			
Display Defect	•	ABS Warning Light	•
ESP Fault/Traction Control Malfunction Light	•	Diesel Particulate Filter Light	•
Airbag Warning Light	⊘	Oil Pressure Warning Light	⊘
Brake Warning Light	•	Power Steering Warning Light	•
No Dashboard Lights	⊘	Tire Pressure Monitoring System	•
Equipments Test			
Main & Spare Keys Functioning	⊘	Electric Windows	•
Navigation System	•	Audio Equipment	•
Parking Sensors / Cameras Functioning	⊘	AC / Heating System	•
Engine			
Engine Status / EML	•	Engine Leak Visible	•
Engine Starts	②		
Gearbox			
Gear Box	•		
Levels			
Brakes Fluid	•	Coolant Fluid	•

Test Drive Inspection

description.

Steering Wheel Steering | Noise / Anomaly **Engine** The Gears Scratch / Skip / **Engine Noise Abnormal Operation Fume Quantity Power Loss Brake Brake System Anomaly** General **Test Driven Status** No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer NA Not applicable ■ Not tested Disclaimer Please also note the "UserGuide condition report", which shows the scope of the vehicle

User Guide