



Hüsge Gruppe®
Die Gutachter

status report

customer:	BCA Autoauktionen GmbH
reference:	

vehicle data			
Mercedes-Benz E -Klasse Lim. E 220 d (213.004)			
Vehicle identification number	WDD2130041A345610	mileage read:	73185 km
..			
First Registration / construction year:	12.10.2017 / 2017	Visit Date / place of birth:	06.12.2024 Bad Fallingbostal
Bodywork:	cars	Re - import:	unknown
Body type:	limousine	KBA no. :	1313//FDI
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1950 ccm / 143 kW (194 PS)	Engine:	rear-wheel drive
paint:	gray	Number of previous owners:	4
Doors / seats:	4 / 5	number keys:	1
Next HU / AU:	- / -	cushion type:	Imitation leather / fabric
Service book available:	no	Interior Color:	Multicolor
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	3 - Average
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
Hard Disk Drive	1	no / 6	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ available

☒ not available

Hüsge GmbH
Ein Unternehmen der Hüsge Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsge
Dipl.- Ing. (FH) Bernd Hüsge

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Pirelli	225/55/R17/97Y 5 mm
1st axis - right / states .	Pirelli	225/55/R17/97Y 5 mm
2nd axis - Left / states .	Pirelli	225/55/R17/97Y 3 mm
2nd axis - right / states .	Pirelli	225/55/R17/97Y 3 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• Airbag deactivated • Anti- lock braking system (ABS) • Pelvic airbags (pelvisbag) • Electron. Stability Program (ESP) • Driving Assistance System Attention Assist (fatigue detection sensor) • Hill Start Assist • Automatic transmission - (9 stages) • Infotainment system Connect ME • Body 4 doors • Automatic air conditioning (Thermatic 2 zones) • Head airbag system front • Center console piano lacquer look • PRE - SAFE system • Rußpartikelfilter • Windscreen wipers with rain sensor • Side airbags (side airbag), front • Electric front seats . adjustable	• Airbag Driver / passenger side • Audiosystem Audio 20 (USB, GPS) • Design and equipment line avant-garde <i>Seitenschweller Wagenfarbe, Komfort-Fahrwerk tiefergelegt (Agility Control), LM-Felgen, LM-Felgen</i> • Driving Assistance System Agility Select / Select Dynamic (driving mode switch) • Driving Assistance System Collision Warning with braking function (Collision Prevention Assist) • Electric windows front + rear • Urea tank (AdBlue), enlarged • Isofix admissions for child seat in back seat • • Knee airbag , driver's side • Mercedes- Benz emergency call system • • Tire Pressure Monitoring System • Low emissions Euro 6 emission standards • SCR (AdBlue technology) • power steering • Central locking with remote control

special Features	
• Filing package • Equipment package business <i>Scheinwerfer LED High Performance, Fahrassistenz-System: aktiver Park-Assistent, Navigationsmodul Garmin MAP Pilot, Infotainment-System: Remote Online, Sitzheizung vorn, Kraftstofftank: vergrößert</i> • Velour floor mats • Metallic paint	• Trailer hitch (ball head pivots) • Avantgarde interior <i>Zeituhr (Analog), Innenausstattung: Zierteile Aluminium, Sitzbezug / Polsterung: Stoff / Ledernachbildung Artico, Ambiente-Beleuchtung, Brillenfach im Dachhimmel integriert</i> • Interior Features hardwood black ash • Multibeam LED <i>Fahrassistenz-System: Fernlichtassistent Adaptive plus</i>

• Parking package <i>Fahrassistenz-System: aktiver Park-Assistent, Kamerasystem 360 Grad</i> • Rear seatback split / folding • Seat comfort package • Preparation Garmin GPS MAP PILOT	• Tyre repair kit (Tirefit) • Heated washer nozzles • Mirror package <i>Außenspiegel elektr. anklappbar, Außen-/Innenspiegel mit Abblendautomatik</i>
--	--

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Reifen VR beschädigt

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit							
Alternator / Generator:			examined limited	Battery / accumulator:			
oil loss:			examined limited			examined limited	
air conditioning:			examined limited	lighting system:			examined limited
coupling:			unavailable	exhaust System:			examined limited
engine running:			examined limited	shock absorber:			examined limited
transmission:			examined limited				

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen Kotflügel VL Nachlackiert

damage



component	Damage	Rep kind
1. Front fender - left	Subsequently painted	acceptable
2. maintenance	Due	Replace
3. proof of maintenance	Missing	Replace
4.	Missing	Replace
5. Key with remote control	Missing	Replace
6. Felge (Aluminium) vorne rechts	Scratch(es)	Paint
7.	Damaged	Replace
8. exterior body	Surface scratch(es)	
9.	Wear and tear	acceptable
10.	Dirty	
11. Türeinstieg Vorne - Links	Dented	Smart repair
12.	Odour	Ozone treatment
13.	Burn hole	Replace
14. flooring	Burn hole	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,\r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims



rims




rims



engine compartment



service book



Others



Navigation system



1. Front fender - left



6. Felge (Aluminium) vorne rechts




6. Felge (Aluminium) vorne rechts




7.



7.



8. exterior body



9.



9.



10.



10.



11. Türeinstieg Vorne - Links



11. Türeinstieg Vorne - Links




13.



13.



14. flooring



14. flooring