

# MERCEDES CLASSE CLS Classe CLS Shooting Brake 350 d Executive A



VIN NO WDD2189261A195824 Registration Number ER602KQ

MOT Date

**:2:** -

Number of Owners Number of Keys

**9**1

Odometer Reading

Last Service

₩-

Last Service Mileage

First Registration Date

**1**90354 km

**2**024-09-16

187391

2017-10-20

Country First Registered

### **Inspection Report Summary**

Customer	BCAuto Encheres	Report Number	P20250922090110
Inspection Date / Place	2025-09-22 / BCA MITRY	Cosmetic Grade	3

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	2987
Engine Size	3.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Rear
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	149

### Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			


























# Equipment

Central locking	Electrically folding wing mirrors	Rear parking sensors	Electric Tailgate
Cruise control	Power assisted steering	Electrically adjustable seats	Radio
Alloys wheels	Stability control	Front parking sensors	Satellite navigation


# **Equipment Details**

Seat Heating	Front	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Glass		

# Wheels & Tyres

Left Rear Tyre Depth	5	Left Front Tyre Depth	7
Right Rear Tyre Depth	5	Right Front Tyre Depth	7

# Cosmetic Damage



	Component	Damage	Comments
1	Bumper / Back	Paint / Scratch / Line	
2	Rim	Out of Bodywork / Scratch	
3	Door / Front Left	Paint / Scratch / Line	
4	Door / Front Left	Paint / Scratch / Line	
5	Rim / Front Left	Out of Bodywork / Scratch	
6	Rim	Out of Bodywork / Scratch	
7	Mirror / Front Right	Paint / Scratch / Line	
8	Door / Back Right	Bodywork / Dent / Deformation	
9	Door / Back Right	Paint / Scratch / Line	
10	Side Panel / Back Right	Bodywork / Dent / Deformation	
11	Rim Brake pads	Out of Bodywork / Scratch	
12	Seat / Front Left	Interior / Scraped	

13 Floor Carpet

Interior / Burn



1. Bumper / Back Paint / Scratch / Line -

2. Rim Out of Bodywork / Scratch -



3. Door / Front Left Paint / Scratch / Line -

4. Door / Front Left Paint / Scratch / Line -




5. Rim / Front Left Out of Bodywork / Scratch -

6. Rim Out of Bodywork / Scratch -



7. Mirror / Front Right Paint / Scratch / Line -

8. Door / Back Right Bodywork / Dent / Deformation -



9. Door / Back Right Paint / Scratch / Line -



10. Side Panel / Back Right Bodywork / Dent / Deformation -



11. Rim Brake pads Out of Bodywork / Scratch -



12. Seat / Front Left Interior / Scraped -



13. Floor Carpet Interior / Burn -

## **Mechanical Condition**

Tyres			
Presence Anti-Theft Lock Nut			
Dashboard Lights			
ABS Warning Light	<b>⊘</b>	Diesel Particulate Filter Light	•
ESP Fault/Traction Control Malfunction Light	•	4WD Light	NA
Dashboard Working	•	Engine Light	•
Oil Pressure Warning Light	•	Airbag Warning Light	•
Brake Warning Light	•	Level - Fuel / Battery	30
Transmission Warning Light	•	Service Light	•
Steering Fluid Level	NA		
Equipments Test			
Electric Windows	•	Convertible, Sunroof, Wagon, Flatbed truck, Tailgate electrics test	•
Dump / Trail / Tail Gate Lift	NA	Main & Spare Keys Functioning	•
Central Locking	•	Audio Equipment	•
Navigation System	•	AC / Heating System	•
Parking Sensors / Cameras Functioning	•		
Levels			
Oil - Condition	•	Level - Oil	•
Coolant Fluid - Condition	•	Coolant Fluid	•
Brakes Fluid	•		
Engine			
Cross Member	<b>⊘</b>	Serpentine Belt	•
Control Liquid Leak			
Comments			
Comments	Le frein à main (h-s)		

# Charge Port Condition NA Charge lead 1 condition /Charge lead 2 condition Hybrid System Fault NA Charge lead 2 condition

### **Test Drive Inspection**

Test Drive			
Engine functioning	<b>⊘</b>	Engine / Aux Belt / Pulley Noise	<b>②</b>
Vehicle Starts	•	Steering Noise/Gripping	•
Engine Power	<b>②</b>	Smoke Quantity	•
Transmission	•	Clutch Functioning	<b>⊘</b>
Steering	•	Brakes Functionning	•
<ul> <li>No troubles detected, good condition or correct tests, according to vehicle age and mileage</li> <li>Damages or malfunction detected that requires repairs by the buyer</li> <li>Not applicable</li> <li>Not tested</li> </ul>			

### **Disclaimer Section**

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.