

MERCEDES Classe S W/V 222 Benzina S 500 V8 Maximum 4matic auto



VIN NO WDD2220851A151149 Registration Number EY714VK

MOT Date

★ 2025-02-21

Last Service

=-

Number of Owners

:2:-

Last Service Mileage

Number of Keys

ø

First Registration Date

2015-03-16

Odometer Reading

119550 km

Country First Registered

Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250926091310
Inspection Date / Place	2025-09-26 / BCA Lodi	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Sequential
Colour	Silver	Engine Size (cc)	4663
Engine Size	4.7	No of Doors	4
Body Type	Sedan	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	211

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			









































Equipment


CD - single	Power assisted steering	Rain sensitive windscreen wipers	LED Headlamps
Anti-lock braking	Digital Radio	Electrically folding wing mirrors	Satellite navigation
Volante multifuncion	Remote adjusting wing mirrors	Reversing Camera	Traction control
Stability control	Central locking	Radio	Rear parking sensors
Alloys wheels	Bluetooth	Electrically adjustable seats	Front parking sensors
Sunroof	Full size spare wheel - steel	Remote central locking	Cruise control
Trip Computer			

Wheels & Tyres

Mounted Tires

Tyre / Wheel Type	Summer	
	CONTINENTAL	245/45//R19 - 102Y / 2 mm
	CONTINENTAL	245/45//R19 - 102Y / 2 mm
	BRIDGESTONE BRIDGESTONE- TURANZA T005	245/45//R19 - 102Y / 2 mm
	BRIDGESTONE BRIDGESTONE- TURANZA T005	245/45//R19 - 102Y / 2 mm

Cosmetic Damage



13	Door / Front Left	Paint / Scratch / Line
14	Rim / Back Left	Out of Bodywork / Scratch
15	Rocker Panel / Center Left	Paint / Scratch / Line
16	Bumper / Back	Paint / Scratch / Line
17	Fender / Back Right	Bodywork / Poor Previous Repair
18	Door / Back Right	Bodywork / Dent
19	Door / Front Right	Bodywork / Poor Previous Repair
20	Pillar / Front Right	Bodywork / Poor Previous Repair
21	Hood	Bodywork / Dent
22	Tailgate	Bodywork / Poor Previous Repair
23	Other	Bodywork / Poor Previous Repair



1. Dashboard / Front Interior / Warning Light ON -

2. Center Console Interior / Burn -




3. Panel Filling / Front Left Interior / Scratched -

4. Seat / Front Left Interior / Scratched -




5. Panel Filling / Back Left Interior / Broken -

6. Rim / Front Right
Out of Bodywork / Scratch -



7. Fender / Front Right Bodywork / Poor Previous Repair -

8. Hood Paint / Chipping -



9. Fender / Front Left Bodywork / Dent -

10. Rim / Front Left Out of Bodywork / Scratch -



11. Windshield / Front Glass Break / Impact -

12. Pillar / Front Left Bodywork / Poor Previous Repair -



13. Door / Front Left Paint / Scratch / Line -

14. Rim / Back Left Out of Bodywork / Scratch -



15. Rocker Panel / Center Left Paint / Scratch / Line -



16. Bumper / Back Paint / Scratch / Line -



17. Fender / Back Right Bodywork / Poor Previous Repair -




18. Door / Back Right Bodywork / Dent -



19. Door / Front Right Bodywork / Poor Previous Repair -

20. Pillar / Front Right Bodywork / Poor Previous Repair -



21. Hood Bodywork / Dent -

22. Tailgate Bodywork / Poor Previous Repair -



23. Bodywork / Poor Previous Repair -

Mechanical Condition

Engine			
Vehicle Start - up	•	Engine Starts	•
Engine Leak Visible	•		
Clutch			
Clutch Functioning	•		
Equipments Test			
Other Equipments	•	AC / Heating System	•
Levels			
Brakes Fluid	•	Coolant Fluid	•
Test Drive Inspection			
Other Checks			
Brakes	•	Steering	•
Suspension	•		
Gearbox			
Manual Gearbox	•		
General			
Test Driven Status	•	Test Drive Comment	SPIA MOTORE ACCESA.
Equipments Test			
Steering Noise / Anomaly	•		
Engine			
Power Loss	•	Fume Quantity	•
Engine Noise	•		
 No troubles detected, good condition or correct tests, according to vehicle age and mileage Damages or malfunction detected that requires repairs by the buyer Not applicable Not tested 			