



Hüsges Gruppe®
Die Gutachter

status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Mercedes-Benz B -Klasse B 220 CDI / d

Vehicle identification number	WDD2462031J303444	mileage read:	232925 km
First Registration / construction year:	20.01.2015 / 2014	Visit Date / place of birth:	12.09.2025 Riedstadt-Goddelau
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	1313//EJW
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	2143 ccm / 130 kW (177 PS)	Engine:	front-wheel drive
paint:	JUPITERROT - UNILACK	Number of previous owners:	2
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	4 - moderate
documents:		condition inside:	4 - moderate
visit condition:	-		
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided /	Last service at / on:
CD / DVD	2	maintained:	- / -
		no / -	

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Ein Unternehmen der Hüsges Gruppe
Bankverbindung
Sparkasse Krefeld
Kto.-Nr. 1048206 · BLZ 320 500 00

Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
Fax: 02154 / 9534 1025
Email:
info@huesges-gruppe.de



Rechtsform: Gesellschaft
mit beschränkter Haftung
Sitz: Willich
Registergericht: Krefeld HRB
Steuer-Nr.: 102/5821/0943

Geschäftsführung:
Arndt Hüsges
Dipl.- Ing. (FH) Bernd Hüsges

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Dunlop	205/55/R16/91W 1 mm
1st axis - right / states .	Dunlop	205/55/R16/91W 1 mm
2nd axis - Left / states .	Dunlop	205/55/R16/91W 3 mm
2nd axis - right / states .	Dunlop	205/55/R16/91W 3 mm
traffic Safety:	not roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Adaptive brake lights • Anti- lock braking system (ABS) • Front armrest with compartment • Power side mirrors . adjustable and heated, both • Outside temperature display • Indicator integrated into mirrors • Rev counter • Door sill panels , front (stainless steel) • Driver assistance system active brake assist
<i>Bremsassistent, Fahrassistentz-System: Auffahrwarnsystem mit Bremsfunktion (Collision Prevention Assist)</i> • Hill Start Assist • Parking brake electrically • Transmission 7 - speed dual - clutch transmission DCT
<i>Tempomat</i> • Isofix admissions for child seat in back seat • air Conditioning • Comfort chassis (Agility Control) • Rear headrests (3- fold) • Steering wheel (comfort) with multi-function • Steering column (steering wheel) mechan. adjustable • model refinement • speed-sensitive steering • trip computer • Rear seat backrest split / folding • Headlamps with integrated daytime running lights
<i>Tagfahrlicht LED</i> • Front left seat height adjustment • Start / Stop system | <ul style="list-style-type: none"> • Airbag Driver / passenger side • Acceleration skid control (ASR) • Amenities BlueEFFICIENCY • Body color door mirrors • Pelvic airbags (pelvisbag) • Design and equipment line Style
<i>Sitz-Komfort-Paket, Sitz vorn rechts höhenverstellbar, Sitze vorn neigungsverstellbar, Innenausstattung: Zierteile Linienoptik, Getränkehalter vorn (doppelt), Steckdose (12V-Anschluß) im Fond, LM-Felgen, LM-Felgen</i> • Off switch for headlights • Electron. Stability Program (ESP) • Driving Assistance System Attention Assist (fatigue detection sensor) • Electric windows front + rear • Luggage compartment cover / shade • Infotainment system Connect ME • Body 5-door • Knee airbag , driver's side • Head airbag system (Windowbag) • Load anchoring / Lashing • Steering wheel with shift paddles / buttons • Mercedes- Benz emergency call system • Engine 2.1 ltr. - 130 kW CDI KAT • Tire Pressure Monitoring System • Rußpartikelfilter • Low emissions Euro 6 emission standards • Side airbags (side airbag), front • Seat cover / upholstery fabric • Exterior door handles body color • Alarm / status indicator for seat belts in the rear |
|---|--|

• tinted glazing • immobilizer	• Central locking with remote control
---	---

special Features	
• Trailer hitch (ball head pivots) • Easy- Vario system <i>Gepäckraum-Paket, Steckdose (12V-Anschluß) im Koffer-/Laderaum, Armlehne hinten klappbar mit Durchlademöglichkeit (herausnehmbar), Sitzlehne vorn rechts klappbar</i> • Headliner black • Rear View Camera • Heated front seats	• Audio system Audio 20 (with color display) • Driving Assistance System Active Parking Assist • Steering wheel (leather / 3-spoke) with multifunction <i>Schalt-/Wählhebelgriff Leder</i> • Headlamp LED High Performance

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable Wartungsnachweise fehlen
reference:	
Note Road Safe:	Beide Reifen Vorne Verschlissen

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine



Demontagearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			in order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was examined during the inspection .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtanlage could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen.

damage



component	Damage	Rep kind
1. Sidewall - Rear - Left	Subsequently painted	acceptable
2. Beide Vorderen Sitze	Dirty	
3. proof of maintenance	Missing	Replace
4. maintenance	Due	Replace
5. Reifendruckkontrollleuchte	Error message	Carry out a fault diagnosis
6. Rim rear - right	Scratch(es)	Paint
7. Rim front - right	Scratch(es)	Smart repair
8. Beide Reifen Vorne	Worn	Replace
9. Front right wheel housing liner	Damaged	Replace
10. Unfallschaden Vorne, Schadenserweiterung möglich	Accident damage	Replace
11. hood	Wear and tear	acceptable
12. A-pillar Front - Left	Wear and tear	acceptable
13. Front door - left	Deformed	Refurbish and paint
14. roof	Damaged	Refurbish and paint
15. Rear door - left	Deformed	Refurbish and paint
16. Sidewall - Rear - Left	Deformed	Refurbish and paint
17. Heckklappe Spoiler	chipped paint	Paint
18. Rear bumper	Scratch(es)	Paint
19. tailgate	Delle	Smart repair
20. tailgate trim	Wear and tear	acceptable
21. Door Rear - right	Deformed	Refurbish and paint
22. Front door - right	Wear and tear	acceptable
23. motor insulation	Damaged	Replace
24. mit dem 2. Schlüssel kann das Fahrzeug nicht gestartet werden.	Damaged	Carry out a fault diagnosis
25. steering wheel	Damaged	Smart repair

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



1. Sidewall - Rear - Left



2. Beide Vorderen Sitze



2. Beide Vorderen Sitze



4. maintenance



5. Reifendruckkontrollleuchte



6. Rim rear - right



7. Rim front - right



8. Beide Reifen Vorne



8. Beide Reifen Vorne



9. Front right wheel housing liner



10. Unfallschaden Vorne, Schadenserweiterung möglich



10. Unfallschaden Vorne, Schadenserweiterung möglich



10. Unfallschaden Vorne, Schadenserweiterung möglich



10. Unfallschaden Vorne, Schadenserweiterung möglich



10. Unfallschaden Vorne, Schadenserweiterung möglich



11. hood



11. hood



11. hood



12. A-pillar Front - Left



13. Front door - left



13. Front door - left



14. roof



14. roof



15. Rear door - left



15. Rear door - left



16. Sidewall - Rear - Left



16. Sidewall - Rear - Left



16. Sidewall - Rear - Left



16. Sidewall - Rear - Left



17. Heckklappe Spoiler



18. Rear bumper



18. Rear bumper



18. Rear bumper



18. Rear bumper




19. tailgate



20. tailgate trim



20. tailgate trim



21. Door Rear - right



21. Door Rear - right



21. Door Rear - right



21. Door Rear - right



21. Door Rear - right



22. Front door - right



23. motor insulation



25. steering wheel



25. steering wheel