



Expertise

Protocol number: 41716547
Order number / reference: 25226594
Inspection date: 26 Sept 2025

Manufacturer: Mercedes-Benz	Model: Vito 111 CDI Lang
VIN: WDF44760313610623	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 111 CDI Lang	
Vehicle Identification number	WDF44760313610623
Mileage (Read)	63,351 km
First registration	25 Jun 2019
Number of holders	1
Next periodical technical inspection	08/2027
(Report not on hand)	
Power / Engine displacement	84 kw / 1,598 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Brillantsilber metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	39,700 km
Last maintenance on / at	08/2025 at 63,035 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FK637942
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1313 / EKK 01977		
Emission standard	EURO6;Y;PI/CI; N1 III, N2	Fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Steel	Pirelli	4mm / 4mm
2)	205/65 R16 107T	Winter tyres on Steel	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 103H	Summer tyres on Steel	Michelin	3mm / 3mm
2)	205/65 R16 103H	Summer tyres on Steel	Michelin	4mm / 4mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • ABS, ESP, ASR, EBD, BAS • Attention Assistant • Outside temperature display • Brake light, third • Ceiling interior light • Electric window lifter driver/passenger • Seat belt warning device for driver and front passenger seats • Headrests (2), front • Upholstery: fabric "Tunja" black • Wheels: steel rims 6.5 J x 16 • Crosswind Assist • Front stabilizer • Cruise control • Lashing eyes in the cargo area • Maintenance interval display >>ASSYST< • Central locking with radio remote control | <ul style="list-style-type: none"> • Airbag for driver and front passenger • Exterior mirrors, manually adjustable (2) • Hill start assist • Brake lights, adaptive • diesel particulate filter • Transmission: 6-speed manual • Boot lid • Instrument cluster • Mercedes-Benz emergency call system • Tires: 195/65 R 16 C • Key: 3-button radio remote control • Power steering • 12V socket • Partition wall continuous • Windshield washer fluid level warning light • Immobiliser |
|--|--|

Extra equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Loading/unloading (load increase to 3.05 t GVW) • Battery: fleece battery 12 V / 92 Ah • Comfort roof control unit • Lockable glove box • Large fuel tank, approx. 70 liters • LED light strip in the cargo area • Package: Smoker's package • Tire pressure monitoring • Key: 3-button radio remote control in conjunction with the removal of the partition wall • Seat heating on driver's side • auxiliary heater, electric | <ul style="list-style-type: none"> • Exterior mirrors electrically adjustable and heated, left and right • Deletion: Cruise control • Air conditioning controlled Tempmatic • Paint finish: metallic • Steering wheel adjustable in tilt and height • Tires: 205/65 R 16 • Rear view camera • Seat: Lumbar support driver's seat • Seats: Comfort driver's seat • Heat-insulating glass (driver's cab) |
|---|--|

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Multimedia system	Radio (Mehrkosten möglich) - Malposition - Perform diagnosis
2	Door - front left side	Door (FESTSTELLER TÜR V L) - Defective - Replace
3	Fuel system	Tank cap - Scratched - Smart repair



No.	Component group	Description
4	Boot lid / rear door	Seal - Malposition - Repair
5	Door - front left side	Door - Dent / paintcoat damage - Smart repair
6	Side panel - rear left side	Side panel - Scratched - Smart repair
7	Roof	Roof - Corrosion - Smart repair
8	Trim / covers	Door trim - front left side - Scratched - Replace
9	Mudguard - left side	Mudguard - left side - Scratched - Paint
10	Front bumper	Front bumper - Scratched - Replace
11	Braking system	Brake discs - front (Tragbild mangelhaft) - Corrosion - Replace
12	Rear bumper	Rear bumper - Scratched - Replace
13	Bonnet	Bonnet (Steinschlag) - Corrosion - Repair and paint
14	Boot lid / rear door	Boot lid (Dellen) - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Shelf installation	Shelf installation (Dellen) - Scratched - No deduction
2	Wing mirror - left side	Cap - Scratched - No deduction
3	Trim / covers	Boot lid - interior trim - Scratched - No deduction
4	Interior	Cargo area floor - Scratched - No deduction
5	Door - front right side	Door - Scratched - No deduction
6	Wing mirror - right side	Cap - Scratched - No deduction
7	Headlight	Headlight - right side - Stone chips - No deduction
8	Headlight	Headlight - left side - Stone chips - No deduction
9	Braking system	Brake discs - rear - Corrosion - No deduction
10	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 27 Sept 2021	1.701,92 €
2	Rear, Provided by user / customer, from 1 Jan 2020	2.503,48 €

Accident damages

No.	Accident
1	Side right

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - left side	144 µm
----------------------	--------



Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view ([Online link](#))



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.





Figure 35: Misc.




Figure 36: Misc.




Figure 37: Misc.




Damage 1: Multimedia system: Radio (Mehrkosten möglich) - Malposition
- Perform diagnosis




Damage 1: Multimedia system: Radio (Mehrkosten möglich) - Malposition
- Perform diagnosis



Damage 2: Door - front left side: Door (FESTSTELLER TUER V L) -
Defective - Replace



Damage 2: Door - front left side: Door (FESTSTELLER TUER V L) -
Defective - Replace



Damage 3: Fuel system: Tank cap - Scratched - Smart repair



Damage 3: Fuel system: Tank cap - Scratched - Smart repair



Damage 3: Fuel system: Tank cap - Scratched - Smart repair



Damage 4: Boot lid / rear door: Seal - Malposition - Repair



Damage 4: Boot lid / rear door: Seal - Malposition - Repair




Damage 4: Boot lid / rear door: Seal - Malposition - Repair



Damage 4: Boot lid / rear door: Seal - Malposition - Repair



Damage 5: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 5: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage 5: Door - front left side: Door - Dent / paintcoat damage - Smart repair



Damage 5: Door - front left side: Door - Dent / paintcoat damage - Smart repair




Damage 6: Side panel - rear left side: Side panel - Scratched - Smart repair



Damage 6: Side panel - rear left side: Side panel - Scratched - Smart repair



Damage 7: Roof: Roof - Corrosion - Smart repair



Damage 7: Roof: Roof - Corrosion - Smart repair




Damage 8: Trim / covers: Door trim - front left side - Scratched - Replace



Damage 8: Trim / covers: Door trim - front left side - Scratched - Replace



Damage 8: Trim / covers: Door trim - front left side - Scratched - Replace



Damage 9: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 9: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 9: Mudguard - left side: Mudguard - left side - Scratched - Paint




Damage 9: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 9: Mudguard - left side: Mudguard - left side - Scratched - Paint



Damage 10: Front bumper: Front bumper - Scratched - Replace




Damage 10: Front bumper: Front bumper - Scratched - Replace



Damage 10: Front bumper: Front bumper - Scratched - Replace



Damage 10: Front bumper: Front bumper - Scratched - Replace



Damage 11: Braking system: Brake discs - front (Tragbild mangelhaft) - Corrosion - Replace




Damage 11: Braking system: Brake discs - front (Tragbild mangelhaft) - Corrosion - Replace



Damage 11: Braking system: Brake discs - front (Tragbild mangelhaft) - Corrosion - Replace



Damage 11: Braking system: Brake discs - front (Tragbild mangelhaft) - Corrosion - Replace



Damage 12: Rear bumper: Rear bumper - Scratched - Replace



Damage 12: Rear bumper: Rear bumper - Scratched - Replace



Damage 12: Rear bumper: Rear bumper - Scratched - Replace



Damage 12: Rear bumper: Rear bumper - Scratched - Replace




Damage 12: Rear bumper: Rear bumper - Scratched - Replace



Damage 12: Rear bumper: Rear bumper - Scratched - Replace



Damage 13: Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint




Damage 13: Bonnet: Bonnet (Steinschlag) - Corrosion - Repair and paint




Damage 14: Boot lid / rear door: Boot lid (Dellen) - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid (Dellen) - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid (Dellen) - Scratched - Repair and paint



Damage 14: Boot lid / rear door: Boot lid (Dellen) - Scratched - Repair and paint



Wear and tear 5: Door - front right side: Door - Scratched - No deduction



Wear and tear 5: Door - front right side: Door - Scratched - No deduction




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Repainting 1: Mudguard - left side



Repainting 1: Mudguard - left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WDF44760313610623
Hersteller / Modell: MERCEDES BENZ MB Vito 111 CDI Lang

Datum	KM-Stand	Beschreibung
08.08.2025	63.041	AU; Batterie ern; Systemtest/Eigendiagnose
05.08.2025	63.035	Regelwartungsdienst
14.12.2023	55.701	Reparatur Sonstiges; Wartung Sonstiges
21.06.2023	51.428	AU; Bremsflüssigkeit ern; Systemtest/Eigendiagnose
08.02.2023	51.428	Bremsinspektion vo + hi; Regelwartungsdienst
01.06.2021	30.104	AU
28.05.2021	30.104	Kleine Inspektion