



status report

customer: BCA Autoauktionen GmbH
contract number:
reference:

vehicle data

Ford EcoSport ST-Line

Vehicle identification number	WF01XXERK1KD17771	mileage read:	112428 km
First Registration / construction year:	06.06.2019 / 2019	Visit Date / place of birth:	03.06.2025 Neuss
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	8566//BMR
Fuel / emission class:	gasoline / € 6	transmission type:	6 speed manual transmission
Displacement / power:	998 ccm / 103 kW (140 PS)	Engine:	front-wheel drive
paint:	Ruby-Rot (Metallic)	Number of previous owners:	3
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	Leather / fabric
Service book available:	yes	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	51112 / 12.04.2022
Vehicle roadworthy:	yes	Vehicle roadworthy:	yes
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	4 - moderate
state general:	4 - moderate		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	2	yes / -	51112 / 12.04.2022

☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires		
Tyre / wheel type:	summer tires	aluminum
1st axis - Left / states .	Goodyear	205/50/R17/89V 5 mm
1st axis - right / states .	Goodyear	205/50/R17/89V 5 mm
2nd axis - Left / states .	Goodyear	205/50/R17/89V 5 mm
2nd axis - right / states .	Goodyear	205/50/R17/89V 5 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment	
• 3 - point safety belt rear • Anti -lock braking system (ABS) • Drive Front Wheel Drive • Body color door mirrors • board computer • Cool \u0026 Sound Package <i>Audiosystem: Radio mit Ford SYNC (AppLink und Touchscreen), Audiobedienung am Lenkrad, 6 Lautsprecher, Sprachsteuerung und Bluetooth-Schnittstelle, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, USB-Anschluss, Fahrassistenten-System: Sicherheitssystem SYNC mit automatischem Notruf, AUX-IN-Anschluss, Farbdisplay (8 Zoll), Klimaautomatik, Handschuhfach mit Kühlfunktion</i> • Theft alarm system • Elektron . Stability Program (ESP) • Driving Assistance System Brake Assist • Electric windows front and rear with convenience closing • Luggage office cover / shade • Transmission 6-speed - Type 6MX65 • Handbrake grip Leather • Dust and pollen filter • Isofix admissions for child seat • Anthracite grille • Steering wheel (leather 3-spoke) • LM rims • facelift • My Key (2nd vehicle keys can be programmed) • Park Pilot System rear • Power KeyFree - start function • Tire repair kit • Back seat armrest partly / hinged (6040)	• Ambient lighting front (LED) • Anti-Slip Regulation (ASR) • Electric wing mirror . adjustable and heatable • Flashing light integrated in exterior mirrors • Spectacles compartment in roof liner / roof console • Roof rails black • Electr . Brake-force Distribution • Driving Assistance System Hill Start Assistant (Hill Holder) • Color display for on-board computer • Velour floor mats • Cruise control system (cruise control) <i>Geschwindigkeits-Begrenzeranlage</i> • Cupholders at the front • rear window heatable • Intelligent Protection System (IPS) <i>Knieairbag Fahrerseite, Airbag Fahrer-/Beifahrerseite, Kopf-Schulter-Airbag vorn und hinten, Seitenairbag vorn</i> • Body 5-doors • Lumbar support front left seat • Steering column (steering wheel) height / telescopic adjustment • Center console with armrest • • fog lights • Aluminium pedals • • Tire Pressure Monitoring System • • Shift / selector lever handle leather (2 colors) • Rain-sensing wipers

• Gearshift / selector lever leather • Gear shift indicator • Headlamps with darkened background • Body color side skirts • Front left seat height adjustment • Sun visor with mirror right • Stowage / storage compartment under front right seat • Daytime Running Lights LED • • auxiliary heating	<i>Innenspiegel mit Abblendautomatik</i> • Headlamp Assist with day / night sensor • Electric power steering • Sun visor with mirror left • Start / Stop system • Bumper Sport design • Outside handles body color • Central locking with remote control
---	---

special Features	
• <i>Audiobedienung am Lenkrad, 7 Lautsprecher, Sprachsteuerung und Bluetooth-Schnittstelle, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, USB-Anschluss, Fahrassistenz-System: Sicherheitssystem SYNC mit automatischem Notruf, AUX-IN-Anschluss, FordPass Connect inkl. eCall, Ford SYNC 3 mit Navigation, Farbdisplay (8 Zoll)</i> • Design-Package 4 <i>Bi-Xenon-Scheinwerfer, Dachspoiler (große Ausführung) Wagenfarbe, Verglasung hinten abgedunkelt (Privacy Glass)</i> • Paint ruby red metallic • Winter package <i>Frontscheibe heizbar, Frontscheibe teilweise heizbar, Sitzheizung vorn, Lenkrad heizbar</i>	• Roof painted in a different color / contrasting color • Easy Driver Package 2 <i>Außenspiegel elektr. anklappbar, Parkpilotsystem vorn und hinten, Parkpilotsystem hinten, Rückfahrkamera</i> • Seat cover / upholstery Leather

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	If not properly repaired The vehicle repaired previous damage have been observed on the body outer skin that are exposed and apparently with no disassembly of components with residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			examined limited		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			examined limited	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			not possible		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) could be considered limited during the visit .
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The clutch could be tested only limited within the test drive / pull test .
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Alters-, Transport- und Laufleistungsbedingte Gebrauchsspuren vorhanden. Kosten- und Schadenserweiterung möglich.

damage



component	Damage	Rep kind
1. Front door - right	Subsequently painted	acceptable
2.	Dirty	
3.	Dirty	
4. Door trim Rear - right	Scratch(es)	Replace
5. Front door - right	Execution defect	Paint
6. Rear bumper	Deformed	Replace
7. tailgate	Deformed	Smart repair
8. Sidewall - Rear - Left	Damaged	Refurbish and paint
9.	Dirty	
10. Front door - left		Refurbish and paint
11. Front fender - left	Chipping from stones	Smart repair
12. hood	Chipping from stones	Paint
13. maintenance	Due	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



1. Front door - right



2.



3.




4. Door trim Rear - right



4. Door trim Rear - right



5. Front door - right



5. Front door - right




6. Rear bumper



6. Rear bumper



7. tailgate



7. tailgate



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left



8. Sidewall - Rear - Left




8. Sidewall - Rear - Left



9.



10. Front door - left



10. Front door - left



11. Front fender - left




11. Front fender - left



12. hood



12. hood



12. hood



12. hood