


### Vehicle details

VIN	WF02XXERK 2NM68671	Brand	FORD	Maintenance date	-
Licence Plate	R9-40-LB	Model	PUMA 1.0 EcoBoost Hybrid Titanium auto 5d	Maintenance mileage	-
Registration date	07/10/2022	Year	2022	Exterior Color	White Solid
Odometer	184 617 km	Engine size	999	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

### Inspection Details

Inspection date	20/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



### Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Automatic Gearbox	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


### Removable element

Spare wheel kit	✓
Rear parcel shelf	✓



### Technical Document

Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓



### Tyres




### Exterior

<b>2</b>		<table border="0"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Dent &amp; Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Tailgate / Boot door	Position	Back	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair	<b>4</b>		<table border="0"> <tr><td>Part</td><td>Step plate</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Step plate	Position	Back right	Damages	Scatched	Severity	-	Repair mode	For info
Part	Tailgate / Boot door																								
Position	Back																								
Damages	Dent & Chips																								
Severity	Diameter (mm) > 20																								
Repair mode	Repair																								
Part	Step plate																								
Position	Back right																								
Damages	Scatched																								
Severity	-																								
Repair mode	For info																								

**Interior damage**

<b>1</b>		<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning	<b>3</b>		<table border="0"> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Scatched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Interior tailgate lining	Position	-	Damages	Scatched	Severity	-	Repair mode	Smart Repair
Part	Interior cleaning																								
Position	Front																								
Damages	Stained/dirty																								
Severity	-																								
Repair mode	Cleaning																								
Part	Interior tailgate lining																								
Position	-																								
Damages	Scatched																								
Severity	-																								
Repair mode	Smart Repair																								

**Others**

<b>5</b>		<table border="0"> <tr><td>Part</td><td>Damage appraisal</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Damage appraisal	Position	Front	Damages	Stone impact	Severity	-	Repair mode	For info
Part	Damage appraisal											
Position	Front											
Damages	Stone impact											
Severity	-											
Repair mode	For info											