

status report

customer:	Bank 11, Neuss
contract number:	987363530
reference:	

vehicle data			
Ford Focus			
Vehicle identification number	WF06XXGCCGFU26729	mileage read:	131730 km
..			
First Registration / construction year:	30.11.2015 / 2015	Visit Date / place of birth:	30.09.2025 Dorfmark
Bodywork:	cars	Re - import:	no
Body type:	hatchback	KBA no. :	8566//BKC
Fuel / emission class:	diesel / € 6	transmission type:	automatic
Displacement / power:	1997 ccm / 110 kW (150 PS)	Engine:	front-wheel drive
paint:	black	Number of previous owners:	6
Doors / seats:	5 / 5	number keys:	1
Next HU / AU:	01.2025 / 01.2025	cushion type:	substance
Service book available:	yes	Interior Color:	gray
smoking vehicle:	no	Last service km / on the:	120987 / 09.04.2024
Vehicle roadworthy:	yes	Vehicle roadworthy:	no
Submitted vehicle documents:	For example, I (Fzg.Schein)	state outside:	4 - moderate
visit condition:	-	condition inside:	3 - Average
state general:	3 - Average		

Accessories (presented to the visiting time)			
GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
-	1	yes / -	120987 / 09.04.2024
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available** ☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	All season tires	aluminum
1st axis - Left / states .	Vredestein	215/55/R16/93H 5 mm
1st axis - right / states .	Vredestein	215/55/R16/93H 5 mm
2nd axis - Left / states .	Nokian	215/55/R16/97U 6 mm
2nd axis - right / states .	Nokian	215/55/R16/97V 6 mm
traffic Safety:	roadworthy	
spare wheel:	-	
state spare wheel:	-	

standard equipment

special Features

standard equipment

- | | |
|---------------------------------------|--------------------|
| • ABS | • Towbar |
| • Power side mirrors . | • board computer |
| • ESP | • Power windows |
| • Driver and passenger airbags | • air Conditioning |
| • Multifunction steering wheel | • Fog Lights |
| • PDC / V + H | • radio |
| • Rear View Camera | • power steering |
| • Hightadjustable | • cruise control |
| • Central locking with remote control | |

We remind you that the data provided were taken from the DAT database.\r\nNo liability can be assumed for the completeness and correctness.

General examination

Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed. Hoist or lifting means not available .
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Batterie Tiefentladen

Farbabweichung Plastikteile

Accident injury assessment

Rep. Predamages / -height gross:	Expertly repaired On a vehicle coating thickness measurement on the body outer skin were noted repaired previous damage in the frames that were repaired and apparently without disassembly of components without residual traces accident . If there is an impairment of the observed accident before it was taken into account in if conducted vehicle valuation.
Layers of paint thickness measurement:	Out of tolerance At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were outside the tolerances of original finishes .
Existing collision damage:	found At the unrepaired vehicle accident damage were observed on visual examination on the body skin .
reference:	Fahrzeug mit bestehenden Unfallschaden, zur Schadensermittlung wurden keine Demontearbeiten durchgeführt, verborgen gebliebene Schäden können nicht ausgeschlossen werden. Unfallschaden Kosten wurden überschlägig Kalkuliert, Kostenerweiterung möglich.

Overview conducted technology audit					
Alternator / Generator:			examined limited	Battery / accumulator:	
			Out of order		
oil loss:			examined limited		
air conditioning:			examined limited	lighting system:	
			examined limited		
coupling:			unavailable	exhaust System:	
			examined limited		
engine running:			examined limited	shock absorber:	
			examined limited		
transmission:			examined limited		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
coupling:	The vehicle has no clutch , as it is a Autmatikgetriebe or the like.
exhaust System:	The exhaust system has been tested only restricted during the visit .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
shock absorber:	The shock absorber could be tested only restricted during the visit .
transmission:	The transmission could be examined in the context of limited test drive / pull test .
reference:	*Fahrzeug hat Alter und Laufleistungs bedingte Gebrauchsspuren innen und außen VIN Abfrage nicht möglich, Fahrzeugdaten und Ausstattung können abweichen. Kostenerweiterung möglich. Kotflügel VR Nachlackiert Unfallschaden HL Schaden und Kosten Erweiterung möglich

damage



	component	Damage	Rep kind
1.	Front fender - right	Subsequently painted	acceptable
2.	maintenance	Due	Replace
3.	Key with remote control	Missing	Replace
4.	battery	Defective	Replace
5.	Rear bumper	Accident damage	Replace
6.	Sidewall - Rear - Left	Accident damage	Replace
7.	Front bumper	Scrape	Smart repair
8.	A-pillar Front - right		Smart repair
9.	exterior body	Surface scratch(es)	
10.		Wear and tear	acceptable
11.		Dirty	
12.	tailgate trim	Scrape	Replace

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted ,r\nand for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others




1. Front fender - right




5. Rear bumper



5. Rear bumper



5. Rear bumper



6. Sidewall - Rear - Left



6. Sidewall - Rear - Left



6. Sidewall - Rear - Left



6. Sidewall - Rear - Left



7. Front bumper



7. Front bumper



7. Front bumper



7. Front bumper



8. A-pillar Front - right



8. A-pillar Front - right




8. A-pillar Front - right



9. exterior body



10.



10.



11.



11.



12. tailgate trim



12. tailgate trim