



status report

customer: Bank 11, Neuss
contract number: 1010833530
reference:

vehicle data

Ford Kuga Cool

Vehicle identification number	WF0AXXWPMJU61034	mileage read:	60452 km
First Registration / construction year:	18.12.2018 / 2018	Visit Date / place of birth:	12.09.2025 Knautnaundorf
Bodywork:	SUV	Re - import:	no
Body type:	hatchback	KBA no. :	8566//BMQ
Fuel / emission class:	gasoline / € 6	transmission type:	manual transmission
Displacement / power:	1498 ccm / 88 kW (120 PS)	Engine:	front-wheel drive
paint:	Frost-Weiß	Number of previous owners:	1
Doors / seats:	5 / 5	number keys:	2
Next HU / AU:	- / -	cushion type:	substance
Service book available:	no	Interior Color:	black
smoking vehicle:	yes	Last service km / on the:	- / -
Vehicle roadworthy:	no	Vehicle roadworthy:	no
Submitted vehicle	-	state outside:	5 - neglected
documents:		condition inside:	5 - neglected
visit condition:	-		
state general:	5 - neglected		

Accessories (presented to the visiting time)

GPS sat nav disk:	Fzg.Schlüssel:	Service book provided / maintained:	Last service at / on:
SD Card	2	no / -	- / -
☒ AHK key	☒ AHK removable	☒ AHK fixed	☒ AHK swivel
☒ Fernbed . entertainment	☒ Fernbed . Auxiliary heating	☒ headphone	☒ LED headlights
☒ Load compartment cover	☒ navigation system	☒ Persenning	☒ partition net
☒ Wind Deflector	☒ Xenon headlights		

☒ **available**

☒ **not available**

Hüsges GmbH
Gießerallee 23
47877 Willich
Tel.: 02154 / 9534 0
E-Mail: gutachten@huesges-group.eu

The status report was created impartially and to the best of my knowledge. The images listed in the status report are part of the vehicle description regarding the equipment and the vehicle condition.



Hüsges Gruppe®
Die Gutachter



mounted tires

Tyre / wheel type:	Winter tires	steel
1st axis - Left / states .	Nexen	235/55/R17/103V 6 mm
1st axis - right / states .	Nexen	235/55/R17/103V 6 mm
2nd axis - Left / states .	Nexen	235/55/R17/103V 5 mm
2nd axis - right / states .	Nexen	235/55/R17/103V 5 mm
traffic Safety:	roadworthy	
spare wheel:	Tirefit	
state spare wheel:	-	

standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Anti -lock braking system (ABS) • Drive Front Wheel Drive • Audio control on the steering wheel • board computer • Chrome surround side windows • Roof spoiler body color • Easy-Driver-Package
<i>Außenspiegel elektr. anklappbar, Bodenleuchte im Außenspiegel, Parkpilotsystem vorn und hinten, Parkpilotsystem hinten</i> • Elektron . Stability Program (ESP) • Driving Assistance System Brake Assist • Footwell illumination at the front • Cruise control system (cruise control) • Interiors Aluminium decor • Intelligent Protection System (IPS)
<i>Knieairbag Fahrerseite, Airbag Fahrer-/Beifahrerseite, Seitenairbag vorn, Kopf-Schulter-Airbag vorn, Kopf-Schulter-Airbag hinten</i> • Body 5-doors • Grille silver • Steering wheel with paddles • Headlamp leveling • facelift • My Key (2nd vehicle keys can be programmed) • Electric parking brake • Wheelbase 2690 mm • Tire Pressure Monitoring System • Low emissions Euro 6 emissions standard • Gear shift indicator • Front left seat height adjustment | <ul style="list-style-type: none"> • Anti-Slip Regulation (ASR) • Audio Navigation System Ford SD (with Ford SYNC)
<i>6 Lautsprecher, Vorrüstung Mobiltelefon/Handy mit Bluetooth-/USB-Schnittstelle, Sprachsteuerung und Bluetooth-Schnittstelle, USB-Anschluss, AUX-IN-Anschluss, Ford SYNC 3 mit Navigation</i> • Electric wing mirror . adjustable and heatable • Spectacles compartment in roof liner / roof console • Roof rails (aluminum) • Dimmer instrument lighting • Electr . Brake-force Distribution • Driving Assistance System Hill Start Assistant (Hill Holder) • Electric windows front and rear with convenience closing • Speed ??Begrenzeranlage • Transmission 6-speed - type MMT6 • Dust and pollen filter • Isofix admissions for child seat • Climate control 2 zones • Steering wheel (leather 3-spoke) • Steering column (steering wheel) height / telescopic adjustment • Center console with armrest • • fog lights • Power KeyFree - start function • Tire repair kit • Back seat armrest partly / hinged (6040) • Gearshift / selector lever leather |
|---|---|

• Sun visor with mirror right (lit) • Start / Stop system • Daytime Running Lights • Outside handles body color • Rear protective devices • Warning system for rear seat belts • Central locking with remote control	• Electric power steering • Sun visor with mirror left (illuminated) • Sports seats, front • Socket (12V connection) in the boot / load compartment • Daytime Running Lights LED • Underride protection • tinted glazing • Immobiliser (electronic) • Moldings below the side windows chrome décor
--	---

special Features	
• Towbar preparation <i>Anhänger-Stabilisierungs-Programm (TSA)</i> • Visibility Package <i>Scheinwerfer-Assistent mit Tag-/Nachtsensor, Scheibenwischer mit Regensensor, Scheinwerfer mit Ausschaltverzögerung, Innenspiegel mit Abblendautomatik</i> • Glazing behind darkened (privacy glass)	• carpet floor mats • Special paint Frost White • Winter package <i>Scheinwerfer-Reinigungsanlage (SRA), Frontscheibe heizbar, Sitzheizung vorn, Lenkrad heizbar</i>

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General examination	
Subfloor Inspection:	not possible A visit to the underside of your vehicle could not be performed.
Mileage plausible:	not testable not testable
reference:	
Note Road Safe:	Bremse nicht in Ordnung; Motor geht aus, Beleuchtung nicht prüfbar

Farbabweichung Plastikteile

Accident injury assessment	
Rep. Predamages / -height gross:	no detectable As part of a paint film thickness measuring the body outer skin no previous damage could be detected .
Layers of paint thickness measurement:	Within the tolerances At the vehicle , a resist layer thickness measurement was carried out on the body outer skin. The measured values ??were within the tolerances of original finishes .

Existing collision damage:

Evidence that points to a repaired accident damage or repainting carried out , were identified.

Not established

On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .

reference:

Overview conducted technology audit					
Alternator / Generator:		✓	examined limited	Battery / accumulator:	
				✗	Out of order
oil loss:		✓	examined limited		
air conditioning:		✗	not possible	lighting system:	
				✗	not possible
coupling:		✗	not possible	exhaust System:	
				✗	not possible
engine running:		✗	Out of order	shock absorber:	
				✗	not possible
transmission:		✗	not possible		

Performed testing technology	
Alternator / Generator:	The function of the alternator (generator) was tested using the charging indicator light in the instrument cluster .
Battery / accumulator:	The battery (accumulator) was discharged for visiting time . **Battery deep discharge. Vehicle was bridged with a jumper.
oil loss:	The vehicle could be checked only limited to oil leaks .
air conditioning:	The air conditioning could not be checked during the inspection . *Motor geht immer wieder aus
lighting system:	The lighting system could not be tested for visiting time . **No power supply.
coupling:	The coupling could not be checked during the inspection .
exhaust System:	The exhaust system could not be checked during the inspection .
engine running:	A field test of the engine had to acoustic or visual defects for visiting time . **Engine warning light. Engine run out of round.
shock absorber:	The shock absorber could not be checked during the inspection .
transmission:	The transmission could not be checked for visiting time .
reference:	*Das Fahrzeug hat Alters- und Gebrauchsspuren, mangelnde Pflege, Begutachtung aufgrund der Besichtigungsbedingungen eingeschränkt möglich

damage



	component	Damage	Rep kind
1.	Batterie	Not okay	Replace
2.	Motorraum		Replace
3.	Motor (läuft unrund, geht aus)	Engine damage	Carry out a fault diagnosis
4.	Motor	Error message	Carry out a fault diagnosis
5.	Radio		Carry out a fault diagnosis
6.	Innenraum (weiterhin Geruch, Ozonbehandlung wurde schon durchgeführt)	Odour	Carry out a fault diagnosis
7.	Laderaumabdeckung	Missing	Replace
8.	Kofferraum und Innenraum	Wear and tear	acceptable
9.	Fußmatten Hinten Vorne Rechts	Missing	Replace
10.		Burn hole	Replace
11.	Bodenbelag	Burn hole	Smart repair
12.	tailgate	Sticker	
13.	Front door - left	Damaged	Smart repair
14.	Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Verschmutzungen, Flugrost)	Not okay	
15.	Bordbuchmappe inkl. Bedienungsanleitungen und Wartungsnachweis	Missing	Replace
16.	Wartung (nicht durch Wartungsnachweis belegt)	Missing	Replace
17.		Not okay	Replace
18.		Not okay	Replace
19.		Not looked after	
20.	Beleuchtung (Batterie nicht in Ordnung)		Carry out a fault diagnosis

The expert points out that the vehicle in addition to age to the damage listed in the report and may have a high mileage -related wear , as in normal use are inevitable (small bumps , dents , scratches) and thus is not entitled to change or reduction .

There shall be no liability for any defect and / or remained hidden damage in terms of electronics and mechanics accepted , and for fraudulent misrepresentation and concealed defects .

photographic record



front Left



front Right



rear Left



rear Right



inside



inside



trunk



instrument cluster



mileage



filler cap



rims



rims




rims



rims



engine compartment



service book



Others



Navigation system



2. Motorraum



2. Motorraum



2. Motorraum



2. Motorraum



2. Motorraum



2. Motorraum




2. Motorraum



2. Motorraum



2. Motorraum



2. Motorraum




2. Motorraum



2. Motorraum



4. Motor



5. Radio



8. Kofferraum und Innenraum



8. Kofferraum und Innenraum



8. Kofferraum und Innenraum



9. Fußmatten Hinten Vorne Rechts



9. Fußmatten Hinten Vorne Rechts



10.



10.



10.



11. Bodenbelag



11. Bodenbelag



12. tailgate



12. tailgate



13. Front door - left



13. Front door - left



13. Front door - left



14. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Verschmutzungen, Flugrost)



14. Fahrzeug (Kratzer, Harz-/Säureeinwirkung, Verschmutzungen, Flugrost)



17.



17.



17.



17.




17.



17.



18.



18.



18.




18.



19.



19.




19.



19.



19.



19.



19.



19.



19.