



Expertise

Protocol number: 41565907
Order No. / Reference: 25137373
Inspection date: 12 Sept 2025

Manufacturer: Ford

Model: Transit 350 L4 Einzelkabine Trend Koffer LBW

VIN: WF0DXXTTGDKL49342



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Transit 350 L4 Einzelkabine Trend Koffer LBW

Vehicle Identification number	WF0DXXTTGDKL49342
Mileage (Read)	19,635 km
First registration	30 Jul 2019
Number of holders	1
Next periodical technical inspection	07/2023
(Report on hand)	

Power / Engine displacement	96 kw / 1,995 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Lorry < 3,5t

Colour / colour code	frostweiß
Doors / Seats	2 / 3
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	0 km
Last maintenance on / at	07/2023 at 8,105 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available
		Letter No.	FK436483
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	Limited: access	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / 000 000		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	Fine dust sticker	
Permitted total weight	3,400 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Pirelli	5mm / 5mm
2)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel	Michelin	6mm / 6mm
2)	235/65 R16 115R	Summer tyres on Steel	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R	Summer tyres on Steel	Michelin	7 mm

Legend: Tread depth information for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • 1 battery • Anti-lock braking system with electronic brake-force distribution (EBD) • roof, flat • Headlining in driver's cab • tachometer • Front window lifter, electric • Ford Easy Fuel • Transmission: 6-speed transmission • Interior lighting with delay circuit • Paint finish: Solid paint • Steering column, adjustable in height and reach • Particulate filter: diesel particulate filter • Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires • Headlight dipped beam with switch-off delay • Seat belts • Recirculation circuit • Heat-insulating glazing, slightly tinted • Second key with remote control | <ul style="list-style-type: none"> • Driver's side airbag • Exterior mirrors, electrically adjustable and heated • On-board computer • Roof, overhead storage compartment at the front • Roof marker lights • Electronic Safety and Stability Program (ESP) with Traction Control (TSC) • Cruise control including leather steering wheel • Glove compartment with lockable lid • Front air conditioning • leather steering wheel • Fog light • Flatbed: Standard flatbed (wide) • Headlights with static cornering light • Power steering • Daytime running light • Immobiliser • Central locking with remote control |
|--|---|

Extra equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Passenger side airbag (with airbag deactivation function) • Speed limiter 90 km/h (cannot be switched off) • Lightweight case Baesweiler • Package: Visibility Package I (electrically adjustable exterior mirrors, heated - heated windscreen - windscreen washer sensor) • Wheels/Tires: Spare wheel, steel wheel • Seats: Seat Package 15 (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion angle, height) - double passenger seat with storage compartment under individually foldable seat cushions - headrests, height adjustable - tray integrated in the double passenger seat (fold-out) - seat heating for driver - seat heating for passenger - inside armrest for driver - lumbar support, manual (driver's seat) - seat cover: fabric) | <ul style="list-style-type: none"> • Exterior mirror, long arm (with integrated indicators) • LBW Sörensen type X1A 0750SL 2R • Retrofitting rear view camera • Radio: Audio system 15: Ford navigation system including Ford SYNC 3 with AppLink and touchscreen (16.5 cm screen diagonal - radio, MP3-capable, dual tuner, DAB/DAB+, speed-dependent volume control, audio remote control on the steering wheel, 4 front speakers, USB port, AUX input - voice control - Bluetooth and USB interface - hands-free system - SMS reading/sending function - Bluetooth audio streaming - emergency call assist - SD card slot - acoustic and visual route guidance - TMCpro - detailed visualization (3D display) - Michelin travel guide for Europe) |
|---|--|

Brief expert findings

Documents submitted	At the time of the inspection, the registration certificate Part 2 (letter) was available, but the registration certificate Part 1 (certificate) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was verified during the inspection by the undersigned.
Inspection	The inspection conditions were inadequate for examining the vehicle due to the limited access. No lifting equipment or pit was available to inspect the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/maneuvering was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors



No.	Component group	Description
1	Misc.	Inspection / maintenance (Unvollständig) - No evidence - No deduction
2	Door - front right side	Brightware - lower - Scratched - Loss in value
3	Seat - front	Seat base trim - left side (Blende Sitzverstellung) - Missing - Replace
4	Misc.	Accident prevention regulations tail lift - Expired - Perform
5	Boot lid / rear door	Boot lid (LBW Korrosionsschutz erforderlich) - Scratched - Smart repair
6	Misc.	Main inspection - Due - Perform
7	Trim / covers	Cargo area - lining - right side - Scratched - Smart repair
8	Side panel - rear left side	Side panel (Kofferaufbau inkl. Portalrahmen) - Scratched - Paint
9	Misc.	Inspection / maintenance - Due - Perform
10	Trim / covers	Cargo area - lining -left side (Teilersatz) - Broken / torn - Repair
11	Side panel - rear right side	Side panel (Kofferrwand inkl. Portalrahmen hinten) - Scratched - Repair and paint
12	Side panel - rear right side	Side panel (Kofferaufbau unten, Unterzug) - Deformed - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Front bumper	Front bumper - Stone chips - No deduction
6	Roof	Roof (Kofferaufbau, von innen sichtbar) - Scratch(es) - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
(*Functional tests of driver assistance systems are not included in the scope of services!*)
- a photo documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles from Alphabet Fuhrparkmanagement GmbH. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects which, according to the underlying standard, can no longer be attributed to normal use or wear and tear are listed in the product under "Depreciating Factors".

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Apparently, no repaired previous damage could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich.
- Das Fahrzeugdach konnte unter den gegebenen Bedingungen nicht begutachtet werden. Etwaige wertmindernde Faktoren fließen nicht in diese Beurteilung hinein.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Instrument cluster



Figure 7: Instrument panel



Figure 8: Interior 360° view



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres




Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Damage 2: Door - front right side: Brightware - lower - Scratched - Loss in value



Damage 2: Door - front right side: Brightware - lower - Scratched - Loss in value



Damage 3: Seat - front: Seat base trim - left side (Blende Sitzverstellung) - Missing - Replace



Damage 3: Seat - front: Seat base trim - left side (Blende Sitzverstellung) - Missing - Replace



Damage 4: Misc.: Accident prevention regulations tail lift - Expired - Perform




Damage 4: Misc.: Accident prevention regulations tail lift - Expired - Perform



Damage 5: Boot lid / rear door: Boot lid (LBW Korrosionsschutz erforderlich) - Scratched - Smart repair



Damage 5: Boot lid / rear door: Boot lid (LBW Korrosionsschutz erforderlich) - Scratched - Smart repair



Damage 6: Misc.: Main inspection - Due - Perform



Damage 7: Trim / covers: Cargo area - lining - right side - Scratched - Smart repair



Damage 7: Trim / covers: Cargo area - lining - right side - Scratched - Smart repair



Damage 7: Trim / covers: Cargo area - lining - right side - Scratched - Smart repair



Damage 7: Trim / covers: Cargo area - lining - right side - Scratched - Smart repair



Damage 7: Trim / covers: Cargo area - lining - right side - Scratched - Smart repair



Damage 7: Trim / covers: Cargo area - lining - right side - Scratched - Smart repair



Damage 8: Side panel - rear left side: Side panel (Kofferaufbau inkl. Portalrahmen) - Scratched - Paint



Damage 8: Side panel - rear left side: Side panel (Kofferaufbau inkl. Portalrahmen) - Scratched - Paint




Damage 8: Side panel - rear left side: Side panel (Kofferaufbau inkl. Portalrahmen) - Scratched - Paint



Damage 8: Side panel - rear left side: Side panel (Kofferaufbau inkl. Portalrahmen) - Scratched - Paint



Damage 8: Side panel - rear left side: Side panel (Kofferaufbau inkl. Portalrahmen) - Scratched - Paint



Damage 9: Misc.: Inspection / maintenance - Due - Perform



Damage 10: Trim / covers: Cargo area - lining -left side (Teilersatz) - Broken / torn - Repair



Damage 10: Trim / covers: Cargo area - lining -left side (Teilersatz) - Broken / torn - Repair



Damage 11: Side panel - rear right side: Side panel (Kofferwand inkl. Portalrahmen hinten) - Scratched - Repair and paint



Damage 11: Side panel - rear right side: Side panel (Kofferwand inkl. Portalrahmen hinten) - Scratched - Repair and paint



Damage 11: Side panel - rear right side: Side panel (Kofferwand inkl. Portalrahmen hinten) - Scratched - Repair and paint



Damage 12: Side panel - rear right side: Side panel (Kofferaufbau unten, Unterzug) - Deformed - Replace



Damage 12: Side panel - rear right side: Side panel (Kofferaufbau unten, Unterzug) - Deformed - Replace



Damage 12: Side panel - rear right side: Side panel (Kofferaufbau unten, Unterzug) - Deformed - Replace



Damage 12: Side panel - rear right side: Side panel (Kofferaufbau unten, Unterzug) - Deformed - Replace



Wear and tear 6: Roof: Roof (Kofferaufbau, von innen sichtbar) - Scratch(es) - No deduction



Wear and tear 6: Roof: Roof (Kofferaufbau, von innen sichtbar) - Scratch(es) - No deduction



Wear and tear 6: Roof: Roof (Kofferaufbau, von innen sichtbar) - Scratch(es) - No deduction



Wear and tear 6: Roof: Roof (Kofferaufbau, von innen sichtbar) - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0DXXTTGDKL49342

Hersteller / Modell: FORD FORD Transit Fahrgestell Einzelkabine Trend

Datum	KM-Stand	Beschreibung
14.05.2025	18.200	Batterie ern; Systemtest/Eigendiagnose
11.07.2023	8.105	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Wartung Sonstiges
15.07.2021	0	HU + AU
17.06.2021	1.027	Kleine Inspektion; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern