



FORD C-MAX

C-MAX 1.6 TDCi - 90 Ghia

VIN NO WF0EXXGCDE9R04269
Registration Number AC727FK



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



2009-07-30

Odometer Reading



213876 km

Country First Registered



Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20251007083258
Inspection Date / Place	2025-10-07 / BCA GARONS	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1560
Engine Size	1.6	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	119
Engine Rating CV		Metalic Colour	Yes
Accident Damage	No	Euro Emission	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Cruise control	Power assisted steering	Radio
Front fog lamps			

Equipment Details


Seat Heating	No	Air Conditioning	Yes
--------------	----	------------------	-----

Cosmetic Damage

21 Dommages



13 Dommages



Component		Damage	Comments
1	Seat Cushion / Back Right	Interior / Dirty	
2	Seat Cushion / Front Right	Interior / Dirty	
3	Seat Cushion / Front Left	Interior / Dirty	
4	Seat Cushion / Back Left	Interior / Dirty	
5	Panel Filling / Back Left	Interior / Loose	
6	Panel Filling / Front Left	Interior / Loose	
7	Panel Filling / Back Right	Interior / Loose	
8	Luggage Space Cover / Back	Interior / Missing	
9	Panel Filling / Front Right	Interior / Loose	
10	Hubcap / Back Left	Out of Bodywork / Scratch	
11	Shield / Front	Paint / Scratch / Line	
12	Door / Back Right	Paint / Scratch / Line	

13	Shield / Front	Paint / Scratch / Line
14	Hubcap / Front Left	Out of Bodywork / Scratch
15	Hubcap / Back Right	Out of Bodywork / Scratch
16	Hubcap / Front Right	Out of Bodywork / Breakage
17	Front Light / Front Right	Glass Break
18	Seat Cushion / Back Left	Interior / Dirty
19	Front Light / Front Left	Glass Break
20	Door Step / Back Right	Interior / Distorted
21	Gear Knob	Interior / Broken
22	Trunk Stick	Paint / Poor Previous Repair
23	Gear Knob	Interior / Worn - out
24	Door / Front Right	Bodywork / Dent / Deformation
25	Shield / Back	Paint / Scratch / Line
26	Roof	Paint / Poor Previous Repair
27	Windshield Wiper Blade / Front Right	Missing Part
28	Door / Back Left	Paint / Scratch / Line
29	Door / Front Left	Paint / Scratch / Line
30	Door / Front Right	Bodywork / Dent / Deformation
31	Trunk Stick	Paint / Poor Previous Repair
32	Door / Back Left	Bodywork / Dent / Deformation
33	Shield / Back	Missing Part
34	Door / Back Left	Paint / Scratch / Line



1. Seat Cushion / Back Right
Interior / Dirty -



2. Seat Cushion / Front Right
Interior / Dirty -



3. Seat Cushion / Front Left
Interior / Dirty -



4. Seat Cushion / Back Left
Interior / Dirty -



5. Panel Filling / Back Left
Interior / Loose -



6. Panel Filling / Front Left
Interior / Loose -



7. Panel Filling / Back Right
Interior / Loose -



8. Luggage Space Cover / Back
Interior / Missing -



9. Panel Filling / Front Right
Interior / Loose -



10. Hubcap / Back Left
Out of Bodywork / Scratch -



11. Shield / Front
Paint / Scratch / Line -



12. Door / Back Right
Paint / Scratch / Line -



13. Shield / Front
Paint / Scratch / Line -



14. Hubcap / Front Left
Out of Bodywork / Scratch -



15. Hubcap / Back Right
Out of Bodywork / Scratch -



16. Hubcap / Front Right
Out of Bodywork / Breakage -



17. Front Light / Front Right
Glass Break -




18. Seat Cushion / Back Left
Interior / Dirty -



19. Front Light / Front Left
Glass Break -




20. Door Step / Back Right
Interior / Distorted -



21. Gear Knob
Interior / Broken -



22. Trunk Stick
Paint / Poor Previous Repair -



23. Gear Knob
Interior / Worn - out -



24. Door / Front Right
Bodywork / Dent / Deformation -



25. Shield / Back
Paint / Scratch / Line -




26. Roof
Paint / Poor Previous Repair -



27. Windshield Wiper Blade / Front Right
Missing Part -



28. Door / Back Left
Paint / Scratch / Line -



29. Door / Front Left
Paint / Scratch / Line -



30. Door / Front Right
Bodywork / Dent / Deformation -



31. Trunk Stick
Paint / Poor Previous Repair -



32. Door / Back Left
Bodywork / Dent / Deformation -



33. Shield / Back
Missing Part -



34. Door / Back Left
Paint / Scratch / Line -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.